

NDCRS ARCHITECTURAL SITE FORM

PAGE 1

Field Code MAC-112

SITS# 32 BK 206

SITE IDENTIFICATION

Map Quad Grubb Lake Site Name _____
Map Quad _____ Site Name _____

LTL ___TWP 161 R 93 SEC 33 QQQ _____ QQ 5 Q 5
LTL ___TWP _____ R _____ SEC _____ QQQ _____ QQ _____ Q _____
LTL ___TWP _____ R _____ SEC _____ QQQ _____ QQ _____ Q _____
LTL ___TWP _____ R _____ SEC _____ QQQ _____ QQ _____ Q _____

NAD 1983, UTM 5400337 N ZONE 13N
NAD 1983, UTM 665633 E

Subsection:
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

City: _____
Street Number: _____
Street Name: 91st St NW
Urban Legal Description: _____

SITE DATA

Total # **Architectural** Features: 9

Fieldwork Date: 03/11/2018

Reconnaissance Survey Intensive Survey

Project & Principal Investigator:

Project: Burke County Windfarm; PI: Ed Stine

Report Title & Author(s):

Title: Architectural Survey for the Burke County Wind Energy Center, Burke County, North Dakota prepared for Burke Wind, LLC; Author: Emily Sakariassen

Contracting firm or Agency completing the form:

Metcalf Archaeological Consultants, Inc.

Additional Information:

SHSND USE

Area of Significance 2 Ecozone 20 Verified Site 1 CR Type 1
Area of Significance _____ Ecozone _____
Area of Significance _____ Ecozone _____

Recorded By E. Sakariassen & K. Troendle Date Recorded 03/11/2018
(First Name & Last Name) (mm/dd/year)

**NDCRS ARCHITECTURAL SITE FORM
PAGE 2—Feature Data**

Field Code MAC-112

SITS# 32 BK 206

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 2

Construction Date _____

Feature Type 9

Condition 5

Feature Date 4

Context 30

Plan Shape 5

Structural System 25

Primary Exterior 26

Style Utilitarian

Original Owner's Ethnicity _____

Secondary Exterior _____

Architect/Builder _____

Other Information: _____

Foundation None Stories 1.0

Roof/Cornice Gable-front; asphalt shingle

Window Original openings intact, most original sash intact

Dating Method(s): Professional Estimate

Feature Preservation Recommendation(s) (Check all that apply):

Individual nomination

Contributes to a potential district

No nomination potential

Will not contribute to a district

Potential district—feature would be a contributing element if other properties constitute a district

Thematic nomination potential

Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

Historical associations require further investigation

Recorded By E. Sakariassen & K. Troendle
(First Name & Last Name)

Date Recorded 03/11/2018
(mm/dd/year)

**NDCRS ARCHITECTURAL SITE FORM
PAGE 3—Feature Data**Field Code MAC-112SITS# 32 BK 206**Complete a Page 3 for each feature.****1. Feature Description, Integrity, Eligibility:**

DESCRIPTION: Feature 2 is a public building, likely a one-room schoolhouse, that has been moved onto the property. It is wood-framed with a gable-front roof and nested gable-roofed vestibule on the east side. Aside from this vestibule, the feature has a rectangular footprint and is currently sitting atop concrete blocks. The exterior is clad in horizontal clapboards. The roof is covered in asphalt shingles. The windows appear original and consist of one-over-one-lite double-hung sash. The primary entry is on the north side of the entry vestibule and consists of a paneled wood door with three vertically-divided window lites.

INTEGRITY: The feature is in fair condition. Some window glass is broken and the exterior materials show signs of prolonged exposure and deferred maintenance. Paint is failing and the shingles are worn affecting integrity of materials. Due to the building's relocation, integrity of location, association, setting, and feeling have been lost.

ELIGIBILITY: This feature has been evaluated for eligibility against the NRHP Criteria. It is found to lack integrity sufficient to convey historic character in reference to associations with events that have made significant contribution to the broad patterns of our history under Criterion A, historically significant persons under Criterion B, characteristics of a type, period, or method of construction under Criterion C, and it is unlikely to yield important information in reference to research questions under Criterion D. Metcalf recommends this feature not eligible for inclusion in the NRHP.

Recorded By E. Sakariassen & K. Troendle Date Recorded 03/11/2018
(First Name & Last Name) (mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code MAC-112SITS# 32 BK 206

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 4

Construction Date _____

Feature Type 9Condition 5Feature Date 4Context 30Plan Shape 5Structural System 25Primary Exterior 26Style Utilitarian

Original Owner's Ethnicity _____

Secondary Exterior _____

Architect/Builder _____

Other Information: _____

Foundation None Stories 1.0Roof/Cornice Gable-front; asphalt shingleWindow Original openings intact, some original sash remainsDating Method(s): Professional Estimate

Feature Preservation Recommendation(s) (Check all that apply):

 Individual nomination Contributes to a potential district No nomination potential Will not contribute to a district Potential district—feature would be a contributing element if other properties constitute a district Thematic nomination potential Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

 Historical associations require further investigationRecorded By E. Sakariassen & K. Troendle
(First Name & Last Name)Date Recorded 03/11/2018
(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM
PAGE 3—Feature DataField Code MAC-112SITS# 32 BK 206**Complete a Page 3 for each feature.****1. Feature Description, Integrity, Eligibility:**

DESCRIPTION: Feature 4 is a public building, likely a schoolhouse, that has been moved onto the property. It is wood-framed with a gable roof. The feature has a rectangular footprint with no foundation. The exterior is clad in horizontal clapboards, the roof is covered in asphalt shingles. The primary entry is a paneled wood door centered on the east gable end. Above the door, in the apex of the gable, is a single-lite awning window. Two windows are on the north elevation and two are on the south elevation. The windows are two-over-two-lite double-hung windows but the sash on the north elevation is in very poor condition with no remaining glass; the windows on the south elevation have been covered with plywood. A single-lite window is the only fenestration on the west gable end, and is located in the apex of the gable.

INTEGRITY: The feature is in fair condition. Exterior materials show signs of prolonged exposure and deferred maintenance. Paint is failing and windows have been damaged, affecting integrity of materials. Due to the building's relocation, integrity of location, association, setting, and feeling have been lost.

ELIGIBILITY: This feature has been evaluated for eligibility against the NRHP Criteria. It is found to lack integrity sufficient to convey historic character in reference to associations with events that have made significant contribution to the broad patterns of our history under Criterion A, historically significant persons under Criterion B, characteristics of a type, period, or method of construction under Criterion C, and it is unlikely to yield important information in reference to research questions under Criterion D. Metcalf recommends this feature not eligible for inclusion in the NRHP.

Recorded By E. Sakariassen & K. Troendle Date Recorded 03/11/2018
(First Name & Last Name) (mm/dd/year)

**NDCRS ARCHITECTURAL SITE FORM
PAGE 4—SITE DESCRIPTION**Field Code MAC-112SITS# 32 BK 206**Complete one Page 4 for the entire site.**

2. Owner's Contact Information:

3. Access (to rural areas):

From the intersection of ND Highway 5 and ND Highway 40, approximately 0.5 miles south of Columbus, turn south onto ND Highway 40 and continue south for 11.6 miles. Turn east onto 91st St NW and continue for 0.3 miles. The site is accessed by a gravel two track located south of of 91st St NW.

4. Site Area (ft²): 2,203,7735. Description of **SETTING**:

The site is set on top of a hill in rolling upland topography with kettle lakes to the east and south. A mature shelter belt runs north and east, separating a modern quonset and a number of auto bodies and modern grain bins that are at the northwest end of the site.

Recorded By E. Sakariassen & K. Troendle Date Recorded 03/11/2018
(First Name & Last Name) (mm/dd/year)

**NDCRS ARCHITECTURAL SITE FORM
PAGE 5—SITE DESCRIPTION**Field Code MAC-112SITS# 32 BK 206**6. Summary of ALL Site Features & Evaluation of Significance:**

MAC-112 is a farm consisting of 9 architectural features. Feature 1 is a single-story house composed of two double-wide trailer houses combined to form an L-shaped structure. Feature 2 is a public building, likely a one-room school house, which has been moved onto the property. Feature 3 is a small wood-framed structure, likely a child's play house. Feature 4 is a second public building, likely a school house, which has been moved onto the property. Feature 5 is a pair of cylindrical metal grain bins manufactured by Husky. Feature 6 is a cylindrical metal grain bin. Feature 7 is a wood-framed, gable-roofed machine shed/storage building. Feature 8 is a series of four surplus holding tanks that have been made into grain bins. Feature 9 is a series of surplus holding tanks of a slightly different build that have been made into grain bins. Overall, the site is in good condition. These features vary in age, condition, and level of integrity. Alterations and deferred maintenance have had most affect on the site's integrity of materials.

According to the 1914 Atlas of Burke County, L.C., Adamson owned 160 acres in the northeast quarter of section 33 in Leaf Mountain Township, which would include the location of site MAC-112 (George A. Ogle and Co. 1914). However, Metcalf has deduced from historic aerial imagery that all features recorded, including Features 2 and 4, were built or moved onto the property after 1961 and any structures associated with previous occupations are no longer extant (NDSWC 2015).

Site MAC-112 has been evaluated for eligibility against the NRHP Criteria. It is found to lack significant association with events that contribute to the broad patterns of our history under Criterion A or persons considered significant under Criterion B. The site does not represent significant characteristics of a type, period, or method of design under Criterion C, and is unlikely to yield important information in reference to research questions under Criterion D. This site is recommended not eligible for inclusion in the NRHP.

7. References/Comments:

George A. Ogle and Co.

1914 Standard Atlas of Burke County, North Dakota. George A. Ogle and Co., Chicago, IL

ND State Water Commission

2015 Burke County, 1961 [aerial photograph]. 1:20000. Aerial Imagery Map Service

<https://aerial.swc.nd.gov/>, accessed 3/22/2018.

Recorded By E. Sakariassen & K. Troendle Date Recorded 03/11/2018
(First Name & Last Name) (mm/dd/year)


NDCRS SITE FORM ATTACHMENTS SECTION

Field Code: MAC-112

SITS# 32BK




Atwell
Burke County Wind Farm
Burke County, ND
MAC-112



181818 - 3/22/2018

TRS: 161N. 93W. sec.33

1:2000



NAD 1983 UTM Zone 13N



- Architectural Feature
- Postcontact Site

Figure 1: Sketch map of site MAC-112 depicted on aerial imagery.

NDCRS SITE FORM ATTACHMENTS SECTION

Field Code: MAC-112

SITS# 32BK



Figure 4: Site MAC-112, Feature 2, view southwest (Image 108-530).



Figure 5: Site MAC-112, Feature 2, view northeast (Image 108-533).

NDCRS SITE FORM ATTACHMENTS SECTION

Field Code: MAC-112

SITS# 32BK



Figure 8: Site MAC-112, Feature 4 with Feature 2 in the background, view northeast (Image 108-537).



Figure 9: Site MAC-112, Feature 4, view southwest (Image 108-538).