	NDCRS ARC	<i>HITECTU</i> PAGE				ATE
Field Code QCRS-N	MC2A			SITS# 32 B	O 945	
SITE IDENTIFICATION			me <u>Adela</u>	aide School		
LTLTWP LTLTWP			QQQ	QQ QQ		Q <u>5</u> Q Q
NAD 1983, UTM NAD 1983, UTM	601788 N 511287 E	ZONE	13N			Subsection: $1 = N\frac{1}{2}$
City:						$2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$
Street Number:						$4 = W^{1/2}$ $5 = NE^{1/4}$
Street Name:						6 = SE¼ 7 = SW¼ 8 = NW¼
Urban Legal Description	:		_			O = INVV /4
SITE DATA						
Total # <u>Architectural</u> Fe	eatures: 1					
Fieldwork Date: 0	7/18/2023					
Reconnaissance Survey	/ Int	ensive Surve	ey 🖌			
Project & Principal Inves Bowman Wind Farm - M Report Title & Author(s):	litigation - Kristyn V	Vard, Archite	ctural His	storian		
Contracting firm or Agen	icy completing the f	orm:				
Quality Cultural Resour	ce Services/Impact	7G				
Additional Information: Additional photos includ	led in the NDCRS A	Attachments	Section o	f this site.		
SHSND USE Area of Significance Area of Significance Area of Significance	Ecozone		Verified S	Site	CR Type	9
Recorded By	Kristyn W	ard		Date Recorde	ed0	7/18/2023
	ne & Last Name)		_			(mm/dd/year)

	ARCHITECTURAL SITE	FORM
Field Code QCRS-MC2A		SITS# 32 BO 945
Complete one Page 2 for each	<u>architectural feature</u> at th	
Architectural Feature #1		
Construction Date1916	Feature Type	Condition 4
Feature Date	Context	Plan Shape
Structural System	Primary Exterior	Style <u>Not Applicable</u>
Original Owner's Ethnicity	Secondary Exterior <u>N/A</u>	Architect/Builder
Other Information:		
Poured concrete		_Stories
Roof/Cornice		
Window		
Dating Method(s):		the book "Prairie Tales", 1916 or 1917.
Individual nomination		
Contributes to a potential distr	ict	
No nomination potential		
Will not contribute to a district		
Potential district—feature wou	ld be a contributing element if oth	er properties constitute a district
Thematic nomination potential	I	
Component of a historic site o	r landscape	
recreates original site, orientat	choices)—a) relocation occurred v tion, landscape, & spatial relations) relocation has damaged eligibility	hips; c) compatible in context
Historical associations require	further investigation	

Recorded By	Kristyn ward Date Recor		07/18/2023	
,	(First Name & Last Name)		(mm/dd/year)	

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

UPDATE

Field Code QCRS-MC2A

SITS# 32 BO 945

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

[2023] When the site form was originally completed in 2020 the school building was recorded as having only one story. During the 2023 visit the interior was documented and shows a complete basement level. Additionally, in 2020 a weather vane base on the top of the steeple was noted and that the weather vane was missing. Interviews with Braatan and Hedrickson tell us that it was the base of the flag pole and that the flag pole is missing, not a weather vane.

Interior descriptions in 2020 refer to "main room" but interior inspection have shown that the interior consisted of two spaces that were previously divided into classroom space on the south half of the school and a teacherage on the north half of the school. The wall was built during the teaching tenure of Lois Anderson, at which point she lived in the northern half of the school. The teacherage was not moved at the time that the living quarters were established in the school, it was sometime after.

Additionally, Hendrickson recalled shoveling coal from the addition on the western side of the school house in order to feed the coal burning stove and heat the building. He mentioned that about two years before he finished school they changed to a different heating system that used a different type of fuel from a tank that was mounted on the roof of the addition. The tank is no longer on the roof of the addition.

Extensive damage has been done to the main floor of the Adelaide Schoolhouse. The ceiling has holes that proceed through the roof and sunlight can be seen. This has allowed rain and snow to penetrate the roof and caused the plaster to rumble. Laths behind the plaster are visible and in some places missing. Other portions of the walls are exposed brick where the plaster has crumbled. Interior door frames and interior transom window frames are largely intact. The hardware for opening and closing the interior transoms are still attached to the door frames, however only one is still attached to the transom as well. One remaining interior door is still attached to the hinges and opens to the stairwell that leads to the girls' toilet.

The basement level of the school and is accessed by a stairwell in the northeast corner. Floors and walls in the basement are poured concrete with brick completing the basement walls from about ground level to the base of the main floor walls. Windows in the basement are all missing and the frames are bent or missing, likely due to the bowing foundation.

Exterior window frames are largely in tact on the main floor and still contain some of the original hardware, however most glass panes are broken or have sustained bullet holes.

Recorded By	Kristyn Ward	Date Recorded	07/18/2023
	(First Name & Last Name)		(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

UPDATE

Field Code QCRS-MC2A

SITS# 32 BO 945

Complete one Page 4 for the entire site.

2. Owner's Contact Information:

Charlotte Miller, 806-620-2202

3. Access (to rural areas):

4. Site Area (ft²):_____

5. Description of **SETTING**:

[2023] An oral history interview with two students, Gerald Braaten and Gerald Hendrickson, who attended school here provided more information about additional structures previously located at the school.

Hendrickson stated that there was previously a barn with two additions on the west edge of the lot behind the school. The barn was removed during Hendrickson's tenure at the school and historic aerials do not show a barn at this location, which hows that it was removed prior to 1957.

Hendrickson also indicated that a teacherage was located to the north of the school. Analysis of historic aerial photos show the teacherage still on site in 1957. Lois Anderson, a student and teacher at the Adelaide Schoolhouse discussed living in the teacherage before moving into the northern half of the schoolhouse building once the Braaten family constructed a dividing wall in the classroom space.

Recorded By	Kristyn Ward	_ Date Recorded	07/18/2023
	(First Name & Last Name)		(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

UPDATE

Field Code QCRS-MC2A

SITS# 32_BO_945

6. *Summary of ALL* Site Features & Evaluation of Significance:

[2023] Updated information on this site shows that two of the three original structures are no longer at the location, which has impacted the historic integrity of the setting. Hendrickson, along with at least two other families that he could remember, rode horses to school from the surrounding farms. With the barn missing from the location, evidence of some students using that mode of transportation would have remained unknown without the oral history to add context.

The removal of the teacherage has also changed the setting of the schoolhouse. Teachers had to stay at the location if they did not live close enough to commute daily. An interview with Hendrickson showed that some of his teachers did live in the teacherage. An interview with Anderson shows that she lived in the teacherage as well prior to moving into the school.

The remaining architectural feature is a good example of a brick rural schoolhouse, however the structure is badly deteriorated. The basement walls have substantial cracks and bowing, the floors on the main floor have holes down to the basement level. The roof also has holes, which has allowed the interior to be weathered with the plaster walls and ceilings crumbling in most places. However, the Adelaide Schoolhouse does contribute to the historic rural schoolhouse time period and is an example that could be added to the Country School House Project that was started in 2009.

7. References/Comments:

References are included in an attached report. Oral history recordings and transcriptions are also included for the State Archives and NDSHPO Ref# 20-0335.

Recorded By	Kristyn Ward	Date Recorded	07/18/2023
	(First Name & Last Name)		(mm/dd/year)

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.



Figure 1. View of front of QCRS-MC2A facing west.



Figure 2. View of front and south sides of QCRS-MC2A facing northwest.

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.



Figure 3. View of south side of QCRS-MC2A facing north.



Figure 4. View of rear and south side of QCRS-MC2A facing northeast.

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.



Figure 5. View of rear of QCRS-MC2A facing east.



Figure 6. View of rear and north side of QCRS-MC2A facing southeast.

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.



Figure 7. View of north side of QCRS-MC2A facing south.



Figure 8. View of front and north side of QCRS-MC2A facing southwest.

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.



Figure 9. Detail of windows on north side of QCRS-MC2A facing south.



Figure 10. Additional exterior window details on front of QCRS-MC2A facing west.

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.



Figure 11. Detail of addition on rear of QCRS-MC2A facing south.



Figure 12. Roof details on addition to rear of QCRS-MC2A facing east

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.



Figure 13. Detail of addition on rear of QCRS-MC2A facing northeast.



Figure 14. Detail of bell tower on QCRS-MC2A facing northwest.

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.



Figure 15. Detail of roof elements and vent behind bell tower on QCRS-MC2A facing southwest.



Figure 16. Detail of flagpole attachment on bell tower of QCRS-MC2A facing southeast.

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.



Figure 17. Detail of roof line and chimney on rear of QCRS-MC2A facing southwest.



Figure 18. Detail of doorframe on front of QCRS-MC2A facing west.

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.



Figure 19. Inside QCRS-MC2A front door in vestibule facing southwest into classroom.



Figure 20. Inside QCRS-MC2A front door showing doorway to girls' toilet stairway, facing south.

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.




Figure 21. Stairway in south corner of QCRS-MC2A to girls' toilet facing south.

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.




Figure 22. Stairway in southeast corner of QCRS-MC2A towards girls' toilet, directed west.

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.



Figure 23. Girls' toilet in QCRS-MC2A facing east.



Figure 24. Facing east up stairway from girls' toilet in QCRS-MC2A.

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.



Figure 25. From south interior first floor doorway facing southwest.



Figure 26. Interior QCRS-MC2A southwest corner facing northeast.

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.



Figure 27. Southwest corner QCRS-MC2A facing northeast showing door to vestibule and exit.



Figure 28. Southwest corner QCRS-MC2A facing east showing window and wall details.

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.



Figure 29. South window details in QCRS-MC2A.



Figure 30. North and east window details facing northeast in QCRS-MC2A.

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.



Figure 31. Ceiling details slightly south of center of rear wall in QCRS-MC2A.



Figure 32. Ceiling details in northwest corner of interior QCRS-MC2A.

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one Attachments Section for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.



Figure 33. Forced air registers on center of rear wall facing west.



Figure 34. Forced air register in vestibule, interior wall between vestibule and classroom, south side of QCRS-MC2A.

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.



Figure 35. Stairway from vestibule to basement in northeast corner of QCRS-MC2A.



Figure 36. View into basement through interior window in stairwell facing south.

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.



Figure 37. Ductwork in basement, doorway to boys' toilet pictured, facing south.



Figure 38. Entrance to room in basement along east wall, doorway to boys' toilet in background.

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.



Figure 39. North portion of basement room facing north, opposite boys' toilet.



Figure 40. Boys' toilet in basement facing south.

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.



Figure 41. Doorway into basement room along eastern side of building. Interior stairwell window also visible, facing northwest.



Figure 42. At base of stairs into basement, facing west, doorway pictured leads to rear addition.

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.



Figure 43. Doorway into rear addition, facing southwest.



Figure 44. Detail of first floor supports as they rest on basement foundation, rear of building facing southwest.

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.



Figure 45. Ductwork and cement wall, rear of basement facing south.



Figure 46. Addition on rear of building, photo taken from doorway in basement facing south.

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.



Figure 47. North basement wall showing bowed foundation.



Figure 48. Northeast basement windows facing north.

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one Attachments Section for the entire site. Include: Topographic map (with guad name and legal description), sketch map, photographs, and any other attachments.



Figure 49. aerial photograph from 1957 showing teacherage to the north of QCRS-MC2QA

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.




Figure 50. aerial photograph from 1972 showing the teacherage location north of QCRS-MC2A vacant.

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.

Historic Context:

Bowman County, North Dakota was organized by the state legislature in June 1907 with Bowman being made the official county seat in July 1907. Many people moved to Bowman County as the Northern Pacific Railroad sold their land holdings in the county to private companies after filing bankruptcy. Western Land Securities Company out of St. Paul, Minnesota then sold these acres to homesteaders. Railroads did not make a direct route to Bowman County until 1908, however the anticipation of the arrival still encouraged homesteaders to settle the county and helped fuel the settlement boom. The county population grew from 172 in 1885 to 4,668 by 1910, with Rhame alone hosting a population of roughly 500 people by 1911.

One of the townships to benefit from the population boom was Adelaide Township. Little Adelaide Schoolhouse was built in 1909 and was originally a wooden structure roughly two miles to the south of the current brick building. However, the wooden structure was replaced around 1916-1917 to accommodate the growing student population in the township, which peaked in Bowman County by the 1930 census with a total count of 5,119.

Many one room schoolhouses had additional buildings on the property and Adelaide was no exception. Though most schools had privies separate from the school structure, Adelaide had both girls' and boys' toilets located within the school building itself. The girls' toilet was down a set of stairs in the southeast corner and the boys' was in the basement. Also in the basement was access to coal storage through a doorway into the addition on the western side of the building. Students would take turns shoveling the coal into the stove that heated the building.

The Department of Public Instruction also issued a pamphlet in 1904 with information to help schoolhouses organize or improve their classrooms. One suggestion that David Kidd quoted in his article, "A Woman's Quest to Visit North Dakota's One-Room Schools" from a 1904 pamphlet by the Department of Public Instruction, "Gray, dull green, and tan are good colors," and while we cannot say for certain that this pamphlet inspired the color choices in the Adelaide Schoolhouse when it was constructed approximately 12 years after the pamphlet was issued, remnants of "dull green" paint can still be seen on portions of the plaster on the interior.

Adelaide also had a teacherage near the school. Not all teachers lived in the teacherage at the school, particularly if their homes were close enough that they could commute for classes. Lois Anderson, a teacher at Adelaide School, started her tenure living in the teacherage but moved into the main schoolhouse once a divider was built between the two large areas on the main floor, which provided her with living space. The teacherage appears on aerial photographs in 1957 but it was sold and moved from the location prior to the next available photograph taken in 1972.

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.

Adelaide School stands out from many of the other one-room schools. Typically, one teacher presided over students in first through eighth grade. However, Adelaide students could attend the first two years of high school at the schoolhouse for a few years after it was opened. These high school grades were only offered at the Adelaide Schoolhouse for a short time. Prior to officially consolidating, the high school grades were moved to Rhame and Bowman.

Many one-room schoolhouses like Adelaide were built in locations to allow students who had to walk or ride horses to school to reach the schools. Adelaide school had a barn located to the west of the schoolhouse to accommodate students who rode horses. Prior to the earliest aerial photograph taken in 1957 students no longer rode horses and the barn no longer existed. Many students got rides to school from family members but those who did not were bused to Rhame after the consolidation.

Though recent years have seen an increase in population in North Dakota as a whole, rural areas have continued to suffer a continuous decline since the 1980s and a consistent, though not steady, decline since the 1930s. Much of the decreasing population trend can be attributed to the Dust Bowl and economic downturn in the 1930s during the Great Depression.

Another factor causing the decrease in rural populations on the Northern Great Plains can be attributed to the advancement in farm technology, which allowed fewer workers to do more work. Farm size could also be increased because the mechanical equipment helped decrease the labor load and increase the productivity on the acreage. Increasing farm sizes can be seen by comparing statistics from 1910 and 1969. In 1910 approximately 30% of Bowman County was part of established farms. By 1969, only a few years after Adelaide School closed, roughly all of the available land in North Dakota was part of established farms. Yet despite the substantial increase in farmed land there were half as many individual farms as there had been in 1910.

Declining rural populations caused many of the one-room schoolhouses in the United States to consolidate into larger districts as a cost-saving measure and Adelaide schoolhouse was just one of hundreds that were consolidated when it was closed in 1960. The remaining 11-12 students who were still attending Adelaide Schoolhouse, including Gerald Braaten and the one other student in his grade, were sent to Rhame to finish their public education after consolidation.

Adelaide was not be the last school to be consolidated either. Though the overall state population grew 14.8% between 2010 and 2021, the most recent numbers show that the rural population decreased in North Dakota by almost 14%. Bowman County alone saw a 7.6% decrease in population and information available for Adelaide Township specifically shows only 29 people lived in the township as of 2010.

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.

Between 1961 and 1999, North Dakota school districts shrank from over 1,000 to less than 230. By 2022 school districts shrunk even further to 173 districts with only five one-room schools still in use in North Dakota. Despite Adelaide being consolidated into the Rhame school district, Rhame also did not survive the consolidation movement unscathed with the high school closing in 2007. Though the Rhame Elementary School does continue to serve students in kindergarten through the 6th grade.

Recorded By Kristyn Ward

Date Recorded 07/18/2023

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.

Sources

Bowman County, North Dakota <u>https://en.wikipedia.org/wiki/Bowman_County,_North_Dakota</u> – Accessed 08/13/2023

- Bowman County School District #1 https://www.bowman.k12.nd.us/page/about-us-elementary – Accessed 08/16/2023
- Genealogy Trails History Group, Bowman County, North Dakota Genealogy and History <u>http://genealogytrails.com/ndak/bowman/history.html</u> Accessed 08/13/2023
- Hudson, John, "Two Dakota Homestead Frontier," in Annals of the Association of American Geographers. Dec 1973, Vol. 63, Issue 4, P 442-462. Accessed via EBSCO on 08/16/2023. <u>https://research.ebsco.com/c/75sext/viewer/pdf/j7eb5e3n35</u>
- Kidd, David, "A Woman's Quest to Visit North Dakota's One-Room Schools," in Governing: The Future of States and Localities, published 07/07/2022. Accessed on 08/16/2023 <u>https://www.governing.com/context/a-womans-quest-to-visit-north-dakotas-one-room-schools</u>
- Kidd, David, "North Dakota's Small Schools Fight for Survival," in Governing: The Future of States and Localities, published 06/23/2022. Accessed on 08/16/2023 <u>https://www.governing.com/now/north-dakotas-small-schools-fight-for-survival</u>
- Manso, Kathleen Kennedy, "N.D. Schools Struggle With Enrollment Declines," published in Education Week on 11/03/99. Accessed on 08/16/2023 via EBSCO. https://research.ebsco.com/c/75sext/viewer/html/smjdnscblr
- North Central Regional Center for Rural Development, "Why Do People in the North Central Region Leave Their Rural Communities?" published on 01/21/2022. Accessed on 08/16/2023. <u>https://ncrcrd.ag.purdue.edu/2022/01/21/why-do-people-in-the-north-central-region-leave-their-rural-communities/</u>
- Public School Review: Rhame High School <u>https://www.publicschoolreview.com/rhame-high-school-profile</u> – Accessed 08/16/2023

Rural Area Development Committee, Prairie Tales, published 1965.

Recorded By Kristyn Ward

Date Recorded 07/18/2023 NDCRS SITE FORM ATTACHMENTS SECTION

Field Code QCRS-MC2A

SITS# 32 BO 0945

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.

USA Facts, Our Changing Population: North Dakota <u>https://usafacts.org/data/topics/people-society/population-and-demographics/our-changing-population/state/north-dakota/</u> – Accessed 08/16/2023

Zentner, Joe, "From the Old West to Modern Times on the Prairie, Children Often Learned in One-Room Schoolhouses." Wild West. April 2006. Vol. 18 Issue 6, P 60-61. Accessed via EBSCO on 08/16/2023. <u>https://research.ebsco.com/c/75sext/viewer/pdf/yai2lrfdxj</u>

Recorded By Kristyn Ward

Date Recorded 07/18/2023

NDCRS ARCHITECTURAL FORM PAGE 1

UPDATE

Field Code <u>QCRS-M</u>	C2A			SITS# 32 BO	945
Map Quad <u>Rhame, ND</u>					
Map Quad		5	Site Name		
LTLT. <u>131</u> N., R LTLTN., R LTLTN., R LTLTN., R NAD <u>1983</u> UTM NAD <u>1983</u> UTM City: Street Number:	W., Sec W., Sec W., Sec 601788 5112874	QQQ QQQ Zone 	_ of the QQ _ of the QQ _ of the QQ I <u>3N</u> _	of the Q of the Q	1 = N ¹ / ₂ 2 = E ¹ / ₂
Street Name:					
Urban Legal Description:					
Total Number of Archite		1			
Fieldwork Date: 05/	28/2020				
Reconnaissance Survey	✓	Intensive	e Survey		
Project & Principal Invest	tigator:				
Bowman Wind Farm - Lind	dsay D.J. Scott (Ard	cheology) an	d Mark Carpente	er (Architectural	History)
Contracting Firm or Agen	ncy Completing the	e Form:			
Quality Cultural Resource	Services				
Additional Information:					
SHSND USE Component Component Component	-	Verif	ed Site	_ CR Type	
Recorded By:	Mark Carp	enter	Date F	Recorded:	05/28/2020

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS SITE FORM CONTINUATION PAGE

Field Code

SITS# 32BO0945

Complete a *Continuation Page(s)* for information that does not fit in the space available on other sections of a Site Form.

The warranty for Adelaide School was possibly established by George S. Madden in 1923. Further details about the school

Date	Deed	Grantor	Grantee	Description	Vol.	Page
2/8/1923	Warranty	State of North	George S.	Adelaide	30	485
2/0/1/25	warranty	Dakota	Madden	School		
11/22/10/6	Contract	State of North	Le e Varla eth		84	55
11/23/1946	for Deed	Dakota	Joe Kulseth			
		Joe and Ruth	John Rouzie		74	176
3/1/1957 Warrant	Warranty	Kulseth	and L. J.			
	_	Kuisein	Flados			
9/7/1057	Contract	John Rouzie and L.	Melvin Miller	Contract for	84	189
8/7/1957	for Deed	J. Flados	Mervin Miller	Deed		
		Ico and Duth	John Rouzie	Correction to	74	236
1/8/1962	Correction	Joe and Ruth Kulseth	and L. S.	Warranty		
		Kuisein	Flados	Deed - 1957		

Table 1. Land Transfers for Township 131 N, Range 104 W, Section 21 NE/NE

Lindsay D.J. Scott

Date Recorded

NDCRS ARCHITECTURAL FORM

PAGE 2 – Feature Data

			OFDATE
Field Code <u>QCRS-MC2A</u>		S# 32 <u>BO</u>	945
Complete one Page 2 for each architectura	I feature at the site.		
Architectural Feature # <u>1</u>			
Construction Date			
Feature Date <u>1915-1930</u>			
Structural System Wood Frame			
Original Owner's Ethnicity			
Feature Type 9 - School; Church school			
Context Education			
Primary Exterior Brick			
Secondary Exterior			
Condition Fair			
Plan Shape Square			
Style Craftsman			
Architect/Builder			
Foundation Earthen Brick	Stories1.	0	
Roof/Cornice Hipped			
WindowMost original windows and openings	intact		
Dating Method(s) Professional Estimate			
Miscellaneous Information 1917 Bowman C	ounty Atlas does not indicate	school; Base	ed on Style it is circa 1920
Feature Preservation Recommendation(s)	(Check all that apply):		
 Individual nomination 	(oncon an that apply).		
Contributes to a potential district			
No nomination potential			

- _____Will not contribute to a district
- _____Potential district—feature would be a contributing element if other properties constitute a district
- _____Thematic nomination potential
- Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) __relocation has damaged eligibility

_____Historical associations require further investigation

 Recorded By:
 Mark Carpenter
 Date Recorded:
 05/28/2020

NDCRS ARCHITECTURAL FORM

PAGE 3 – Feature Data

UPDATE

Field Code QCRS-MC2A

SITS# 32 BO 945

Complete one Page 3 for each architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

This feature consists of a schoolhouse with entry foyer and shed style addition on its back (west) side. It is a single story structure with a half basement. The main building has a hipped roof with the foyer having a mansard style roof under a bell steeple. A metal weather vane base is on top of the steeple; however, the weather vane is missing. The wood roof has asphalt shingles over top and is eroded on the edges and has open-ended rafters. A brick chimney is on the back end of the main building and the top of the chimney is falling apart. The roof peak of the main room is oriented north-south while the foyer has a peak oriented east-west. The exterior of the schoolhouse contains light yellow/tan bricks with red brick half basement and white protruding brick wainscotting. The main entry way (east facing) consists of a small concrete porch with metal pipe railings leading to the entry way door which is missing. There is a lower door, also east facing, to the north of the main entry door; however, this door has been boarded up. The majority of the windows on the main floor are four-over-four with several short windows in the half basement. Overall, this structure is deteriorating and in poor condition.

The schoolhouse retains historic integrity of location, setting, design, materials, workmanship, feeling, and association. The setting has been compromised due to transmission lines and oil developments; however, these are minor visual intrusions into the overall landscape.

This schoolhouse is recommended eligible under Criteria A and Criteria C due to its association with rural education in southwestern North Dakota and because it embodies distinctive characteristics of craftsman style schoolhouse from circa 1920.

2. Owner's Contact Information:

Charlotte Miller

	Recorded By:	Mark Carpenter	Date Recorded:	05/28/2020
--	--------------	----------------	----------------	------------

NDCRS ARCHITECTURAL FORM PAGE 4 – Site Description

Field Code QCRS-MC2A

SITS# 32 BO 945

UPDATE

3. Site Area (ft²): 2,225

4. Description of Access and Site Setting:

From the intersection of Main Street and U.S. Highway 12 in Rhame, North Dakota, proceed southwest on Rhame Road (Main Street) for approximately 4.9 miles. Turn right (west) on what is believed to be 87th Street (unmarked road approximately 0.22 miles south of existing substation) and proceed for 1 mile. Schoolhouse is located at the first intersection (on what is believed to be 159th Avenue and 87th Street) on the southwest side of the intersection.

5. Summary of ALL Site Features and Evaluation of Significance:

Site contains one feature a circa 1920 schoolhouse. This schoolhouse retains much of its historic integrity and, although deteriorating, serves as a good example of rural schoolhouses from this time period.

6. References/Comments:

None.

NDCRS SITE FORM

ATTACHMENTS SECTION

Field Code QCRS-MC2A

SITS# 32BO

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.




Figure 1. Site Location Map for QCRS-MC2A. T131N, R104W, Section 21 USGS 7.5' Rhame, North Dakota topographic quadrangle 1973

Recorded By Mark Carpenter (First Name & Last Name) Date Recorded

05/28/2020 (mm/dd/year)

NDCRS SITE FORM ATTACHMENTS SECTION

Field Code QCRS-MC2A

SITS# 32BO

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.




Figure 2. Site plan for QCRS-MC2A

Recorded By Mark Carpenter (First Name & Last Name) Date Recorded 05/28/2020 (mm/dd/year)

NDCRS SITE FORM ATTACHMENTS SECTION

Field Code QCRS-MC2A

SITS# 32BO

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.



Figure 3. View of front of QCRS-MC2A facing west.



Figure 4. View of front and south sides of QCRS-MC2A facing northwest.

Recorded By Mark Carpenter (First Name & Last Name) Date Recorded

05/28/2020 (mm/dd/year)

NDCRS SITE FORM ATTACHMENTS SECTION

Field Code QCRS-MC2A

SITS# 32BO

Complete one *Attachments Section* for the entire site. Include: Topographic map (with <u>quad name</u> and <u>legal description</u>), sketch map, photographs, and any other attachments.



Figure 5. View of front and north sides of QCRS-MC2A facing west-southwest.



Figure 6. View of rear and north sides of QCRS-MC2A facing east-southeast.

Recorded By Mark Carpenter (First Name & Last Name) Date Recorded

05/28/2020 (mm/dd/year)

	NDCRS SITE FORM ARCHITECTURAL SITES Page 1
	SITS # <u>32</u> BD
	Field Code Sullisger Site Name School houser
	Map Quad <u>Rhame</u> 1. N ¹ / ₂ Map Quad 2. E ¹ / ₂
SITE DATA	LTL Twp Image: R Image: QQ QQ
^	City
	Street # Street #
	Street Name Street Name
	# of Features
URE DATA	O.I. Feature # O.O. Feature Type O. Condition Construction Date Context * O.O. Feature Type O. Condition Feature Date Context * O.O. Primary Exterior * Secondary Exterior Structural System ** O.O. Primary Exterior * Secondary Exterior Ethnic Style * Architect/Builder O.S.O.S.G.S.G.S.G.S.G.S.G.S.G.S.G.S.G.S.
SHSND US	Area Signf MS Number Soil Association Ecozone Area Signf MS Number Soil Association Ecozone Area Signf MS Number MS Number MS Number CR Type Verified Site Non-Site State Registry State Registry Stational Register
	Coder LTPTI Date Coded 8/2/97 Reconnaissance Survey IS.D.S. VENEDULIT MIntensive Survey Manuscript/Report Title:
	Author(s): Isera & Velure

in w

Ν		ECTURAL SITE	FORM
	F	bage 1A	
Field Code SU 159	Feature	Number	SITS # <u>32</u>
	DESCRIP	TIVE SECTION	
FOUNDATION	STORIES	ROOF TY	PE / CORNICE
WINDOW CONDITION	He	gable	hip
WINDOW CONDITION]	DATING METHO	DD
fair		profession	nal estimate
PRESERVATION RECOM	MENDATION (check all that appl	y)
1) 🔀 Individual Nominat	ion 2)	Contributes to a	potential district
3) No nomination pote			
·			be a contributing element if
neighboring properti			
6) \times Thematic nomination	on potential	7) Compone	nt of historic site/landscape
8) Feature has an impo	rtant physical, sp	atial, functional, h	nistoric or architectural
relationship to the si	te/complex/farms	tead	
9) Moved: A) relocation	on occurred within	n historic period.	B) recreates original site,
orientation, landscap	e and spatial char	acteristics. C) co	mpatible in context with
neighboring structure	es. D) relocation	has damaged elig	ibility.
10) Request comparati	ve study of neigh	boring properties	
11) Historical associat	ions require furth	er investigation	

DESCRIPTION/INTEGRITY/ELIGIBILITY

2.1


This substantial schoolhouse dates from about 1920. It has a foundation of poured concrete and clay tile. The school is constructed of brick of more than one shade, ranging from light red to buff. It also makes ornamental use of poured concrete just above the foundation on the exterior wall, just under the eves on the exterior wall, and in the sills of the windows. The school has a hip roof covered with asphalt shingles. The banks of all double-hung windows on the north and south walls are in fair condition at best--the wood frame is deteriorating and most of the glass is broken out. A distinctive feature of the building is the belfry rising to a point from the hipped base at the top of the front entry way (front door missing) on the east side of the building. The steps up to the entry are poured concrete with rails of 2 inch pipe. A massive brick chimney is directly opposite the entry way on the west face of the roof. This leads to the furnace and the basement of the building. On this (west) wall is a shed-roof addition to the building that is a coal room. This coal room is constructed of clay tile and shingled with wood shingles. It has an entry door on its south side and a small window on that side also. Coal was deposited through two square holes in the roof of this coal room. There is a full, finished basement under the school. The basement is accessible via a second doorway on the east wall to the north of the main entry. It also is accessible by staircases leading from the fover downstairs to the left and right. On the

Urban Legal Description _____ X SEE CONTINUATION SHEET entry level, the foyer leads into two classrooms, on the north and the south, equal sides. The partition wall between the two classrooms was removable in order to make one large room. In fact, the partitions are removed and are stored in the basement. The interior of the school has been severely vandalized.

27

12


Despite much of the superficial damages done by the elements and by vandalism, this building remains structurally sound. In all respects its integrity remains high. It represents an attempt to preserve rural education in the countryside by the construction of rural consolidated schools. This gives the building importance and significance in association with the historical theme of education in North Dakota. This site should be considered for nomination to the National Register as an individual property or as part of a thematic nomination of rural consolidated schools.




Photograph	ic Coverage, Hist	oric Arch	itectural Survey	of Bowman	n Count	y, 1997		
Roll $()$	Frame 20	Site SU	159Feature	Date	818	View from	SE	
Subject:	School hou	SP.						


22

. ..









12


1.1

Photographic	Coverage	, Hist	oric Architectur	ral Survey	of Bowman County, 1997
Roll DDDD	Frame	1	Site SU 159	Feature	Date 7/17/98 View from NE
Subject:	Scho	0/6	mice.		



 Roll DDDD Frame
 Site SU 159 Feature
 Date 7/1/168 View from 56

 Subject:
 Subject:



Photographic	Coverag	e, Hi	storic Arc	hitectu	ral Survey of	Bowman County, 1997	
RollDDDD	Frame	3	Site SL	1159	Feature	Date 7/11/78 View from	SE
Subject:	Belf	rs.	m so	600	1Louse		



hotographic oll ү \/	Frame	22	Site SU				Date &	18	View fr	om C
ubject: So	reath	183	inda	NUS	al	Sch	000	hau	I GP	
	-								-	
					Û			ľ	1	1
			ap an an air					Concession.		
the second									In	
							2			
State State					5					
と言い	SE.		-							
	A .	AND	*			Bit in			11:	
And the second second					15				I I A	
		Cara Cara			EXAT				L	Herst
inerstellande Normalisette	2) - Carlos		1	and the second			1			Constant
E. as	ICL /CL						G	IE-II		
	and and a					1. and - 100 (3) (3)	Da		1	
			CALIFIC PROPERTY AND ADDRESS OF						1.1.15	AN DECEMBER AND DECEMBER AND ADDRESS AND ADDRE ADDRESS AND ADDRESS

42 . 12.

Roll / 1/ Frame 4 Site SU 59 Feature Date 2/2 View from SUS Subject: Coal com and distion

