

NDCRS ARCHITECTURAL FORM

PAGE 1

UPDATE

Field Code Fairview School #1

SITS# 32 BU 158

Map Quad Antler NW

Site Name Fairview School #1

Map Quad

Site Name

LTL T. 163 N., R. 83 W., Sec. 16 QQQ 5 of the QQ 6 of the Q 5

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

NAD 1983 UTM 5424070 Zone 14N

NAD 1983 UTM 321981

Subsection
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

City:

Street Number:

Street Name: 33rd Avenue

Urban Legal Description:

Total Number of Architectural Features: 1

Fieldwork Date: 7/19/2020

Reconnaissance Survey

Intensive Survey

Project & Principal Investigator:

Country School House Project
Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Contracting Firm or Agency Completing the Form:

Additional Information:

SHSND USE

Component Study Unit Verified Site CR Type

Component

Component

Recorded By: Kathy Wilner Date Recorded: 8/6/2020

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM  
PAGE 2 – Feature Data

Field Code Fairview School #1

SITS# 32 BU

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date 1904

Feature Date 1900-1915

Structural System Wood Frame

Original Owner's Ethnicity \_\_\_\_\_

Feature Type 9 - School; Church school

Context Education

Primary Exterior Wood, Horizontal Siding

Secondary Exterior Stone, Uncut

Condition Excellent

Plan Shape Rectangular

Style Other Style

Architect/Builder \_\_\_\_\_

Foundation Uncut stone with cement Stories 1

Roof/Cornice Hip on the school, gable entry

Window Double hung, glass intact

Dating Method(s) School History

Miscellaneous Information \_\_\_\_\_

**Feature Preservation Recommendation(s) (Check all that apply):**

Individual nomination

Contributes to a potential district

No nomination potential

Will not contribute to a district

Potential district—feature would be a contributing element if other properties constitute a district

Thematic nomination potential

Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

Historical associations require further investigation

Recorded By: Kathy Wilner Date Recorded: 8/6/2020

**NDCRS ARCHITECTURAL FORM**  
**PAGE 3 – Feature Data**

Field Code Fairview School #1SITS# 32 BUComplete one Page 3 for *each* architectural feature at the site.

## 1. Feature Description, Integrity, Eligibility:

The feature is a large one/two room school on a basement of uncut stone in cement. The roof of the building has been covered with green metal sheeting. There is a cupola above the entry at the southeast corner of the school. The cupola houses the original bell. The entry and cupola are also roofed with green sheet metal. The four sides of the cupola are filled in with lattice work painted white. The top of each opening has a curved board for decoration. The soffits are closed. The school measures about 40 feet north to south and 30 feet east to west.

A rake board begins the siding under the roof eaves on all four sides and a water board completes the siding. The rest of the siding is 6 inch wood lap with 4 inch wood corner trim. The front of the entry has decorative cornice returns with a diamond patterned insert above the door. A half moon window sits about a solid core entry door. Access to the entry is up six steps to a platform porch which has rails on both sides.

Many windows give lots of light to the interior of the school. The west side has three small double hung windows as well as one tall one. Also on the west side are three basement windows, one fixed pane and two three fixed pane windows. The south side has two large double hung windows and two three pane windows in the basement. The north side has three large double hung with with two more basement windws, one three pane and the other two. On the east side there are three double hung windows with yet more basement windows, this time a pair of three pane windows next to each other. All glass intact. Wide cornices adorn all the upper windows. The walls in the school are wallboard and the ceiling is pressed tin. There is a beadboard divider hanging down from the ceiling about about three feet that was likely used to put up a divider to make two rooms. Blackboards are located in the northwest corner of the room as well as between windows on the east side with a long blackboard on the west wall under the higher placed windows. The entry leads into a spacious coat room and has a door to the basement. 4 panel wood doors give entry into the main room of the school, both sides can be separate and there is also a door to the basement. There is wainscot throughout the school. Lots of furnishings of the time.

The basement has tongue and groove flooring (as does the school room) as well as beadboard ceiling. There are also toilets. Walls downstairs are cement as well as lathe and plaster. Light fixtures, switches and electrical cord are evidence of electricity. The school was built in 1904 and closed in 1959.

## 2. Owner's Contact Information:

Duane & Ladonna Feland  
 3125 Cty Rd 2  
 Antler ND 58711

Recorded By: Kathy Wilner Date Recorded: 8/6/2020

**NDCRS ARCHITECTURAL FORM**  
**PAGE 4 – Site Description****Field Code** Fairview School #1**SITS#** 32 BU3. Site Area (ft<sup>2</sup>):

4. Description of Access and Site Setting:

The school sits just north of an abandoned farm site with farm fields all directions. It is located on 33rd Avenue. Take 107th St NW west of Antler 6 miles to 33rd Ave NW. Go south about 1 1/2 miles to see the school on the west side of the road.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Information and photo's shared by Lorie Yocum.

**Recorded By:** Kathy Wilner **Date Recorded:** 8/6/2020

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.



West Side

Fairview School #1


7192020

Kathy Wilner

TO

South  
Side





East Side

Fariview School #1

7/19/2020

Kathy Wilner

BU

North Side





Imagery ©2020 Google, Imagery ©2020 CNES / Airbus, Landsat / Copernicus, Maxar Technologies, USDA Farm Service Agency, Map data ©2020 2000 ft

Feature