(mm/dd/year)

### NDCRS ARCHITECTURAL SITE FORM PAGE 1

		·/(OL ·	SIT	<b>IS# 32</b> BU	760
SITE IDENTIFICATION					
Field Code Scandia #1		Site Name So			
Map Quad Roth		Site Name			
Map Quad					
LTL TWP 163 R	78 SEC	5 qqq[	a QQ	8	Q 8
	SEC _	. <u>.</u> QQQ.			<u> </u>
LTL TWP R	R SEC _ R SEC _	QQQ _ QQQ _			=
UTM 542688	3 IN	70NF		ſ	
UTM 367048	114	ZONE NAD 1	13N 927 NA	D 1983	Subsection: 1 = N½
City:					2 = E½ 3 = S½
Street Number:					4 = W½
[ door o. th			=		5 = NE1/4 6 = SE1/4
Street Name: 108th St N	70				7 = SW1/4
Urban Legal Description:			_	l	8 = NW1/4
SITE DATA					
Total # <b>Architectural</b> Fea	itures: 1				
Fieldwork Date: 3/	18/2020				
Reconnaissance Survey	Intens	ive Survey			
Project Title & Supervisor:	:				
Country Schoolhouse Pro	oject				
Report Title & Author(s):					
Additional Information:					
SHSND USE Area of Significance Area of Significance	Ecozone	Verified Site Non-Site _		CR Type .	2
Recorded By	Kathy Wilne	er	Date Reco	orded 5/23	/2020

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

(First Name & Last Name)

# NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Recorded By Kathy (First Name & Last Name)	Wilner Date	te Recorded 5/23/2020		
	. VA/CL	- F/00/0000		
Historical associations require t	further investigation			
—_with neighboring structures; d)		onships; c) compatible in context vility		
Moved (specify all applicable cl	hoices)—a) relocation occurre	ed within a historic period; b)		
——Component of a historic site or landscape				
Thematic nomination potential				
Potential district—feature would be a contributing element if other properties constitute a district				
Will not contribute to a district				
No nomination potential				
Contributes to a potential district	ct			
Individual nomination				
Feature Preservation Recommend	dation(s) (Check all that a	ipply):		
Dating Method(s): Estimate				
The state of the s				
Roof/Cornice Gable Window Double hung, some class				
Cabla		Stories1		
Foundation Poured Concrete		Otarias 1		
Other Information:				
Original Owner's Ethnicity	Secondary Exterior	Architect/Builder		
Structural System 25	Primary Exterior 26	Style Other Style		
Feature Date 2	Context 7	Plan Shape 5		
Construction Date	Feature Type 9	Condition 4		
Architectural Feature # 1				
Complete one Page 2 for each architectural feature at the site.				
Field Code Scandia #1		SITS# 32 BU		

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

## NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

	FAGE 3—Feature Date	V-2
Field Code Scandia #1		SITS# 32 BU

#### Complete a Page 3 for each feature.

#### 1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a concrete foundation. The roof is covered with pieces of asphalt shingles over wood shakes. The roof on the west side is falling in. There is a red brick chimney with some bricks broken off. Metal capping with finials seals the peak on both the entry and the school. The soffits are open.

A rake board runs under the peaks of the roof followed by 6 inch wood lap siding with 6 inch corner trim. There is an entry at the north end of the building with a 5 panel wood door. There is one broken, double hung window on the north wall of the entry, no glass left. There are two pairs of two over two double hung windows on the east wall of the school with some glass. Four more two over two, double hung windows are on the south wall, again some glass. There is one narrow window on the north side of the school room and I believe the coatroom is between the entry and the school room. A 4 panel wood door leads into the school room from that coatroom. Two half moon windows are located above the blackboards on the west wall. The interior walls are wallboard and beadboard with much of it fallen off. The ceiling is wall board over lathe and much of the wallboard has fallen. The floor is tongue and groove hard wood. There is a lot of junk laying around in the school. A picture rail can be seen on some of the walls and there is an oil burning stove on the north wall of the school. Light fixtures and outside electrical lines indicate electricity.

(First Name & Last Name)

(mm/dd/year)

## NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Scandia #1	SITS# 32 BU
Complete one Page 4 for the entire	site.
2. Owner's Contact Information: Conrad and Clarice Tande 9950 6th Ave NW Souris ND 58783	
	W 5 miles to 5th Ave NW. Turn right and go north to 5 miles school is located on the first farm site. It is an abandoned
4. Site Area ( <b>ft</b> ²):	
	site with trees directly west as well as south. There are ll building. Farm fields are all directions around the farm
Recorded By Kathy Wiln (First Name & Last Name)	Date Recorded 5/23/2020 (mm/dd/year)

### NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

PAGE 5—3ITE DESCRIPTION				
Field Code Scandia	#1		SITS# 32	BU
6. Summary of ALL Site Features & Evaluation of Significance:				
7. References/Comment Kathy Wilner 366 43rd Ave SE Bowdon ND 58418	ts:			
Photos and information	provided by Lorie Arc	len Yocum		
	Kathy Wiln	er	Date Recorded	5/23/2020
(First Nan	ne & Last Name)			(mm/dd/year)



South Side

Scandia #1 3/18/2020 Kathy Wilner BU

West Side





North Side

Scandia #1

3/18/2020 Kathy Wilner BU

East Side





Imagery ©2020 Google, Imagery ©2020 Maxar Technologies, USDA Farm Service Agency, 100 ft Feature