

NDCRS ARCHITECTURAL FORM
PAGE 1

Field Code Lincoln School #1

SITS# 32 BU 783

Map Quad Overly
Map Quad

Site Name Lincoln School #1
Site Name

LTL T. 160 N., R. 74 W., Sec. 9 QQQ 5 of the QQ 7 of the Q 8
LTL T. N., R. W., Sec. QQQ of the QQ of the Q
LTL T. N., R. W., Sec. QQQ of the QQ of the Q
LTL T. N., R. W., Sec. QQQ of the QQ of the Q

Subsection
1 = N1/2
2 = E1/2
3 = S1/2
4 = W1/2
5 = NE1/4
6 = SE1/4
7 = SW1/4
8 = NW1/4

NAD 1983 UTM 5394872 Zone 14N
NAD 1983 UTM 409650

City:

Street Number:

Street Name: 89th St NE

Urban Legal Description:

Total Number of Architectural Features: 1

Fieldwork Date: 05/14/2021

Reconnaissance Survey [checked]

Intensive Survey

Project & Principal Investigator:

Country School House Project
Kathy Wilner
366 43rd Ave SE, Bowdon, ND 58418

Contracting Firm or Agency Completing the Form:

Additional Information:

SHSND USE
Component Study Unit Verified Site CR Type
Component
Component

Recorded By: Kathy Wilner Date Recorded: 06/03/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM
PAGE 2 – Feature Data

Field Code Lincoln School #1

SITS# 32 BU 783

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date _____

Feature Date 1880-1900

Structural System Wood Frame

Original Owner's Ethnicity _____

Feature Type 9 - School; Church school

Context Education

Primary Exterior Wood, Horizontal Siding

Secondary Exterior _____

Condition Excellent

Plan Shape Rectangular

Style Other Style

Architect/Builder _____

Foundation Poured concrete Stories 1.0

Roof/Cornice Gable

Window Double hung with glass

Dating Method(s) School History

Miscellaneous Information _____

Feature Preservation Recommendation(s) (Check all that apply):

Individual nomination

Contributes to a potential district

No nomination potential

Will not contribute to a district

Potential district—feature would be a contributing element if other properties constitute a district

Thematic nomination potential

Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

Historical associations require further investigation

Recorded By: Kathy Wilner Date Recorded: 06/03/2021

**NDCRS ARCHITECTURAL FORM
PAGE 3 – Feature Data**Field Code Lincoln School #1SITS# 32 BU 783**Complete one Page 3 for each architectural feature at the site.**

1. Feature Description, Integrity, Eligibility:

This feature is a one room school moved to this farm yard and placed on a poured concrete foundation. The gable roof is covered with asphalt shingles. There is a yellow brick chimney at the peak of the roof at the north end. A bell tower sits at the peak of the roof on the south end. The bell tower has asphalt shingles on the roof. There are four posts supporting the roof of the bell tower from a box finished with 6 inch wood lap siding. The school measures 28 feet east to west and 42 feet north to south. The soffits are closed. There are cornice returns at both the north and south ends of the roof.

The siding begins with a rake board under the eaves on all sides of the school. The remainder of the siding is 6 inch wood lap with 6 inch wood corner trim. There is a 5 panel wood door on the south side for entry. A curved transom window above the door is covered. The west side has three small covered arched windows and one larger double hung window that is located in the coat room. The north side has two double hung windows and the east side has 5 double hung windows, all the glass is intact. The walls and ceiling are finished with lathe and plaster and were later covered with tiles. The entry walls and ceiling are all finished with similar tiles. The door between the coat room and school room is a 4 panel wood door with a transom window above it. The doors and windows all have fancy wood trim. The floors are tongue and groove hardwood covered with linoleum. There is a blackboard on the west wall. It has been wired for electricity.

The school opened in 1896 and closed in 1937.

2. Owner's Contact Information:

Michael Haberman
505 Vinje St
Bottineau, ND 58318

Recorded By: Kathy Wilner **Date Recorded:** 06/03/2021

NDCRS ARCHITECTURAL FORM
PAGE 4 – Site Description**Field Code** Lincoln School #1**SITS# 32 BU 783**3. Site Area (ft²):

4. Description of Access and Site Setting:

This building is located on a farm with bins to the south, trees west, a house north and more small buildings to the south and east. Access to this school is from Bottineau ND, go east on Hwy 4 for about 4 1/2 miles to Hwy 60. Go south on Hwy 60 7 and 1/2 miles to 89th St NE. turn left and go east about 3 1/2 miles. The school is at the end of the drive way just east of 22nd Ave NE.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Photos and information shared by Lorie Yocum.
Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Recorded By: Kathy Wilner **Date Recorded:** 06/03/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.



East Side

Lincoln School #1

5/14/2021

Kathy Wilner

BU

West
Side





South Side

Lincoln School #1

5/14/2021

Kathy Wilner

BU



North Side

Google Maps Lincoln School #1 5/14/2021 Kathy Wilner BU



Imagery ©2021 CNES / Airbus, Maxar Technologies, USDA Farm Service Agency, 500 ft
Map data ©2021

Feature