NDCRS ARCHITECTURAL FORM PAGE 1

			_

Field Code			SITS# 32 DV	198
			Long Creek Twp Sch	
Map Quad Paulson Map Quad		Site Name	Bounty School	
LTL T. <u>163</u> N., R LTL T N., R LTL T N., R LTL T N., R	W., Sec W., Sec	_ QQQ of the Q _ QQQ of the Q	Q of the Q Q of the Q	1 = N½ 2 = E½ 3 = S½
NAD 1983 UTM	634213 St NE :			4 = W½ 5 = NE¼ 6 = SE¼ 7 = SW¼ 8 = NW¾
Fieldwork Date: 05 Reconnaissance Survey		Intensive Survey _	<u>~</u>	
Project & Principal Inves WAWSA 29 Mile Waterlin		/ Abbott		
Contracting Firm or Agel Beaver Creek Archaeolog		Form:		
Additional Information: Structure has been demo	olished.			
SHSND USE Component Component	_	Verified Site	CR Type	
Recorded By:	Melody Abl	oott Da	ate Recorded:	05/15/2023

NDCRS ARCHITECTURAL FORM PAGE 2 – Feature Data

UPDATE

Field Code		SITS# 32 <u>DV</u>	<u> 198 </u>
Complete one Page 2	for each architectural feature	at the site.	
Architectural Feature #	1		
Construction Date			
Feature Date			
Structural System			
Original Owner's Ethnic	ity		
Feature Type			
Primary Exterior			
Condition Destroye			
Plan Shape			
Roof/Cornice			
	on		
	Recommendation(s) (Check a		
Individual nomin	nation	,	
Contributes to a	potential district		
No nomination p	ootential		
Will not contribu	te to a district		
Potential district	—feature would be a contributir	ng element if other properties	constitute a district
Thematic nomin	ation potential		
Component of a	historic site or landscape		
site, orientation,	all applicable choices)—a) reloc landscape, and spatial relations amaged eligibility		
Historical associ	iations require further investigat	ion	
Recorded By:	Melody Abbott	Date Recorded:	05/15/2023

NDCRS ARCHITECTURAL FORM PAGE 3 – Feature Data

	PAGE 3 - F	eature Data	UPDATE
Field Code		SITS# 32 <u>DV</u>	198
Complete one Page 3 for each archited	ctural feature at	the site.	
1. Feature Description, Integrity, Eligibili	ty:		
Site 32DV198 is the Long Creek Towns Wilner in 2017. It was a one-story, one-basement foundation. A hipped roof was brick chimney on the south slope. The wood lap siding. Two 1/1 windows were double-hung 1/1 windows on the west double-hung 1/1 windows on the north one on the west elevation, along with a The main entrance was on the east ele additional 5-panel door was located on hardwood floors and wallboard on the external wiring suggested electricity.	room schoolhouses covered with as schoolhouse had be located on the schoolhouse along with elevation. Basement fuel door, four on evation, and it had a the west elevation.	e measuring 30' by 30' on a perpendict shingles and had a repowood-frame construction covoluth elevation along with a both a smaller boarded-up operent windows included two on the north elevation, and two broken wooden steps leading at ground level. The interior	coured concrete aired red and yellow ered with horizontal bard-up opening, three hing, and eight the south elevation, on the east elevation. If to a 5-panel door. An
The site was visited during the current and removed from the property. Aerial traces of the feature had been removed Service [HMAPDS]). Additionally, aerial that the schoolhouse has been at this leads to county, North Dakota," shows that the	imagery shows that d by 2020 (Historical imagery from the ocation since at le schoolhouse was	at the schoolhouse was demo cal Map and Aerial Photograp HMAPDS and Historic Aeria ast 1946. The 1915 "Standar not present at that time.	olished in 2017, and all ohy Dissemination als.com/viewer shows d Atlas of Divide
historic integrity. Consequently, site 32 References: Geo. A. Ogle. 1915. Standard Atlas of Netronline. 2023. Historic Aerials Views	Divide County, No	-	on to the NKHP
2. Owner's Contact Information:			
Recorded By:Melody /	Abbott	Date Recorded:	05/15/2023

32DV198 Update



Figure 1. Overview of site area, view west.




Figure 2. Overview of site area, view south.




32DV198 Update UTM: 634,213 E; 5,418,968 N T163N R96W Sec. 29 Paulson Quad. Map, Souris River Drainage Divide County, North Dakota






Legend







NDCRS ARCHITECTURAL SITE FORM PAGE 1

SITS# 32 DV /98 SITE IDENTIFICATION Field Code Long Creek Township School Site Name Long Cree Site Name Rounty Map Quad Paulson Map Quad LTL __ TWP __163 __ R __ SEC __29__ QQQ __ LTL __ TWP ____ SEC ____ LTL __ TWP _ SEC _ QQQ _ LTL __ TWP _ SEC _ QQQ _ UTM _____5418863 ZONE 13N Subsection: UTM ______624395 NAD 1927 ___ NAD 1983 \(\bullet\) $1 = N\frac{1}{2}$ $2 = E\frac{1}{2}$ City: $3 = 5\frac{1}{2}$ $4 = W^{1/2}$ Street Number: 5 = NE1/4 6 = SE1/4 Street Name: 103rd St NE $7 = SW\frac{1}{4}$ $8 = NW\frac{1}{4}$ Urban Legal Description: SITE DATA Total # Architectural Features: _____1 Fieldwork Date: 8/21/2016 Reconnaissance Survey Intensive Survey ____ Project Title & Supervisor: Country Schoolhouse Project Report Title & Author(s): Additional Information: SHSND USE Area of Significance Ecozone -Verified Site . Area of Significance Ecozone -Non-Site _ Area of Significance _ **Kathy Wilner** Date Recorded_ Recorded By 2/2/2017 (First Name & Last Name) (mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code Long Creek Township School SITS# 32 DV				
Complete one Page 2 <u>for each architectural feature</u> at the site.				
Architectural Feature #1				
Construction Date	Feature Type9	Condition 4	Auginosopy Auginosopy	
Feature Date 3	Context 7	Plan Shape	6	
Structural System 25	Primary Exterior <u>26</u>	Style Other S	Style	
Original Owner's Ethnicity	Secondary Exterior	Architect/Bui	lder	
Other Information:				
Foundation Poured concrete bas	ement	Stories1		
Roof/Cornice_Hip				
Window Openings, very little fran	ning, no glaass			
Dating Method(s): Estimate		ng Papakanan annya kita kaon manalakan ni kaon dapakan milan minya da hawan na ma		
 Feature Preservation Recommendation(s) (Check all that apply): Individual nomination Contributes to a potential district No nomination potential Will not contribute to a district Potential district—feature would be a contributing element if other properties constitute a district Thematic nomination potential Component of a historic site or landscape Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility Historical associations require further investigation 				
Recorded By (First Name & Last	Kathy Wilner Da	te Recorded	2/2/2017 (mm/dd/year)	

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

	Field	Code	Long	Creek	Township	School
--	-------	------	------	-------	----------	--------

CIT	104	22	DV	
2011	21	.52		

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature, also known as Bounty School, is a one room school on a poured concrete basement. The cross hipped roof is covered with asphalt shingles. A large red and yellow repaired brick chimney is located on the south slope of the entry part of the roof. The soffits are closed with shiplap. The building measures 30 feet north to south by 30 feet east to west.

Siding begins with a wide trim board at the top of the exterior wall just under the soffits. The rest of the siding is 6 inch wood lap with 6 inch wood corner trim with waterboard and a skirting board at the bottom. There is little paint left on the building. Below the siding are window openings, 2 on the south side, 1 on the west along with a fuel door, 4 on the north side. There are two window openings on the south side of the entry with some framing and glass, another window closer to the east end of the south side is coverd. There is also one more window on the west side of the entry portion as well as a door at ground level that most likely intersects with the steps going down from the upper level. There are 3 double hung window openings on the west side of the school room and there is little framing and no glass. On the north side there are 8 windows openings with no frame or glass. Without goint inside we could see blackboards on the east wall and the south part of the entry wall. There is a 5 panel wood entry door up some broken steps. There porch support is gone and the roof is sagging. There is wall board on the walls and ceiling. Tongue and groove hardwood covers the floor. Light fixtures and exterior wiring suggest electricity.

Recorded By	,Kathy Wilner	Date Recorded	2/2/2017
	(First Name & Last Name)		(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Long Creek Township School	SITS# 32	DV
Complete one Page 4 <u>for the entire site</u> .		
2. Owner's Contact Information: Paul Brady PO Box 351 Crosby ND 58730		
3. Access (to rural areas):		
From Highway 5 east of Crosby 5 miles to 113th Ave NW, turn le 103rd St NW and drive about 1/2 mile east.	eft and drive north 1 r	nile, turn right onto
4. Site Area (ft²):		
5. Description of SETTING :		
There is a lake to the east and southeast and the school is now directions.	part of a farm site. C	ropland all
Recorded By Kathy Wilner	Date Recorded_	2/2/2017
(First Name & Last Name)		(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Long Creek Town	nship School	SITS# 32_	DV
6. Summary of ALL Site	Features & Evaluation o	of Significance:	
7. References/Comments:			
Kathy Wilner			
366 43rd Ave SE Bowdon ND 58418			
Recorded By(First Name & Las	Kathy Wilner	Date Recorded	2/2/2017 (mm/dd/year)



West Side

Long Creek Township School 8/21/2016

Kathy Wilner DV

North Side






East Side

Long Creek Township School 8/21/2016

Kathy Wilner DV

South Side





Long Creek Township School

8/21/2016

Kathy Wilner

DV



Imagery @2016 Google, Map data @2016 Google 500 ft