State Historical Society of North Dakota

NDCRS ARCHITECTURAL SITE FORM PAGE 1

SITE IDENTIFICATION Field Code Lexington School Site Name Map Quad Site Name	
Map Quad Crosbn SW Site Name	
Map Quad	
LTL TWP 162 R 98 SEC 16 QQQ 6 QQ 6 Q 6 LTL TWP R SEC QQQ QQ QQ QQ Q Q 0 LTL TWP R SEC QQQ QQ QQ Q Q LTL TWP R SEC QQQ QQ QQ Q Q	
UTM N ZONE Subsection UTM E NAD 1927 NAD 1983 1 = N ¹ / ₂	on:
City: $2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$	
Street Number: 4 = W½ 5 = NE¼	
Street Name: 123rd Ave NW 6 = SE¼ 7 = SW½	
Urban Legal Description:	i
SITE DATA	
Total # Architectural Features:1	
Fieldwork Date:8/21/2016	
Reconnaissance Survey Intensive Survey	
Project Title & Supervisor:	
Country Schoolhouse Project	
Report Title & Author(s):	
Additional Information:	
SHSND USE	
Recorded By Kathy Wilner Date Recorded 2/2/2017)

State Historical Society of North Dakota

NDCRS 2009

NDCRS	ARCHITECTURAL SITE	FORM
	PAGE 2—Feature Data	

Field Code Lexington School		SITS# 32	<u>v</u>			
Complete one Page 2 for each architectural feature at the site.						
Architectural Feature #1						
Construction Date	Feature Type <u>9</u>	Condition 5				
Feature Date 3	Context 7	Plan Shape <u>5</u>	ana			
Structural System 25	Primary Exterior 26	Style Other Sty	yle			
Original Owner's Ethnicity	Secondary Exterior	Architect/Build	ler			
Other Information:						
Foundation Poured concrete, half base	ment	Stories11/2	_			
Roof/Cornice_Hip						
Window Double hung,						
Dating Method(s): Estimate						
Feature Preservation Recommendation(s) (Check all that apply): Individual nomination Contributes to a potential district No nomination potential						
Will not contribute to a district						
Potential district—feature would be a contributing element if other properties constitute a district						
Thematic nomination potential						
Component of a historic site or	landscape					
Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility Historical associations require further investigation						
Recorded By Kathy (First Name & Last Name)	Wilner Da	ate Recorded	2/2/2017 (mm/dd/year)			

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Lexington School

SITS# 32 DV

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a large, most likely two+ room, prairie school on a poured concrete half basement. The hip roof of the building, half hip of rht south dormer, modified hiup of the north large dormer as well as the half hip entry are all covered with wood shakes. There is a red brick chimney on the north slope, near the north dormer. The soffits were closed with beadboard but much of that is gone. There are some eaves troughs with down spouts. The building measures 62 feet east to west and 38 feet north to south excluding the entry as well as the north addition. The entry measures 14 feet north to south and 16 feet east to west.

There is a wide trim board running under the soffits on all four side of the school as well as the entry. The remainder of the siding is 6 inch wood lap with 4 inch wood corner trim. Near the bottom of the siding is a water board with skirting board. The top half of the lower level wall is stucco over wood. There are many windows in the school, the south dormer has three window openings, the north dormer has a total of 8 window openings. The main floor of the school has many large double hung windows, looks like the upper window was multipane but most of the glass is missing in all the windows. There were three on the south wall to either side of the entry, two sets of three windows on the east wall, one set of three on the west wall and 3 sets of three on the north wall, all with little framing and no glass. There are many double hung windows above ground in the half basement, little framing and no glass. Much trashing inside the lower level. A set of steps is in the north addition to give access to the lower level from the north side. This addition was used for storage. There is a wood stoop leading to, broken wood and glassless window openings, double doors with no steps remaining to give access. There is a wide wood staircase inside the doors that lead to the upperlevel. Stairs to either side of the central piece lead downstairs. The flooring that we saw is tongue and groove hardwood. The walls are lathe and plaster as is the ceiling. With no entry there is little information about the interior. Wires on the outside of the building suggest electricity.

Recorded By _	Kathy Wilner	Date Recorded	2/2/2017
	(First Name & Last Name)		(mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Lexington School

SITS# 32_DV_____

Complete one Page 4 for the entire site.

2. Owner's Contact Information: Mildred Anderson Rev Trust PO Box 1827 Williston ND 58802

3. Access (to rural areas):

From Crosby, going west on Highway 5, four miles west to 123rd Ave NW, turn left and go south four mile to see the school on the right.

4. Site Area (ft²):_____

5. Description of SETTING:

The land here is rolling hills with crop fields all ways.

Recorded By Kathy Wilner Date Recorded 2/2/2017
(First Name & Last Name) (mm/dd/year)

State Historical Society of North Dakota

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Lexington School

SITS# 32 DV

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By______(First Name & Last Name) **Kathy Wilner**

Date Recorded

2/2/2017 (mm/dd/year)



East Side





South Side

Lexington School8/21/2016Kathy WilnerDV



Google Maps



8/21/2016

Lexington School

Kathy Wilner

DV



Imagery ©2016 Google, Map data ©2016 Google 200 ft

Feature