NDCRS 2009

State Historical Society of North Dakota

NDCRS ARCHITECTURAL SIT	EFORM
PAGE 1	1015
	SITS# 32_DV_295

(First Name & Last Name)		disconstitution of	(mm/dd/year)
Recorded By Kathy Wilne	er Date	Recorded	2/2/2017
SHSND USE Area of Significance Area of Significance Area of Significance	Verified Site Non-Site	CR Type	2
Additional Information:			
Report Title & Author(s):			
Project Title & Supervisor: Country Schoolhouse Project			
Reconnaissance Survey 🖌 Intens	ive Survey		
Fieldwork Date: 8/21/2016			
Total # Architectural Features:1	-		
SITE DATA			
Urban Legal Description:			8 = NW¼
Street Name: 107th St NW			$6 = SE^{1/4}$ $7 = SW^{1/4}$
Street Number:			$4 = W\frac{1}{2}$ $5 = NE\frac{1}{4}$ $6 = 0E\frac{1}{4}$
City:			$2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$
UTMN UTME	ZONE NAD 1927	NAD 1983	
LTL TWP R SEC _ LTL TWP R SEC _ LTL TWP R SEC _	2 QQQ 7 QQQ 7 QQQ 0 QQQ 0 QQQ 0 QQQ 0	QQ QQ QQ	
Map Quad	- 7	7	
Map Quad SKjermo Lake	Site Name		
Field Code Elkhorn Township School #1	Site Name		
SITE IDENTIFICATION			

State Historical Society of North Dakota

NDCRS 2009

NDCRS	ARCHITECTURAL SITE FORM	
PAGE 2—Feature Data		

Field Code Elkhorn Township School #1					
Complete one Page 2 for each architectural feature at the site.					
Feature Type <u>9</u>	Condition 3				
Context.7	Plan Shape 3				
Primary Exterior <u>26</u>	Style Other Style				
Secondary Exterior	Architect/Builder				
	•				
Window Double hung openings Dating Method(s): Estimate Feature Preservation Recommendation(s) (Check all that apply):					
Individual nomination					
Contributes to a potential district					
No nomination potential					
Will not contribute to a district					
Potential district—feature would be a contributing element if other properties constitute a district					
Thematic nomination potential					
Component of a historic site or landscape					
Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility					
	architectural feature at the Feature Type9 Context 7 Primary Exterior 26 Secondary Exterior Secondary Exterior dation(s) (Check all that app dation(s) (Check all that app dation(s) = 100000000000000000000000000000000000				

_____Historical associations require further investigation

Recorded By	Kathy Wilner	Date Recorded	2/2/2017
(Fir	st Name & Last Name)		(mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Elkhorn Township School #1

SITS# 32 DV

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a poured concrete foundation. The intersecting gable roofs along with the half hip of the north addition have very few wood shakes. Remnants of a bell tower are located on the west gable of the entry and has a wood base with four corner posts to the supports of the top of the tower. There chimney is gone. The building measures 28 feet north to south and 20 feet east to west with the north addition measuring 6 feet by 12 feet and the entry 14 feet by 14 feet.

There is a wide trim board under the soffits on all the peak ends with the remainder of the siding 6 inch lap with 6 inch wood corner trim finished by waterboard and a skirting board. The siding is beginning to fall way from the planking. The porch leading to the entry door has fallen away from the school. All the doors are gone throughout the building. There is broken wood door opening into the entry. The walls in the entry are lathe and plaster with beadboard wainscot and much of the plaster is fall off. There are two small window openings on the north wall of the toilet addition. The toilets have 5 panel wood doors. There is a double hung window opening on the west wall of the entry. A diamond shaped opening above the window has no glass. The east wall is wide open with what looks like two sets of three windows with a set of two in the middle for a total of 8 windows, some framing and no glass. The walls and ceiling are lathe and plaster with some of the plaster falling off the walls and all of the ceiling plaster laying on the floor. The floor is tongue and groove hardwood. Blackboards are gone. A furnace is near the north wall with a furnace surround. There is wainscot throughout. No signs of electricity.

(First Name & Last Name)

Kathy Wilner

Date Recorded

2/2/2017 (mm/dd/year)

State Historical Society of North Dakota

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 4-SITE DESCRIPTION

Field Code Elkhorn Township School #1

SITS# 32_DV

Complete one Page 4 for the entire site.

2. Owner's Contact Information:

Murielle & Marshall Tangedal 10785 145th Ave NW Fortuna Nd 58844

3. Access (to rural areas):

From Fortuna, west on Highway 5 2 1/2 miles to 104th St NW which will turn into 144th Ave NW, turn right to go north about 6 1/2 miles, the road will wiggle west and north and go by Skjermo Lake. You are now on 145th Ave NW and you go to 107th St NW and turn left to drive west 1/2 mile to see the school on your right.

4. Site Area (ft²):_____

5. Description of SETTING:

This school looks out over a vast world of pasture and farm fields.

Recorded By (First Name & Last Name)

Kathy Wilner

Date Recorded

2/2/2017 (mm/dd/year)

State Historical Society of North Dakota

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Elkhorn Township School #1

SITS# 32_DV

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By Kathy Wilner (First Name & Last Name)

Date Recorded

2/2/2017 (mm/dd/year)





North Side



West Side

Elkhorn Township School #18/21/2016Kathy WilnerDV

South Side



Google Maps



8/21/2016

Kathy Wilner

DV





Imagery ©2016 Google, Map data ©2016 Google 200 ft