NDCRS ARCHITECTURAL SITE FORM

Lee School #1	PAGE 1 SITS# 32 DV 3	22
SITE IDENTIFICATION		25
Map Quad Stady	Site Name Lee School #1	
Map Quad	_ Site Name	
	31 QQQ 8 QQ 8	Q 5
		Q
LTL _TWP R SEC _ LTL _TWP R SEC _	QQQ QQ	<u>a</u>
NAD 1983, UTM 5389099 N NAD 1983, UTM 598947 E	ZONE 13N	Subsection: 1 = N½
City: Stady		2 = E½ 3 = S½
Street Number:		4 = W½ 5 = NE¼
Street Name: 137th Ave NW		6 = SE¼ 7 = SW¼
Urban Legal Description:		8 = NW1/4
SITE DATA		
Total # Architectural Features: 1		
Fieldwork Date: 6/11/2019		
Reconnaissance Survey V Intens	sive Survey	
Project & Principal Investigator: Country Schoolhouse Project		
Report Title & Author(s):		
Contracting firm or Agency completing the form	n:	
Additional Information:		
SHSND USE	7	- 0
Area of Significance Z Ecozone Z	✓ Verified Site	e 🚣
Area of Significance Ecozone Area of Significance Ecozone		
Kathy Wilner	1/18	2019
Recorded By (First Name & Last Name)	Date Recorded	/mm/dd/voor)

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code Lee School #1		SITS# 32 DV
Complete one Page 2 for e	each architectural feature	at the site.
Architectural Feature # 1		
Construction Date	Feature Type X 9	Condition 5
Feature Date 4	Context X 7	Plan Shape 5
Structural System 25	Primary Exterior 26	Style Other Style
Original Owner's Ethnicity	Secondary Exterior N/A	Architect/Builder
Other Information:		
Foundation Poured concrete		Stories 1
Roof/Cornice Crossed Gable		
Window double hung, little framin	g and no glass	
Dating Method(s): Estimate		
J. 110.110.100		
Feature Preservation Recom	mendation(s) (Check all th	at apply):
Individual nomination		
Contributes to a potential	district	
No nomination potential		
Will not contribute to a dis	strict	
Potential district—feature	would be a contributing elemen	t if other properties constitute a district
Thematic nomination pote	ential	A STATE OF THE PART OF THE PAR
Component of a historic s		
		urred within a historic period; b)
recreates original site, or		elationships; c) compatible in context
Historical associations re	quire further investigation	
Kathy Wilner		1/18/2019
(First Name & Last I		Date Recorded (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately, and save; (5) **Print** and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

And the second s	PAGE 3—Feature Data		
Field Code Lee School #1		SITS# 32 DV	

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a foundation of poured concrete. The roof of the school and entry are covered with asphalt shingles. The belfry has wood shakes on the peaked roof. Metal capping with finials can be seen at the peak of the school roof. The there is a stump of a chimney. The large, wood framed base, belfry sits on the roof of the entry. There is a flag pole at the peak of the belfry. The building measures 28 feet east to west and 20 feet north to south with a 12 by 6 foot addition for the toilets on the west side and a 14 by 8 foot entry on the south. The soffits are closed.

Wide trim boards run under the eaves at the peak ends of the school and entry as well as under the eaves of the bathroom addition. The siding is 6 inch wood lap with 6 inch corner trim. At the bottom edge of the siding there is a skirting board with watertable. The north side has many double hung window openings with no glass and little framing, there are three banks of three windows with plywood covering 5 of the window openings. There are two double hung windows, no glass, in the bathroom addition and another on the south side wall of the entry. On the entry south wall is a round topped window under the peak, again no glass. There is a small window on the west wall of the entry that was likely used for fuel. The entry is reached from a concrete platform covered porch area. The entry door is 5 panel wood, a second door that goes from the entry into the school room is also 5 panel wood. In the southwest corner of the school room is yet another door that looks to go into the fuel room. More doors lead into the bathrooms on the west wall of the school room.

The walls in the interior walls of the school are finished with lathe and plaster. Wainscot covers the lower third of the walls in the school proper. The entry also has lathe and plaster on the walls but no wainscot. The ceiling is pressed tin over lathe and plaster. The floor is tongue and groove hard wood. The blackboards have been removed. A fuse box and ceiling light fixtures indicate electricity was there.

Described De	Kathy Wilner	Date Recorded 1/18/2019	
Recorded by	(First Name & Last Name)	Date Recorded (mm/dd/year)	_

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Lee School #1	SITS# 32 ^{DV}
Complete one Page 4 for the entire sit	<u>e</u> .
Owner's Contact Information: Kay Bendixson Life Estate 618 17th Ave W Williston ND. 598801	
Access (to rural areas): From Highway 85 in Divide County, turn west NW. Turn right and go north about 1 mile to s	on 90th St NW and drive about 3 1/2 miles to 137th Ave ee the school on the west side of the road.
4. Site Area (ft²):	
 Description of SETTING: There is a farm site to the southeast of the sc fenced and not mowed. 	nool and farm land all directions. The immediate area is
}	
Recorded By Kathy Wilner	Date Recorded 1/18/2019
(First Name & Last Name)	(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Lee School #1	SITS# 32 DV
6. Summary of ALL Site Features & Eva	lluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By	Kathy Wilner	Date Recorded 1/18/2019	
	(First Name & Last Name)	(mm/dd/year)	



North Side

Lee School #1 6/11/2018 Kathy Wilner DV

East Side






West Side

Lee School #1

6/11/2018

Kathy Wilner

DV



South Side

1/9/2019 Google Maps



Kathy Wilner

DV



Imagery ©2019 Google, Map data ©2019 Google 200 ft

Feature