NDCRS ARCHITECTURAL FORM PAGE 1

Field Code Hamar School	SITS# 32 ^{ED} _	419
Map Quad Hamar Map Quad	Site Name Hamar School	
LTL T	QQQ 6 of the QQ 8 of the Q 5 QQQ of the QQ of the Q QQQ of the QQ of the Q QQQ of the QQ of the Q	Subsection 1 = N½ 2 = E½
NAD <u>20221983</u> UTM 531947 City: Hamar		5 = NE% 6 = SE% 7 = SW% 8 = NW%
Street Number:		0 - 1444/4
Street Name:1st St and 4th Ave Urban Legal Description:		į.
Total Number of Architectural Features:	1	
Fieldwork Date:10/30/2022		
Reconnaissance Survey	Intensive Survey	
Project & Principal Investigator: Country School House Project Kathy Wilner 366 43rd Ave SE Bowdon ND 58418	×	
Contracting Firm or Agency Completing the	Form:	
Additional Information:		
SHSND USE Component Study Unit18 Component Component	Verified Site CR Type	2
Recorded Bv: Kathy Wiln	er Date Recorded: 11/0	05/2022

NDCRS ARCHITECTURAL FORM PAGE 2 – Feature Data

Field Code Hamar School		SITS# 32 <u>ED 4</u>	19
Complete one Page 2 for eac		e site.	
Architectural Feature #1	ř		
Construction Date			
Feature Date <u>1900-1915</u>			
Structural System Wood Fr	ame		
Original Owner's Ethnicity			
Feature Type 9 - School; Chur	ch school		
Context <u>Education</u>			
Primary Exterior Wood, Ho	rizontal Siding		
Secondary Exterior			
Condition <u>Excellent</u>			
Plan Shape <u>Rectangular</u>			
Style Other Style			
Architect/Builder			
Foundation Poured concrete		Stories1	
Roof/Cornice Hip			
WindowDouble hung, multi pane			
Dating Method(s) Estimate			
Miscellaneous Information			
Feature Preservation Recomm	mendation(s) (Check all that	t apply):	
Individual nomination			
Contributes to a potenti	al district		
No nomination potential	I		
Will not contribute to a c	district		
Potential district—featur	re would be a contributing ele	ment if other properties cons	stitute a district
Thematic nomination po	otential		
Component of a historic	site or landscape		
	cable choices)—a) relocation ape, and spatial relationships; d eligibility		
Historical associations r	equire further investigation		
Recorded By:	Kathy Wilner	_ Date Recorded:	11/05/2022

NDCRS ARCHITECTURAL FORM PAGE 3 – Feature Data

SITS# 32 ED 419

Complete one Page 3 for each architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

This feature is a 2 room school located in a very small town. It is on a poured concrete foundation that raises the building up about 3 feet. The concrete foundation has covered openings to either side of the entry which may give access to the crawl space. The hip roof is covered with metal sheeting with metal capping on all seams. There are two shed additions on the south side that have failing asphalt shingles and some metal sheeting on the east addition. There is a tall, red brick chimney located near the edge of the roof on the south slope near the east end of the school. The soffits are closed. The school measures 53 feet east to west and 26 feet north to south. The east addition measures 16 feet by 16 feet with the bathroom addition measuring 16 feet north to south by 6 feet east to west.

The siding begins with a rake board under the eaves on all side of the school. The remainder of the siding on the school is 6 inch wood lap with 6 inch corner trim. A water board runs around the entire school. The two additions on the south side also have 6 inch wood lap siding with 6 inch corner trim. On the north side there is a bump out for the entry. A gable roofed portico leads to the school entry with walls on the east and west sides of concrete steps and platform. The bottom foot under the roof peak of the entry has a bit of decorative roofing which slants to the north. The same slanted foot adds decoration under the higher gable roof of the entry. A half moon window is located under the peak of the entry. Two additions are seen on the south side of the school. The east most addition has a door that faces east. There may have been a window on this wall as well. Inside concrete steps lead into the school at the southeast corner. This addition has a furnace and well located inside. The other addition is bathrooms. Two small windows face south from this addition. There is a small double hung window to either side of the portico. Stepping inside the entry door you can go either right or left to go into one or another of the school rooms. Just inside both school rooms are rows of coat hooks. All the doors are 5 panel wood doors with large transom windows. This school served all grades when it was in use. There are several, large double hung windows with intact glass. Two windows are located either side of the entry with two pair of similar windows on the west and east walls. One more window is located on the south side between the two additions. Some of the windows are covered. The floor is hardwood. The walls and ceiling are wallboard with wainscot on the lower 1/3 of the walls. Blackboards are located on either side of the center wall. More blackboards run along the south walls in both school rooms. A door near the entry wall gives acess to the other school room. Light fixtures and outside wiring speaks of electricity.

2. Owner's Contact Information:
Freeborn Township
Kevin Gleason, Supervisor, Chairman
2558 Hwy s0
Tolna Nd 58380

Date Recorded: 11/05/2022

NDCRS ARCHITECTURAL FORM PAGE 4 – Site Description

	PAGE 4 – SI	te Description	
Field Code Hamar School		SITS# 32 ED 419	
3. Site Area (ft²):			
school is located on the s north of the school is the	the small town of Hama south side of Hamar, so small town of Hamar, p	or ND. Hamar is NE of New Rockford. The outh of 1st St and west of 4th Ave. To the dopulation about 11 people. There are tree outh. The grounds around the school are	
5. Summary of ALL Site Featur	es and Evaluation of Signi	ificance:	
6. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418			
Recorded By:	Kathy Wilner	Date Recorded: 11/05/2022	



West Side

Hamar School 10/30/2022 Kathy Wilner ED

East Side





North Side

Hamar School

10/30/2022 Kathy Wilner ED

South Side





Imagery ©2022 CNES / Airbus, Maxar Technologies, USDA/FPAC/GEO, Map data ©2022

200 ft

Feature