NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM 326F3800			
PAGE 1 SITS# 32 ^{GF}			
SITE IDENTIFICATION			
Field Code Lind Township Hall Site Name Lind Township Hall			
Map Quad Northwood NW Map Quad			
LTLTWP 149 R 55 SEC 26 QQQ 8 Q 8 LTLTWP R SEC QQQ QQQ QQ Q Q 0 LTLTWP R SEC QQQ QQQ QQ Q			
UTM N ZONE Subsection: UTM E NAD 1927 NAD 1983 1 = N½ 2 = E½ 2 2 2			
City: 3 = S½			
Street Number: 5 = NE ¹ / ₄			
Street Name: 2nd Ave NE and 39th St NE 6 = SE¼ 7 = SW¼			
Urban Legal Description:			
SITE DATA			
Total # Architectural Features:1			
Fieldwork Date: 9/30/2017			
Reconnaissance Survey Intensive Survey			
Project Title & Supervisor:			
Country Schoolhouse Project			
Report Title & Author(s):			
Additional Information:			
SHSND USE Area of Significance Area of Significance Ecozone Non-Site			
Recorded By Kathy Wilner Date Recorded 2/16/2018 (First Name & Last Name) (mm/dd/year)			

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data			
Field Code		SITS# 32 GF	
Complete one Page 2 for each architectural feature at the site.			
Architectural Feature #1			
Construction Date	Feature Type <u>9</u>	Condition 5	
Feature Date 3	Context Z	Plan Shape 5	
Structural System 25	Primary Exterior 26	StyleOther Style	
Original Owner's Ethnicity	Secondary Exterior	Architect/Builder	
Other Information: Foundation Poured concrete Roof/Cornice Gable Window double hung, no glass, some fi			
Dating Method(s): Estimate			
Feature Preservation Recommendation(s) (Check all that apply):			

-Contributes to a potential district
- ____No nomination potential
- _____Potential district---feature would be a contributing element if other properties constitute a district
- _____Thematic nomination potential
- ____Component of a historic site or landscape
 - Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context _with neighboring structures; d) relocation has damaged eligibility
- Historical associations require further investigation

Recorded By	Kathy Wilner	Date Recorded	2/16/2018
-	(First Name & Last Name)		(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM

PAGE 3—Feature Data

Field Code Lind Township Hall

SITS# 32 GF

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school, also know as Sunny Side School, sitting on a concrete foundation. The gable roof of the building is covered with wood shakes with metal capping and finials. There is a cement block chimney at the peak near the east end of the school. There are also vent pipes on the soutyh slope that might indicate bathrooms. The soffits are closed.

A wide trim board begins the siding on the east and west walls under the peak of the roof. The remainder of the siding is 6 inch wood lap with 4 inch wood corner trim. Little paint remains. There is an entry door reached from a two step concrete porch. The door is 5 panel wood with a transom above it. Openings would indicate the presence of glass at some point in the past. There are 3 double hung windows on both the south and north sides. The windows have framing on the top half and none on the bottom, all glass is gone. There are decorative headers above all the windows on the outside. Near the east end of the school on the south wall there are two small windows that have stove pipes out the roof above them that could indicate bathrooms. My source did not go into the school to see what is just inside the entry door but I am thinking to the right would have been a coat room. The interior walls and ceiling of the school are covered with beadboard. A trim board runs along the walls at the level that wainscot might be. Between the windows on the north wall there are small blackboards and another larger blackboard runs along the entire west wall. There is a corner cupboard in the northwest corner of the school room, built out of beadboard. The floor is narrow tongue and groove hardwood. Exterior wiring on the west wall is indicative of electricity. A wood stove remains in the school and sits at the east end of the school room. This school closed in 1957.

Just north of the school is a small wood building that was used for either a barn or fuel storage. There are some old desks inside the school along with a couple wood tables.

Recorded By_

Kathy Wilner

Date Recorded 2/16/2018

(First Name & Last Name)

(mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code

SITS# 32 GF

Complete one Page 4 for the entire site.

2. Owner's Contact Information: Lind Township Board Brian Jodock Chairperson 228 39th St NE Northwood ND 58267

3. Access (to rural areas):

Go 4 miles east of Northwood ND on 4th Ave NE, at 39th St NE turn left and travel 2 miles south to see the school at the southeast corner of the intersection.

4. Site Area (ft²):_____

5. Description of SETTING:

There is farm land in all directions with a large farm to the north and another farm sigte southwest. There are trees along the north and east sides of the school yard. A smaller wood building sits just to the north.

Recorded By	Kathy Wilner	Date Recorded	2/16/2018
	(First Name & Last Name)		(mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Lind Township Hall


SITS# 32^{GF}_____

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Photo's were shared by Stacy Brekke, Rural Route 2 Photography.

Recorded By	Kathy	Wilner	Date Recorded	2/16/2018
-	(First Name & Last Name)			(mm/dd/year)




East Side

Lind Township School

09/30/2017 Kathy Wilner (photos Stacy Brekke) GF

Martin.


South Side (SW corner)



North Side

Lind Township School 09/30/2017 Kathy Wilner (photos Stacy Brekke) GF

West Side



bing maps	
Notes	
Lind Township School	
2/6/2018	
Kathy Wilner	

GF

