NDCRS ARCHITECTURAL SITE FORM

Eight Conta [Lind School #99	PAGE 1
Field Code	SITS# 32 GF 38/2
SITE IDENTIFICATION Map Quad Northwood NW	Site Name Lind School #99
Map Quad	_ Site Name
LTL _TWP 149 R 55 SEC LTL _TWP _ R SEC LTL _TWP _TWP _ R SEC LTL _TWP _TWP _TWP _TWP _TWP _TWP _TWP _TWP	33 QQQ 8 QQ 7 Q 8 QQ Q Q Q Q Q Q Q Q Q Q Q
Street Number: 78	5 = NE1/4
Street Name: 41st St NE	6 = SE¼ 7 = SW¼ 8 = NW¼
Urban Legal Description:	8 = NVV24
SITE DATA	
Total # Architectural Features: 1	
Fieldwork Date: 7/18/2018	
Reconnaissance Survey Intens	ive Survey
Project & Principal Investigator: Country Schoolhouse Project	
Report Title & Author(s):	
Contracting firm or Agency completing the form	n:
Additional Information:	
SHSND USE Area of Significance Ecozone	Verified Site <u>L</u> CR Type <u>2</u>
Baserded By Kathy Wilner	Data Recorded 1/20/2019
(First Name & Last Name)	Date Recorded (mm/dd/year)

(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code Lind School #99		SITS# 32 GF
Complete one Page 2 for e	each architectural feature at	the site.
rchitectural Feature # 1		
Construction Date 1891	Feature Type X 9	Condition 7
eature Date 2	Context 7	Plan Shape 5
structural System 25	Primary Exterior 26	Style Other Style
Original Owner's Ethnicity	Secondary Exterior N/A	Architect/Builder
Other Information:	sacrate in the	
oundation Poured concrete and	concrete blocks	Stories 1
oof/Comice Gable		
Jindow Double hung, multipane v	with glass	
eating Method(s): School records		
Individual nomination	mendation(s) (Check all that a	.pp.y/.
No nomination potential		
Will not contribute to a dis	strict	
Potential district—feature	would be a contributing element if	other properties constitute a district
Thematic nomination pote	ential	
Component of a historic s	site or landscape	
recreates original site, ori	able choices)—a) relocation occurre entation, landscape, & spatial relati es; d) relocation has damaged eligil	ionships; c) compatible in context
Historical associations rec	quire further investigation	
Recorded By Kathy Wilner	Da	te Recorded 1/20/2019

Instructions to complete a digital version of this form: (1) Download a copy; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately, and save; (5) **Print** and submit to SHSND.

(First Name & Last Name)

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Lind School #99	PAGE 5—Feature Data	SITS# 32 GF	

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room school on a foundation of poured concrete and concrete blocks. The school was moved to this location in 1960, two years after the school closed in 1958. The roof is covered with metal sheeting and the chimney is gone. The soffits are closed. The building measures 18 feet south to north and 30 feet east to west.

A wide trim board runs under the eaves on all sides of the school. The remainder of the siding is 6 inch wood lap with metal corner trim. The school has 6, four pane, double hung windows on the south wall, all glass intact. On the east wall there are two smaller double hung windows to the left of the 5 panel wood entry door. These windows are for the bathrooms. One more double hung window is to the right of the door. Again, all glass intact. There is a wood platform porch that leads to the entry door. Stepping into the school there is a coatroom to the immediate right and bathrooms are to the left. The walls in the entry are covered with fiberboard and coat hooks are on the west wall of the entry. A 5 panel wood door leads from the entry into the boys toilet, the girls toilet access door is in the school room proper. Another 4 panel wood door leads into the school room. The walls in the main room of the school are also covered with celotex board panels. The lower 1/3 of the wall covered with plywood and painted a different color to act as wainscot. The ceiling is finished with celotex board, tile look. There are two hanging lights with large white globes indicating electricity present. Blackboards are either side of the wood burning stove at the west end of the room. The floors are tongue and groove hardwood.

The school is furnished with maps, desks, teachers desk, a flag on the wall, picture of George Washington, some school memorabilia and more. The original cost of the building was \$248.36 and the land, 2 acres, was bought from Helga Herlickson fpr \$10. The first year furnishings cast \$50.15. School restoration was completed in 1967 and over 1000 folks have visited and signed the guest book.

Recorded By Kathy Wilner	Kathy Wilner	Date Recorded	1/20/2019
Recorded By	(First Name & Last Name)	Date Recorded	(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Lind School #99	SITS# 32GF
Complete one Page 4 for the entire site.	
2. Owner's Contact Information: David Maurseth 78 41st St NE Northwood ND 58267	
 Access (to rural areas): From Northwood ND, drive west 6 miles on Highway 15 t miles to the farm on the east side of the road. 	to 41st St NE. Turn left and go south 4 1/4
4. Site Area (ft²):	
 Description of SETTING: The school is sitting in a farm yard. There are trees to the to the east and farm fields all directions. The land is rolling east of the farm. 	교통이 하지도 있습니다. 아이들에 들어 얼굴하다는 사람들이 되는데 그래요? 그리는 그리는데 그리는데 그리는데 그리는데 그리는데 그리는데 그리는데
Recorded By Kathy Wilner	Date Recorded 1/20/2019
(First Name & Last Name)	(mm/dd/year)

(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

PAGE 5—SITE	DESCRIPTION
ield Code Lind School #99	SITS# 32 GF
Summary of ALL Site Features & Evalua	ation of Significance:
References/Comments: Kathy Wilner	
366 43rd Ave SE Bowdon ND 58418	
ecorded By Kathy Wilner	Date Recorded 1/20/2019

(First Name & Last Name)



South Side

Lind School #99

7/18/2018

Kathy Wilner

GF

West Side





East Side


Lind Township #99

7/18/2018

Kathy Wilner

GF

North Side



1/9/2019 Google Maps



Lind School #99

7/18/18

Kathy Wilner

GF



Imagery ©2019 Google, Map data ©2019 Google 1000 ft