NDCRS ARCHITECTURAL SITE FORM					
Field Code Kempton School	PAGE 1	SITS# 32 GF 3	813		
SITE IDENTIFICATION			210		
Map Quad Kempton	Site Name Kemp				
Map Quad	Site Name				
LTLTWP R SEC.	7 QQQ 6 QQQ QQQ QQQ				
NAD 1983, UTM 5296892 N NAD 1983, UTM 603633 E	ZONE 14N		Subsection: $1 = N\frac{1}{2}$		
City: Kempton			$2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$		
Street Number:			4 = W ¹ / ₂ 5 = NE ¹ / ₄		
Street Name: 10th Ave NE			6 = SE¼ 7 = SW¼ 8 = NW¼		
Urban Legal Description:			0 - 1999/4		
SITE DATA					
Total # <u>Architectural</u> Features: 1					
Fieldwork Date:					
Reconnaissance Survey Intens	sive Survey				
Project & Principal Investigator:					
Report Title & Author(s):					
Contracting firm or Agency completing the forn	1				
Additional Information:					
SHSND USE Area of Significance Area of Significance Area of Significance Area of Significance Ecozone Area of Significance Ecozone Area of Significance Ecozone	e Verified S	ite _L CR Typ	be <u>2</u>		
Recorded By Kathy Wilner		Date Recorded 7/4/2	2019		
(First Name & Last Name)			(mm/dd/year)		

NDCRS ARCHITECTURAL SITE FORM				
	GE 2—Feature Data			
Field Code Kempton School		SITS# 32 ^{GF}		
Complete one Page 2 for each	<u>architectural feature</u> at th	e site.		
Architectural Feature # 1				
Construction Date	Feature Type 9	Condition 5		
Feature Date 2	Context 7	Plan Shape		
Structural System 25	Primary Exterior 26	Style Other Style		
Original Owner's Ethnicity	Secondary Exterior N/A	Architect/Builder		
Other Information:				
Foundation		Stories 1		
Roof/Cornice Hip roof				
Window Double hung, some glass				
Dating Method(s):				

Feature Preservation Recommendation(s) (Check all that apply):

- ____Individual nomination
- ____Contributes to a potential district
- ____No nomination potential
- Will not contribute to a district
- ____ Potential district—feature would be a contributing element if other properties constitute a district
- _____ Thematic nomination potential

____Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context __with neighboring structures; d) relocation has damaged eligibility

_____Historical associations require further investigation

Recorded By	Kathy Wilner	Date Recorded	7/4/2019
	(First Name & Last Name)		(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM

PAGE 3—Feature Data

Field Code Kempton School

SITS# 32 GF

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

This feature is a one room prairie school moved to this location for other uses. Used as a TV repair shop in later years.. It sits on a basement of concrete block. The hip roof is covered with wood shakes and metal finials at the hips. A shed entry at the north side of the school has a sloping shed roof, also covered with shakes. A cement block chimney is located on the outside of the norh wall. There is a trinangular, gable roofed dormer on the south slope of the roof. This is also covered with shakes and a belfry is located on top. The belfry is roofed with wood shakes and has metal capping on the ribs. The belfry has rounded upenings with picket fence trim all four sides and there is a flag pole at the peak. The interior of the dorner is finished with shakes and the soffits are closed. Soffits on the school are also closed.

A rake board runs under the eaves on all four sides of the school. At the bottom of the siding is waterboard with a wide trim board at the bottom. The remainder of the siding is 6 inch wood lap siding with 4 inch wood corner trim. There are glass block windows in the basement walls on both the west and east sides. The south side has a garage door installed for access to the interior. The ground slopes up to the floor of the school. A metal railing is still attached to the wall on the west side of the door, likely used for access for school. The outline of the entry is visible around and above the garage door. There is a small fixed pane window on the south wall to the west of the garage door, the other window was covered with siding. On both the east and west walls near the south end of the building are two more small fixed pane windows. On the east wall there is a bank of 5 large, double hung windows with some glass. It looks like an effort was made to cover some of the windows as they broke. There are blackboards and no wainscot. The floor couldn't be seen for the junk inside the building. Electricity is present.

Recorded By Kathy Wilne (First Name & L	Kathy Wilner	Date Recorded 7/4/2019	
	(First Name & Last Name)	(mm/dd/year)	

NDCRS ARCHITECTURAL SITE FORM PAGE 4---SITE DESCRIPTION

Field Code Kempton School

SITS# 32GF

Complete one Page 4 for the entire site.

2. Owner's Contact Information: Steve and Angela Rosenthal 15870 25R ST. SE Amenia ND 58004

3. Access (to rural areas):

Kemptom is located east of Highway 18. It is 1/2 mile east on Co Rd 6 or 10th Ave NE. The school will be on your left as you travel east. Kempton is south of Larimore.

4. Site Area (ft²): _____

5. Description of SETTING: The building was moved to this location and was used as a TV Repair shop in later years. The school sits at the southwest corner of the villiage of Kempton so there are houses to the northeast and east. Farm fields all other directions.

Recorded By	Kathy Wilner	Date Recorded
	(First Name & Last Name)	(mm/dd/year)

NDCRS	ARC	HITEC	TURAL	SITE	FORM
PAG	GE 5-	-SITE	DESCR	RIPTIC)N

Field Code Kempton School


SITS# 32 GF

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments:
Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Credit goes to Stacy Brekke, RuralRoute2 Photography, for pictures and school information.

Recorded By Kathy Wiln	Kathy Wilner	Date Recorded	//4/2019
	(First Name & Last Name)		(mm/dd/year)



(Photo credit Stacy Brekke – RuralRoute2 Photography)



West Side



East Side

Kempton School

5/31/2019

Kathy Wilner

GF

(Photo credit Stacy Brekke – RuralRoute2 Photography)



South Side



Imagery ©2019 Google, Map data ©2019 200 ft Feature