

NDCRS ARCHITECTURAL SITE FORM

PAGE 1

SITS# 32 MH X 323

SITE IDENTIFICATION

Field Code MAC-UP-43x Site Name _____
Site Name _____

Map Quad Bantry NW
Map Quad _____

LTL ___ TWP 157 R 78 SEC 4 QQQ 6 QQ 7 Q 6
LTL ___ TWP _____ R _____ SEC _____ QQQ _____ QQ _____ Q _____
LTL ___ TWP _____ R _____ SEC _____ QQQ _____ QQ _____ Q _____
LTL ___ TWP _____ R _____ SEC _____ QQQ _____ QQ _____ Q _____

UTM 5367147 N ZONE 14N
UTM 371343 E NAD 1927 ___ NAD 1983

Subsection:
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

City: _____
Street Number: _____
Street Name: _____
Urban Legal Description: _____

SITE DATA

Total # **Architectural** Features: 5

Fieldwork Date: 8/6/2014

Reconnaissance Survey Intensive Survey ___

Project Title & Supervisor:

Project Title: SRT- Upham
Supervisor: Daniel Salas

Report Title & Author(s):

Report Title: SRT Communications' Upham FTTP Exchange: A Class II and Class III Cultural Resource Inventory in Bottineau and McHenry Counties, North Dakota Author: Amie Meade

Additional Information: Site lead: Windmill, three sheds, and a garage

SHSND USE

Area of Significance 2 Ecozone 20 Verified Site 1 CR Type 1
Area of Significance _____ Ecozone _____ Non-Site _____
Area of Significance _____

Recorded By C. Mog and C. Carlson Date Recorded 8/6/2014
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM
PAGE 2—Feature Data

Field Code MAC-UP-43x

SITS# 32 MH

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 3

Construction Date

Feature Type 9

Condition 5

Feature Date 5

Context 13

Plan Shape 5

Structural System 25

Primary Exterior 26

Style Utilitarian

Original Owner's Ethnicity

Secondary Exterior

Architect/Builder

Other Information: Schoolhouse converted to storage building

Foundation None; sitting on lumber Stories 1

Roof/Cornice Front-gabled; wood shake shingles

Window Original openings intact; some glass missing

Dating Method(s): Professional estimate

Feature Preservation Recommendation(s) (Check all that apply):

- Individual nomination
Contributes to a potential district
No nomination potential
Will not contribute to a district
Potential district—feature would be a contributing element if other properties constitute a district
Thematic nomination potential
Component of a historic site or landscape
Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility
Historical associations require further investigation

Recorded By C. Mog and C. Carlson (First Name & Last Name)

Date Recorded 8/6/2014 (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM
PAGE 3—Feature DataField Code MAC-UP-43xSITS# 32 MH**1. Feature Description, Integrity, Eligibility:**

DESCRIPTION: Feature 3 is a one-room schoolhouse that was moved from its original location and converted into a shed. The shed is sitting atop pieces of lumber, and has no actual foundation. The structure is front-gabled, and has a front-gabled entryway/mudroom attached to the north facade. Both the entryway and the main structure are sided in horizontal wood clapboards. The roof is clad in wood shingles. A small shed-roofed addition was placed on the west side, most likely after the structure was moved to its current location. This addition has corrugated steel roofing material, and a large wooden sliding door. The shed has horizontal wood clapboard siding, painted white. The primary entrance to this feature is a standard wood door located on the north facade. There are two double-hung windows, with original wood frames (painted white) and glass intact, on either side of this door. There are three two-over-two-light windows on the east facade, though the bottom two lights of each are boarded up. The remnants of a brick chimney are located on the south end of the roof.

INTEGRITY: Feature 3 is in fair condition. Integrity of location and setting are lost, due to the fact that the structure has been moved, and then converted into a shed. Integrity of materials has been impacted by the loss of glass in several windows, as well as the destruction of most of the chimney. Integrity of design has been reduced by the addition on the west side. Integrity of feeling is profoundly impacted by not only the conversion and relocation of the structure, but by its current general state of deterioration. Only integrity of workmanship is retained.

ELIGIBILITY: Feature 3 has not been evaluated for eligibility to the NRHP. Current survey data are not sufficient to determine significance. Until a deed search can be performed, avoidance is recommended.

Recorded By C. Mog and C. Carlson
(First Name & Last Name)Date Recorded 8/6/2014
(mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM
PAGE 4—SITE DESCRIPTION**Field Code MAC-UP-43xSITS# 32 MH**Complete one Page 4 for the entire site.**

2. Owner's Contact Information:

Private

3. Access (to rural areas):

From Upham, North Dakota, travel north on C Ave S toward Main St. Take the first right onto Main St, and follow for 0.1 miles. Take a slight right onto ND-14 S, and drive for 0.9 miles. Turn right on 6th Ave N, and follow for 6.9 miles. Turn right on 73rd St N, and take for 1.0 mile. Turn left onto 7th Ave N, and follow for 2 miles. Turn right onto 71st St N, follow for 0.3 miles, then turn right. Site lead is on the right.

4. Site Area (ft²): 28,9935. Description of **SETTING**:

The site lead is located north of a gravel road, on an abandoned ranch. The site lead is overgrown with a variety of forbs, shrubs, and trees. Miscellaneous farm machinery and old vehicles are found throughout the site lead. There are several associated outbuildings near the site lead, including some modern grain bins, but as they lie outside the area of potential effect, they were not recorded at the time of inventory.

Recorded By C. Mog and C. Carlson Date Recorded 8/6/2014
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

**NDCRS ARCHITECTURAL SITE FORM
PAGE 5—SITE DESCRIPTION**Field Code MAC-UP-43xSITS# 32 MH**6. Summary of ALL Site Features & Evaluation of Significance:**

Site lead MAC-UP-43x consists of five features on an abandoned ranch/farmstead. Feature 1 is a windmill with a metal frame, which is no longer in use. Feature 1 is in fair condition. Integrity of design and materials has been reduced by the removal of the pump and the missing motor blades. Integrity of feeling is slightly impacted by the deterioration of the structure, which is clearly no longer in use. Feature 2 is a large modular shed/barn, made entirely of corrugated steel. Feature 2 is in good condition and retains all aspects of its integrity. Feature 3 is a one-room schoolhouse that was moved from its original location and converted into a shed. Feature 3 is in fair condition and only integrity of workmanship is retained. Feature 4 is a small garage with a shed-roofed addition. Feature 4 is in fair condition, and retains integrity of location, setting, workmanship, and feeling. Feature 5 is a small shed. Feature 5 is in fair condition, and retains integrity of location, setting, workmanship, and feeling.

The site lead has not been evaluated for eligibility to the NRHP. Current survey data are not sufficient to determine significance. Until a deed search can be performed, avoidance is recommended.

7. References/Comments:

Recorded By C. Mog and C. Carlson Date Recorded 8/6/2014
(First Name & Last Name) (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

**NDCRS SITE FORM
ATTACHMENTS SECTION**

Field Code MAC-UP-43x

SITS# 32MH



Figure 6: View of MAC-UP-43x, to the southeast, Feature 2 (Image 0892).



Figure 7: View of MAC-UP-43x, to the southwest, Feature 3 (Image 0909).

**NDCRS SITE FORM
ATTACHMENTS SECTION**

Field Code MAC-UP-43x

SITS# 32MH



Figure 8: View of MAC-UP-43x, to the northeast, Feature 3 (Image 0915).



Figure 9: View of MAC-UP-43x, to the northwest, Feature 4 (Image 0930).

Recorded By C. Mog and C. Carlson

Date Recorded 8/6/2014