SITE IDENTIFICATION

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 1

SITS# 32 ML

L 1260

Field Code <u>Malcolm Township School</u> Map Quad <u>L-aKe NeHie</u> Map Quad	Site Name <u>Malcolm Township School</u> Site Name
LTLTWPRR SEC LTLTWPR SEC LTLTWPR SEC	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$
UTMN UTME	ZONE NAD 1983 Subsection: NAD 1927 NAD 1983 1 = N ¹ / ₂
City: Coleharbor ND 58531	$2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$
Street Number: Between 25 Ave NW and 26th	Ave NW $4 = W\frac{1}{2}$ $5 = NE\frac{1}{4}$
Street Name: 14th St NW	6 = SE ¹ / ₄ 7 = SW ¹ / ₄
Urban Legal Description:	8 = NW1⁄4
SITE DATA	
Total # Architectural Features: 1	
Fieldwork Date: 9/26/2012	
Reconnaissance Survey 🖌 Intens	ive Survey
Project Title & Supervisor:	
Country Schoolhouse Project	
Report Title & Author(s):	
Additional Information:	
SHSND USE Area of Significance Area of Significance Area of Significance Area of Significance	Verified Site CR Type Non-Site
Recorded By Kathy Wilne (First Name & Last Name)	Date Recorded 2/21/2012

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data					
Field Code Malcolm Township School	ol	SITS# 32_ML			
Complete one Page 2 for each architectural feature at the site.					
Architectural Feature #1					
Construction Date	Feature Type <u>9</u>	Condition 6			
Feature Date 4	Context 7	Plan Shape <u>5</u>			
Structural System 25	Primary Exterior <u>26</u>	Style Hipped Roof Box			
Original Owner's Ethnicity	Secondary Exterior	Architect/Builder			
Other Information:					
Foundation Concrete		_ Stories1			
Roof/Cornice Hip roof					
Window Double Hung on the south and	large, several paned, fixed wind	dows on the east.			
Dating Method(s): estimate					
Feature Preservation Recommend	dation(s) (Check all that ap	oly):			
Individual nomination					
Contributes to a potential distric	ct				
No nomination potential					
Will not contribute to a district					
Potential district—feature would be a contributing element if other properties constitute a district					
Thematic nomination potential					
Component of a historic site or landscape					
Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in contextwith neighboring structures; d) relocation has damaged eligibility					
Historical associations require further investigation					

Recorded By	Kathy Wilner	Date Recorded	2/21/2012	
	(First Name & Last Name)		(mm/dd/year)	

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Malcolm Township School

SITS# 32 ML

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

This is a wood framed school building with 6 inch horizontal wood lap siding. The south side of the school shows some indication of change. There are only two windows and I think one of more was moved and/or covered up. All the corners are finished with metal outside corner molding. There are areas where the siding lines up to indicate change in the siding or repair. The west and north sides have no windows or any indication of openings. The entry is on the east side and there is a concrete step leading up to the door. The door might be original or at least quite old with a large transom window above it. Either side of the door are tall, fixed windows with grids installed. The building sits on a concrete foundation and I did not see any indication of a basement. There is electricity evidenced by the light above the door and conduit on the outside of the building on the east. There are asphalt shinges on the roof and the chimney looks to be of newer brick.

Inside the entry there doors to either side and when I opened the door to the left there was a set of stairs, hence the wonder of the basement. The door to the right took me to voting booths and the space was fairly large and I suspect this space was the coat room. The voting booths are separated by beadboard walls and they were open above 6 feet. You can get into the main room from the entry by going either to the right or the left. Inside the school room the wall between the doors has the chimney in it as well as two small built-in bookcases. There is beadboard wainscoating around the entire room. The remainder of the walls are wallboard with seams covered by a narrow strip of lath. All painted light green. There are blackboards on the west and north walls. A fuel oil furnace sits along the north wall just inside the main room from the old coat room area. There is chimney pipe going to the chimney located between the two built in bookcases. The pipe is help up with wire attached to the ceiling. There are 4 hanging lights with large white globes. The floor is tongue and groove.

This school measures 20 feet north and south by 34 feet east and west. The last school reports submitted from Malcolm Township were in 1959.

Recorded By	Kathy Wilner	Date Recorded	2/21/2012
	(First Name & Last Name)		(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Malcolm Township School

SITS# 32 ML

Complete one Page 4 for the entire site.

2. Owner's Contact Information: Larry & Tammy Evenson 1323A 26th Ave NW

3. Access (to rural areas):

Coleharbor ND 58531

4. Site Area (ft²): _____

5. Description of SETTING:

There are farm sites in the distance to the northeast, north and west. Open farm land to the south.

Recorded By

Kathy Wilner (First Name & Last Name) Date Recorded

2/21/2012 (mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Malcolm Township School

SITS# 32_ML_____

6. *Summary of ALL* Site Features & Evaluation of Significance:


7. References/Comments:

Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By____

Kathy Wilner (First Name & Last Name) Date Recorded

2/21/2012 (mm/dd/year)



Malcolm Twsp. School



Malcolm Twsp. School 9/26/2011 East Side Kathy Wilner ML





Malcolm Twsp. School 9/26/2011 North Side Kathy Wilner ML

