

NDCRS SITE FORM
 ARCHITECTURAL SITES
 page 1

SITS # 32 MN 1633

Field Code B.R.W.U.S.2.S.O.2.4 Site Name F.L.I.C.K.E.R.T.A.I.L.V.I.L.L.A.G.E.
 Field Code _____ Site Name _____

Map Quad STANLEY
 Map Quad _____

- 1. N½
- 2. E½
- 3. S½
- 4. W½
- 5. NE¼
- 6. SE¼
- 7. SW¼
- 8. NW¼
- 9. C

LTL Twp 156 R 91 Sec 28 QQQ 6 QQ 7 QQ 5
 LTL Twp _____ R _____ Sec _____ QQQ 7 QQ 7 QQ 5
 LTL Twp _____ R _____ Sec _____ QQQ 5 QQ 7 QQ 5
 LTL Twp _____ R _____ Sec _____ QQQ _____ QQ _____ QQ _____
 LTL Twp _____ R _____ Sec _____ QQQ _____ QQ _____ QQ _____
 LTL Twp _____ R _____ Sec _____ QQQ _____ QQ _____ QQ _____

City STANLEY

Street # _____

Street # _____

Street Name _____

Street Name _____

of Features 29

1 Feature # 59 Feature Type 6 Condition
 _____ Construction Date 25 Context *
3 Feature Date 5 Plan Shape *
25 Structural System ** 26 Primary Exterior * _____ Secondary Exterior
10 Ethnic 20 Style
101021001 Fieldwork Date 0 Architect/Builder
 _____ Other Information

_____ Soil Association 21 Ecozone 2 Area Signf _____ MS Number
 _____ Soil Association _____ Ecozone _____ Area Signf _____ MS Number
 CR Type Verified Site Non-Site E C F T F
 State Registry National Register

Coder B. Mitchell

Date Coded 01/31/2001


Reconnaissance Survey _____

Intensive Survey X

Manuscript/Report Title: US Hwy 2 Cultural Resource Inventory in Ward, Mountrail, & Williams Counties

Author(s): Bradley E. Perkl and Barbara A. Mitchell, et al.


Photocopy the portion of the 7.5' U.S.G.S. topographic quadrangle that shows the location of the site and surrounding area. Mark the boundaries of the site on the photocopy. Photocopy the portion of the topographic quadrangle must be actual size; reductions or enlargements are unacceptable.



STANLEY, N. DAK (1969 (PR 1981))
T156N, R91W, Section 28

Key

- | | | |
|--------------------------------------|-------------------------------|---|
| 1. Ross Depot | 11. Solberg House | 21. Windmill #1 |
| 2. House (Bank) | 12. Outhouse #1 | 22. Windmill #2 |
| 3. Community Building (Jail) | 13. Country School #3 | 23. Lutheran Church Replica |
| 4. Ross House (Doctor's Office) | 14. Blaisdell Catholic Church | 24. Homestead Shanty |
| 5. Blacksmith Shop | 15. Cook Car | 25. Pole Building #1 |
| 6. Country School #1 (General Store) | 16. Stanley House | 26. Pole Building #2 |
| 7. Country School #2 (Saloon) | 17. Lee House | 27. Gazebo |
| 8. Shed | 18. Barn | 28. Burlington Northern
caboose and boxcar |
| 9. Van Hook House (Style Shoppe) | 19. Chicken Coop | 29. School Wagon |
| 10. Olson House (Doll Cottage) | 20. Outhouse #2 | |



NDCRS ARCHITECTURAL SITE FORM

page 2

Field Code BRW US2 S024

SITS # 32MN

<u>6</u> Feature #	<u>9</u> Feature Type	<u>5</u> Condition
Construction Date	<u>7</u> Context *	
<u>3</u> Feature Date		<u>5</u> Plan Shape *
<u>25</u> Structural System **	<u>26</u> Primary Exterior *	<u>28</u> Secondary Exterior
<u>0</u> Ethnic	<u>14</u> Style	
<u>1100200</u> Fieldwork Date		Architect/Builder
		Other Information

FOUNDATION TYPE	STORIES	ROOF TYPE/CORNICE
<u>Concrete block</u>	<u>1</u>	<u>Front gable; composition shingles</u>

WINDOW CONDITION	DATING METHOD
<u>Original windows replaced/openings altered</u>	<u>Professional estimate</u>

PRESERVATION RECOMMENDATION (check all that apply):

- 1) Individual Nomination
- 2) Contributes to a potential district
- 3) No nomination potential
- 4) Will not contribute to a district
- 5) Potential district not known at this time: feature would be a contributing element if neighboring properties constitute a district
- 6) Thematic nomination potential
- 7) Component of historic site/landscape

- 8) Feature has an important physical, spatial, functional, historic or architectural relationship to the site/complex/farmstead
- 9) Moved: A) relocation occurred within historic period. B) recreates original site, orientation, landscape and spatial relationships. C) compatible in context with neighboring structures. D) relocation has damaged eligibility.
- 10) Request comparative study of neighboring properties
- 11) Historical associations require further investigation

DESCRIPTION/INTEGRITY/ELIGIBILITY Feature #6 is a rural schoolhouse that has been moved into Flickertail Village and currently serves as the "general store." The one-story building is rectangular in plan and is located along the "Main Street" of Flickertail Village. The wood-frame structure has a concrete block foundation and is primarily clad with horizontal wood siding with corner boards. The cladding is not original. A portion of what now serves as a "storefront" has vertical board-and-batten cladding. The front-gable roof is clad with composition shingles. There are two large, divided-light windows on the "storefront." The rest of the windows have been filled in. There is a wood platform on the front of the building that connects it to Feature #7. On the rear of the building there is a slightly shorter gable-roofed addition. The building has been severely altered to be interpreted as a general store, including the in-filling of windows, the introduction of a "storefront," the replacement of the wall cladding, and the addition to the rear.

The building retains little integrity. Furthermore, its removal from its original location has damaged its eligibility. The building does not meet any of the considerations under Criteria Consideration B.

Urban Legal Description _____

SEE CONTINUATION SHEET

NDCRS ARCHITECTURAL SITE FORM

page 2

Field Code BRW US2 S024

SITS # 32MN

<u>7</u> Feature #	<u>9</u> Feature Type	<u>5</u> Condition
Construction Date	<u>7</u> Context *	
<u>3</u> Feature Date		<u>5</u> Plan Shape *
<u>2.5</u> Structural System **	<u>2.6</u> Primary Exterior *	Secondary Exterior
<u>0</u> Ethnic	<u>1.4</u> Style	
<u>1.003.00</u> Fieldwork Date		Architect/Builder
		Other Information

FOUNDATION TYPE	STORIES	ROOF TYPE/CORNICE
<u>Concrete block</u>	<u>1</u>	<u>Front gable; corrugated metal</u>

WINDOW CONDITION	DATING METHOD
<u>Original windows replaced/openings altered</u>	<u>Professional estimate</u>

PRESERVATION RECOMMENDATION (check all that apply):

- 1) Individual Nomination
- 2) Contributes to a potential district
- 3) No nomination potential
- 4) Will not contribute to a district
- 5) Potential district not known at this time: feature would be a contributing element if neighboring properties constitute a district
- 6) Thematic nomination potential
- 7) Component of historic site/landscape

- 8) Feature has an important physical, spatial, functional, historic or architectural relationship to the site/complex/farmstead
- 9) Moved: A) relocation occurred within historic period. B) recreates original site, orientation, landscape and spatial relationships. C) compatible in context with neighboring structures. D) relocation has damaged eligibility.
- 10) Request comparative study of neighboring properties
- 11) Historical associations require further investigation

DESCRIPTION/INTEGRITY/ELIGIBILITY Feature #7 is a rural schoolhouse that has been moved into Flickertail Village and currently serves as the "saloon." The one-story building is rectangular in plan and is located along the "Main Street" of Flickertail Village. The wood-frame structure has a concrete block foundation and is clad with horizontal wood siding with corner boards. The cladding is not original. The front-gable roof is clad with corrugated metal. The windows are primarily wood-framed two-over-two-vertical double-hung. Several of the windows have been filled in. There is a wood platform on the front of the building that connects it to Feature #6. The building has been severely altered to be interpreted as a saloon, including the in-filling of windows and the replacement of the wall cladding.

The building retains little integrity. Furthermore, its removal from its original location has damaged its eligibility. The building does not meet any of the considerations under Criteria Consideration B.

Urban Legal Description _____

SEE CONTINUATION SHEET

NDCRS ARCHITECTURAL SITE FORM

page 2

Field Code BRW US2 S024

SITS # 32MN

<u>13</u> Feature #	<u>9</u> Feature Type	<u>5</u> Condition
<u> </u> Construction Date	<u>7</u> Context *	
<u>3</u> Feature Date		<u>5</u> Plan Shape *
<u>25</u> Structural System **	<u>26</u> Primary Exterior *	<u> </u> Secondary Exterior
<u>0</u> Ethnic	<u>14</u> Style	
<u>1100200</u> Fieldwork Date		<u> </u> Architect/Builder
		<u> </u> Other Information

FOUNDATION TYPE	STORIES	ROOF TYPE/CORNICE
<u>Concrete block</u>	<u>1</u>	<u>Side gable; wood shingles</u>

WINDOW CONDITION	DATING METHOD
<u>Most original windows replaced/openings altered</u>	<u>Professional estimate</u>

PRESERVATION RECOMMENDATION (check all that apply):

- 1) Individual Nomination 2) Contributes to a potential district
- 3) X No nomination potential 4) X Will not contribute to a district
- 5) Potential district not known at this time: feature would be a contributing element if neighboring properties constitute a district
- 6) Thematic nomination potential 7) Component of historic site/landscape

- 8) Feature has an important physical, spatial, functional, historic or architectural relationship to the site/complex/farmstead
- 9) D Moved: A) relocation occurred within historic period. B) recreates original site, orientation, landscape and spatial relationships. C) compatible in context with neighboring structures. D) relocation has damaged eligibility.
- 10) Request comparative study of neighboring properties
- 11) Historical associations require further investigation

DESCRIPTION/INTEGRITY/ELIGIBILITY Feature #13 is a rural schoolhouse from Cottonwood Township that has been moved into Flickertail Village. It is interpreted as a schoolhouse as part of the museum and is located at the end of the "Main Street." The one-story wood-frame building is rectangular in plan and has a concrete block foundation. The building is clad with horizontal wood siding with corner boards; the siding is not original. The side-gable roof is clad with wood shakes. The windows are primarily wood-framed double-hung, although all of the openings on the east facade have been filled in. The front one-third of the building appears to be an addition. It has a bell tower and a wood plaque that reads "Third Class Standard School". The school has been severely altered, including the in-filling of windows and the bell-tower addition; it is not known when the alterations took place.

The building retains little integrity. Furthermore, its removal from its original location has damaged its eligibility. The building does not meet any of the considerations under Criteria Consideration B.

Urban Legal Description
 SEE CONTINUATION SHEET

NDCRS ARCHITECTURAL SITE FORM

page 2

Field Code BRW US2 S024

SITS # 32MN

<u>14</u> Feature #	<u>5.3</u> Feature Type	<u>6</u> Condition
<u>19/14</u> Construction Date	<u>2.8</u> Context *	
<u>3</u> Feature Date		<u>5</u> Plan Shape *
<u>2.5</u> Structural System **	<u>2.6</u> Primary Exterior *	<input type="checkbox"/> Secondary Exterior
<u>0</u> Ethnic	<u>1.4</u> Style	
<u>1100200</u> Fieldwork Date		<input type="checkbox"/> Architect/Builder
		<input type="checkbox"/> Other Information

FOUNDATION TYPE <u>Poured concrete</u>	STORIES <u>1½</u>	ROOF TYPE/CORNICE <u>Front gable; composition shingles</u>
---	----------------------	---

WINDOW CONDITION <u>Most original windows/openings intact</u>	DATING METHOD <u>Museum pamphlet</u>
--	---

PRESERVATION RECOMMENDATION (check all that apply):

- 1) Individual Nomination
- 2) Contributes to a potential district
- 3) No nomination potential
- 4) Will not contribute to a district
- 5) Potential district not known at this time: feature would be a contributing element if neighboring properties constitute a district
- 6) Thematic nomination potential
- 7) Component of historic site/landscape
- *****
- 8) Feature has an important physical, spatial, functional, historic or architectural relationship to the site/complex/farmstead
- 9) Moved: A) relocation occurred within historic period. B) recreates original site, orientation, landscape and spatial relationships. C) compatible in context with neighboring structures. D) relocation has damaged eligibility.
- 10) Request comparative study of neighboring properties
- 11) Historical associations require further investigation

DESCRIPTION/INTEGRITY/ELIGIBILITY Feature #14 is St. Margaret's Catholic Church of Blaisdell. It was moved into Flickertail Village in 1991 and is interpreted as a church. It is located to the south of Feature #13 (the Schoolhouse). The story-and-a-half building is rectangular in plan and has a poured concrete foundation. The wood-frame structure is clad with horizontal wood siding with corner boards. The gable roof is clad with composition shingles and has a pyramidal-roofed bell tower. The windows are wood-framed gothic arches. There is a one-story addition to the rear of the building; it has a gable roof with an offset ridge.

Although the building retains some integrity, its removal from its original location has damaged its eligibility. The building does not meet any of the considerations under Criteria Consideration B.

Urban Legal Description _____

SEE CONTINUATION SHEET

NDCRS ARCHITECTURAL SITE FORM

page 2

Field Code BRW US2 S024

SITS # 32MN

<u>15</u> Feature #	<u>9.9</u> Feature Type	<u>5</u> Condition
_____ Construction Date	<u>2.5</u> Context *	
<u>3</u> Feature Date	<u>5</u> Primary Exterior *	<u>5</u> Plan Shape *
<u>2.5</u> Structural System **	<u>1</u> Secondary Exterior	
<u>0</u> Ethnic	<u>2</u> Style	
<u>110102100</u> Fieldwork Date		<u> </u> Architect/Builder
<u>COOK CAR</u>		<u> </u> Other Information

FOUNDATION TYPE	STORIES	ROOF TYPE/CORNICE
<u>None</u>	<u>1</u>	<u>Gable; material not visible</u>

WINDOW CONDITION	DATING METHOD
<u>Original windows/openings intact</u>	<u>Professional estimate</u>

PRESERVATION RECOMMENDATION (check all that apply):

- 1) Individual Nomination 2) Contributes to a potential district
- 3) X No nomination potential 4) Will not contribute to a district
- 5) Potential district not known at this time: feature would be a contributing element if neighboring properties constitute a district
- 6) Thematic nomination potential 7) Component of historic site/landscape
- *****
- 8) Feature has an important physical, spatial, functional, historic or architectural relationship to the site/complex/farmstead
- 9) Moved: A) relocation occurred within historic period. B) recreates original site, orientation, landscape and spatial relationships. C) compatible in context with neighboring structures. D) relocation has damaged eligibility.
- 10) Request comparative study of neighboring properties
- 11) Historical associations require further investigation

DESCRIPTION/INTEGRITY/ELIGIBILITY Feature #15 is a railroad car that has been moved into Flickertail Village and currently is interpreted as the "Cook Car." The object is of wood construction and has metal wheels. It has several wood-framed windows. The Cook Car is not likely to be found eligible for listing on the National Register of Historic Places.

Urban Legal Description _____
 SEE CONTINUATION SHEET

NDCRS ARCHITECTURAL SITE FORM

page 2

Field Code BRW US2 S024

SITS # 32MN

<u>16</u> Feature #	<u>40</u> Feature Type	<u>6</u> Condition
_____ Construction Date	<u>3.1</u> Context *	
<u>3</u> Feature Date		<u>5</u> Plan Shape *
<u>2.5</u> Structural System **	<u>2.2</u> Primary Exterior *	_____ Secondary Exterior
<u>0</u> Ethnic	<u>1.4</u> Style	
<u>1.010.200</u> Fieldwork Date		_____ Architect/Builder
		_____ Other Information

FOUNDATION TYPE	STORIES	ROOF TYPE/CORNICE
<u>Covered with stucco</u>	<u>1</u>	<u>Front gable; composition shingles</u>

WINDOW CONDITION	DATING METHOD
<u>Original windows replaced/openings altered</u>	<u>Professional estimate</u>

PRESERVATION RECOMMENDATION (check all that apply):

- 1) _____ Individual Nomination 2) _____ Contributes to a potential district
- 3) X No nomination potential 4) X Will not contribute to a district
- 5) _____ Potential district not known at this time: feature would be a contributing element if neighboring properties constitute a district
- 6) _____ Thematic nomination potential 7) _____ Component of historic site/landscape

- 8) _____ Feature has an important physical, spatial, functional, historic or architectural relationship to the site/complex/farmstead
- 9) D Moved: A) relocation occurred within historic period. B) recreates original site, orientation, landscape and spatial relationships. C) compatible in context with neighboring structures. D) relocation has damaged eligibility.
- 10) _____ Request comparative study of neighboring properties
- 11) _____ Historical associations require further investigation

DESCRIPTION/INTEGRITY/ELIGIBILITY Feature #16 is a dwelling from Stanley that has been moved into Flickertail Village and currently houses Girl Scout material donated to the museum by Gloria Nelson; it is called the "Little House". The one-story building is rectangular in plan and is located on the south side of the property. The frame structure and its foundation are covered with stucco. The front-gable roof is clad with composition shingles. The windows are primarily wood-framed, one-over-one double-hung. They are not original to the structure. There is a small one-story lean-to addition to the rear of the building. The house appears to have been severely altered, including the rear addition and the replacement and partial in-filling of windows.

The building retains little integrity. Furthermore, its removal from its original location has damaged its eligibility. The building does not meet any of the considerations under Criteria Consideration B.

Urban Legal Description _____

SEE CONTINUATION SHEET

NDCRS ARCHITECTURAL SITE FORM

page 2

Field Code BRW US2 S024

SITS # 32MN

<u>17</u> Feature #	<u>40</u> Feature Type	<u>5</u> Condition
_____ Construction Date	<u>30</u> Context *	
<u>3</u> Feature Date		<u>2</u> Plan Shape *
<u>25</u> Structural System **	<u>26</u> Primary Exterior *	_____ Secondary Exterior
<u>0</u> Ethnic	<u>14</u> Style	
<u>100200</u> Fieldwork Date		_____ Architect/Builder
		_____ Other Information

FOUNDATION TYPE	STORIES	ROOF TYPE/CORNICE
<u>Poured concrete</u>	<u>1½</u>	<u>Side gable; composition shingles</u>

WINDOW CONDITION	DATING METHOD
<u>Original windows replaced/openings altered</u>	<u>Professional estimate</u>

PRESERVATION RECOMMENDATION (check all that apply):

- 1) _____ Individual Nomination
- 2) _____ Contributes to a potential district
- 3) X No nomination potential
- 4) X Will not contribute to a district
- 5) _____ Potential district not known at this time: feature would be a contributing element if neighboring properties constitute a district
- 6) _____ Thematic nomination potential
- 7) _____ Component of historic site/landscape
- *****
- 8) _____ Feature has an important physical, spatial, functional, historic or architectural relationship to the site/complex/farmstead
- 9) D Moved: A) relocation occurred within historic period. B) recreates original site, orientation, landscape and spatial relationships. C) compatible in context with neighboring structures. D) relocation has damaged eligibility.
- 10) _____ Request comparative study of neighboring properties
- 11) _____ Historical associations require further investigation

DESCRIPTION/INTEGRITY/ELIGIBILITY Feature #17 is a dwelling from rural White Earth that has been moved into Flickertail Village. It once belonged to the Lee family. The story-and-a-half dwelling has an irregular plan and is located on the south side of the property. The frame structure has a poured concrete and concrete block foundation and is clad with horizontal wood siding with corner boards. The side-gable roof is clad with composition shingles. The windows are primarily wood-framed double-hung, although several have been replaced. There is a large, one-story addition projecting from the front of the house and a one-story lean-to addition to the rear. The house has been severely altered, including the replacement and in-filling of windows, the replacement of cladding, and the two additions.

The building retains little integrity. Furthermore, its removal from its original location has damaged its eligibility. The building does not meet any of the considerations under Criteria Consideration B.

Urban Legal Description _____
 _____ SEE CONTINUATION SHEET

NDCRS ARCHITECTURAL SITE FORM

page 2

Field Code BRW US2 S024

SITS # 32MN

<u>18</u> Feature #	<u>62</u> Feature Type	<u>6</u> Condition
Construction Date	<u>13</u> Context *	
<u>3</u> Feature Date	<u>26</u> Primary Exterior *	<u>5</u> Plan Shape *
<u>25</u> Structural System **	<u>0</u> Style	Secondary Exterior
<u>0</u> Ethnic		Architect/Builder
<u>11010200</u> Fieldwork Date		Other Information

FOUNDATION TYPE Poured concrete STORIES 1 ROOF TYPE/CORNICE Gambrel; composition shingles

WINDOW CONDITION Most original windows/openings intact DATING METHOD Professional estimate

PRESERVATION RECOMMENDATION (check all that apply):

- 1) Individual Nomination 2) Contributes to a potential district
- 3) No nomination potential 4) Will not contribute to a district
- 5) Potential district not known at this time: feature would be a contributing element if neighboring properties constitute a district
- 6) Thematic nomination potential 7) Component of historic site/landscape

- 8) Feature has an important physical, spatial, functional, historic or architectural relationship to the site/complex/farmstead
- 9) D Moved: A) relocation occurred within historic period. B) recreates original site, orientation, landscape and spatial relationships. C) compatible in context with neighboring structures. D) relocation has damaged eligibility.
- 10) Request comparative study of neighboring properties
- 11) Historical associations require further investigation

DESCRIPTION/INTEGRITY/ELIGIBILITY Feature #18 is a barn from rural White Earth that has been moved into Flickertail Village. The one-story frame building is rectangular in plan and has a poured concrete foundation. The structure is clad with horizontal wood siding with corner boards. The steep gambrel roof is clad with composition shingles and has exposed rafter tails. There is a small metal roof aerator at the ridge. The windows are primarily wood-framed divided-light windows. There is one sliding batten door on the east facade and a loft door on the west facade.

Although the building retains some integrity, its removal from its original location has damaged its eligibility. The building does not meet any of the considerations under Criteria Consideration B.

Urban Legal Description _____

SEE CONTINUATION SHEET

NDCRS ARCHITECTURAL SITE FORM

page 3

Field Code BRW US2 S024

SITS # 32MN

OWNER'S NAME, ADDRESS, PHONE # _____

PROJECT TITLE US Hwy 2 Cultural Resources Inventory for FHWA and North Dakota Dept. of Transportation
(subcontracted through Houston Engineering); B. E. Perkl and B. A. Mitchell, Co-Principal Investigators

REPORT TITLE US Hwy 2 Cultural Resources Inventory in Ward, Mountrail, & Williams Counties, North Dakota.
Authored by B. E. Perkl & B. A. Mitchell, et al. URS/BRW Report No. 01-01, URS/BRW, Inc., Minneapolis, Minnesota.

SITE AREA 235,215 (in square feet)

ACCESS From Stanley at the intersection of 4th Street East and US Hwy. 2 for approximately 0.7 miles. From there head north onto the property.

DESCRIPTION Flickertail Village is located on a flat parcel of land between the fairgrounds and US Hwy 2. Few trees are on the property, which is fenced off from the surrounding landscape. A gravel drive leads from Hwy 2 past the property. All of the buildings that make up the museum have been collected and relocated to the property since 1981. They are arranged in a linear groups that make up a triangle. The collection of buildings have been continually enlarged and rearranged since 1981.

SUMMARY OF SITE FEATURES AND EVALUATION OF SIGNIFICANCE Summary of Site Features: Ross Depot – 1; House (Bank) – 2; Community Building (Village Jail) – 3; Ross House (Doctors' Office) – 4; Blacksmith Shop – 5; Country School #1 (General Store) – 6; Country School #2 (Saloon) – 7; Shed – 8; Van Hook House – 9; Olson House – 10; Solberg House – 11; Outhouse #1 – 12; Country School #3 – 13; Blaisdell Catholic Church – 14; Cook Car – 15; Stanley House – 16; Lee House – 17; Barn – 18; Chicken Coop – 19; Outhouse #2 – 20; Windmill #1 – 21; Windmill #2 – 22; Lutheran Church Replica – 23; Homestead Shack – 24; Pole Shed #1 – 25; Pole Shed #2 – 26; Gazebo – 27; Burlington Northern Caboose and Boxcar – 28; and School Bus – 29.

Flickertail Village is an architectural museum in Stanley. The property was patented to John C. Tasher in 1905 (GLO Land Records Database). The 1917 Mountrail County atlas indicates that this property was owned by Ollie Studebaker (Ogle & Co. 1917). By 1937 the Mountrail County Fair Association owns the property (WPA 1937). The Ross Depot (Feature #1) was the first building moved to the location, in 1979. In 1980, the Heritage Center Committee was formed and plans were made to restore the depot and develop a "frontier village" based on typical railroad towns. After 1981, additional buildings were moved onto the property. Flickertail Village opened to the public in 1983 (Mountrail County Historical Society 1986).

Per Criteria Consideration B, the Village as a whole cannot be considered eligible for listing on the National Register of Historic Places because it has not achieved significance since the time of its assemblage. None of the individual buildings on the property meets any of the considerations under Criteria Consideration B. Although the Depot (Feature #1) retains some material integrity, modifications during the early 1980s may preclude its nomination under Criterion C.

Photo I.D. Code BRW US2 Roll 29, Frame 21 (B&W); BRW US2 Roll 29, Frame 22 (B&W)

Storage Location State Historical Society of North Dakota: State Historic Preservation Office

Include direction facing, feature number, and photo caption for each submitted photograph.

Flickertail Village, facing East



Flickertail Village, facing SW



Photo I.D. Code BRW US2 Roll 28, Frame 10 (B&W); BRW US2 Roll 28, Frame 11 (B&W)

Storage Location State Historical Society of North Dakota: State Historic Preservation Office

Include direction facing, feature number, and photo caption for each submitted photograph.

General View of Features #1, 2, 3, 4, 5, 6, & 7, facing West



Shed (Feature #8), facing SW



Photo I.D. Code BRW US2 Roll 28, Frame 8 (B&W); BRW US2 Roll 28, Frame 13 (B&W)

Storage Location State Historical Society of North Dakota: State Historic Preservation Office

Include direction facing, feature number, and photo caption for each submitted photograph.

Front of Country School #1 (*General Store*) (Feature #6), facing NW



Rear of Country School #1 (*General Store*) (Feature #6), facing SE



Photo I.D. Code BRW US2 Roll 28, Frame 9 (B&W); BRW US2 Roll 28, Frame 14 (B&W)

Storage Location State Historical Society of North Dakota: State Historic Preservation Office

Include direction facing, feature number, and photo caption for each submitted photograph.

Front of Country School #2 (*Saloon*) (Feature #7), facing NW



Rear of Country School #2 (*Saloon*) (Feature #7), facing SE



Photo I.D. Code BRW US2 Roll 28, Frame 23 (B&W); BRW US2 Roll 28, Frame 24 (B&W)

Storage Location State Historical Society of North Dakota: State Historic Preservation Office

Include direction facing, feature number, and photo caption for each submitted photograph.

Front of Country School #3 (Feature #13), facing NE



Rear of Country School #3 (Feature #13), facing SW

