

NDCRS ARCHITECTURAL SITE FORM

PAGE 1

UPDATE

Field Code

SITS# 32

SITE IDENTIFICATION

Map Quad _____ Site Name

Map Quad _____ Site Name _____

LTL	___TWP	<input type="text" value="153"/>	R	<input type="text" value="88"/>	SEC	<input type="text" value="35"/>	QQQ	<input type="text" value="6"/>	QQ	<input type="text" value="7"/>	Q	<input type="text" value="7"/>
LTL	___TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____
LTL	___TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____
LTL	___TWP	_____	R	_____	SEC	_____	QQQ	_____	QQ	_____	Q	_____

NAD 1983, UTM _____ N ZONE _____
NAD 1983, UTM _____ E

City:

Street Number: _____

Street Name:

Urban Legal Description: _____

Subsection:
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

SITE DATA

Total # **Architectural** Features:

Fieldwork Date: _____

Reconnaissance Survey Intensive Survey _____

Project & Principal Investigator: _____

Report Title & Author(s): _____

Contracting firm or Agency completing the form: _____

Additional Information: _____

SHSND USE

Area of Significance	___	Ecozone	___	Verified Site	___	CR Type	___
Area of Significance	___	Ecozone	___				
Area of Significance	___	Ecozone	___				

Recorded By
(First Name & Last Name)

Date Recorded
(mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately, and save; (5) **Print** and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM
PAGE 2—Feature Data

UPDATE

Field Code Like a Fish Hook School

SITS# 32 MN 668

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date

Feature Type 9

Condition 7

Feature Date 2

Context 7

Plan Shape

Structural System 25

Primary Exterior 26

Style Not Applicable

Original Owner's Ethnicity

Secondary Exterior N/A

Architect/Builder

Other Information:

Foundation Poured concrete Stories 1

Roof/Cornice Gable

Window Double hung, glass

Dating Method(s): History

Feature Preservation Recommendation(s) (Check all that apply):

- Individual nomination
Contributes to a potential district
No nomination potential
Will not contribute to a district
Potential district—feature would be a contributing element if other properties constitute a district
Thematic nomination potential
Component of a historic site or landscape
Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility
Historical associations require further investigation

Recorded By Kathy Wilner
(First Name & Last Name)

Date Recorded 7/5/2019
(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM

PAGE 3—Feature Data

UPDATE

Field Code

SITS# 32

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature has been previously documented, this will update a bit. The building was documented as a church however it also fits the criteria of a school as they used it for both. It was built in 1880 as a Mission Church/School at Fort Berthold. Fun fact for this building is that a wall had to be constructed down the middle of the building as there were tribes who did not care for each other and were unwilling to share the space.

The roof of the building was recently replaced and they put metal that has the look of asphalt shingles on it. They had problems with leaking with asphalt shingles so solved the problem with metal sheeting. A concrete chimney is located on the south sloe near the peak. The soffits are open. The entry of the building has a belfry above the entry with a bell. The entry measures 10 feet square and is nearly three storie high with the look of a church spire. The top of the belfry roof is covered with asphalt shingles.

There is a rake board at the peak ends of the building. The siding is 6 inch wood lap and 4 inch wood corner trim with fair paint protecting it. A ramp leads to the double door of the entry. There are two double hung windows on the north side, three on the south and a pair on the west side. One more double hung window is located on the west wall of the entry. All glass intact. The entry walls and ceiling are all finished with pressed tin. The interior of the main part of the building has lathe and plaster walls and ceiling with some of the ceiling in need of repair as they had some water damage. The floor is tongue and groove hard wood. There are no blackboards and no wainscot. They do have electricity.

This building is the Plaza Museum and they have a nice display of artifacts.

Recorded By

(First Name & Last Name)

Date Recorded

(mm/dd/year)

**NDCRS ARCHITECTURAL SITE FORM
PAGE 4—SITE DESCRIPTION**

UPDATE

Field Code

SITS# 32

Complete one Page 4 for the entire site.

2. Owner's Contact Information:
City of Plaza

3. Access (to rural areas):
It is located at the corner of Berthold Street and 5th Avenue, in the northwest part of town.

4. Site Area (ft²): _____

5. Description of **SETTING**:
Houses all directions as it is located right in town.

Recorded By
(First Name & Last Name)

Date Recorded
(mm/dd/year)

**NDCRS ARCHITECTURAL SITE FORM
PAGE 5—SITE DESCRIPTION**

UPDATE

Field Code

SITS# 32

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments:

Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Recorded By
(First Name & Last Name)

Date Recorded
(mm/dd/year)



West Side


Like a Fish Hook School

6/26/2019

Kathy Wilner

MN

South Side





North Side

Like a Fish Hook School

6/26/2019

Kathy Wilner

MN



East Side



Imagery ©2019 Google, Map data ©2019 100 ft

Feature