# NDCRS ARCHITECTURAL FORM PAGE 1

UPDATE 2020

Field Code Lindvig School Map Quad Williston SE	Si	SITS# 32 <sup>M</sup>	
Map Quad	Si , Sec. 4 QQQ 7 , Sec. QQQ , , Sec. QQQ , , Sec. QQQ , , Sec. QQQ , , Sec. 2000 , ,	te Name of the Q of the QQ of the Q of the QQ of the Q of the QQ of the Q	Subsection $1 = N\frac{1}{2}$ $2 = E\frac{1}{2}$
Street Number: Street Name:County Road 29			
Urban Legal Description: Total Number of <b>Architectural</b> F			
Fieldwork Date: 8/18/2021 Reconnaissance Survey			
Project & Principal Investigator: Country School House Project Kathy Wilner 366 43rd Ave SE Bowdon ND 58418		Survey	
Contracting Firm or Agency Com	pleting the Form:		
Additional Information:			
SHSND USE         Component         Component         Component	Unit Verifie	d Site CR Type	
Recorded By:	Kathy Wilner	Date Recorded:	10/31/2021

# NDCRS ARCHITECTURAL FORM PAGE 2 - Feature Data

Field Code Lindvig School	SITS# 32	MZ	2744
Complete one Page 2 for each architectural feature at the s	site.		
Architectural Feature #1			
Construction Date			
Feature Date <u>1915-1930</u>			
Structural System <u>Wood Frame</u>			
Original Owner's Ethnicity			
Feature Type 9 - School; Church school			
Context <u>Education</u>			
Primary Exterior <u>Wood, Horizontal Siding</u>			
Secondary Exterior			
Condition Excellent			
Plan Shape <u>Rectangular</u>			
Style Other Style			
Architect/Builder			
Foundation Poured Concrete	Stories <u>1</u>		
Roof/CorniceGable			
Window Replacement double hung, glass			
Dating Method(s) Previous documentation estimate			
Miscellaneous Information			
Feature Preservation Recommendation(s) (Check all that a	ipply):		
Individual nomination			
Contributes to a potential district			
No nomination potential			
Will not contribute to a district			
Potential district—feature would be a contributing elem	ent if other proper	ties c	onstitute a district
Thematic nomination potential			
Component of a historic site or landscape			
Moved (specify all applicable choices)—a) relocation of site, orientation, landscape, and spatial relationships; c relocation has damaged eligibility			
Historical associations require further investigation			

Kathy Wilner

## NDCRS ARCHITECTURAL FORM PAGE 3 – Feature Data

# Field Code Lindvig School

SITS# 32 MZ 2744

Complete one Page 3 for each architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

The story of th feature is included in the 2014 documentation. The only change I see since it was documented in 2014 is that the east side window in the entry and a window on the south side of the school have been boarded up.

The interior of the school is in fair shape. The walls and ceiling are finished with lathe and plaster. Some of the ceiling plaster is starting to fall in. Wainscot is seen under the windows the blackboards. The floor is tongue and groove hardwood. There are two blackboards on the north wall to either side of the chimney. There is an oil burning stove connected to the chimney. Light fixtures would indicate the presence of electricity.

2. Owner's Contact Information: Wesley & Barbara Lindvig 14075 41st St NW Alexander ND 58831

### Recorded By:

Kathy Wilner

Date Recorded: 10/31/2021

## NDCRS ARCHITECTURAL FORM PAGE 4 – Site Description

# Field Code Lindvig School

SITS# 32 MZ 2744

3. Site Area (ft<sup>2</sup>):

4. Description of Access and Site Setting:

Access to this school is from Highway 85 11 miles north of Alexander. Look for County Road 29 on the right, turn and go east 2 miles to see the school on the north side of the road. There is a farm just west, rolling hills, farm fields and pasture around the school.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418


**Recorded By:** 

Kathy Wilner

Date Recorded: 10/31/2021



West Side



North Side



South Side









Imagery ©2021 CNES / Airbus, Landsat / Copernicus, Maxar Technologies, USDA Farm 1000 ft Service Agency, Map data ©2021

**Feature** 



Photo taken summer 2010 by SHSND intern Alicia Liebel

# Recorded By: Lorna Meidinger

Date Recorded: 11/17/2020

## NDCRS ATTACHMENT SECTION

# Field Code \_\_\_\_\_

# SITS# 32 MZ 2744



Photo taken summer 2010 by SHSND intern Alicia Liebel

# Recorded By: Lorna Meidinger

Date Recorded: 11/17/2020

## NDCRS ATTACHMENT SECTION

# Field Code \_\_\_\_\_

# SITS# 32 <u>MZ</u> 2744



Photo taken summer 2010 by SHSND intern Alicia Liebel

# Recorded By: Lorna Meidinger

Date Recorded: 11/17/2020

# NDCRS ATTACHMENT SECTION

# Field Code \_\_\_\_\_

# SITS# 32 <u>MZ</u> 2744



Photo taken summer 2010 by SHSND intern Alicia Liebel

# Recorded By: Lorna Meidinger

Date Recorded: 11/17/2020

NDCRS 2009

State Historical Society of North Dakota

NDCRS	<b>ARCHITECTURAL SITE FO</b>	RM
	PAGE 1	

SITS#	32	ΜZ	27	

SITE IDENTIFICATION			
Field Code MAC-MNB-1009	Site Name		
Map Quad <u>Williston SE</u> Map Quad	Site Name		
		QQ <u>7</u> QQ QQ	Q <u>6</u> Q Q
UTM5318119N UTM603297E	ZONE <u>13N</u> NAD 1927	NAD 1983 _	Subsection: $1 = N\frac{1}{2}$ $2 = E\frac{1}{2}$
City:			3 = S½
Street Number:	••••••••••••••••••••••••••••••••••••••		4 = W½ 5 = NE¼
Street Name:			6 = SE¼ 7 = SW¼
Urban Legal Description:			8 = NW1⁄4
SITE DATA			
Total # Architectural Features:2			
Fieldwork Date: 6/17/2014			
Reconnaissance Survey <u>√</u> Intensi	ve Survey		
Project Title & Supervisor:			
Project Title: HDR Engineering Inc.'s McKenzie Supervisor: Diana M. Barg	Northern Bypass		
Report Title & Author(s):			
Report Title: Results of a Cultural Resource Inv Northern Bypass Roadway Project in McKenzie	• •		
Additional Information: Site: One schoolhouse	and one outhouse		
SHSND USE      Ecozone        Area of Significance      Ecozone        Area of Significance      Ecozone	Verified Site Non-Site	CR Type	2
Recorded By D. Barg and A. M	eade Date	Recorded	5/17/2014
(First Name & Last Name)			(mm/dd/year)

NDCRS 2009

Complete one Page 2 for each architectural feature at the site         Architectural Feature #         Construction Date       Feature Type9       Co         Feature Date 4       Context7       Pla         Structural System 25       Primary Exterior 26       Sty         Original Owner's Ethnicity       Secondary Exterior       Arc	TS# 32_ <u>MZ</u> ite. ndition <u>6</u> in Shape <u>5</u>
Architectural Feature #1         Construction Date       Feature Type9 Construction Date         Feature Date 4       Context7 Planet         Structural System 25       Primary Exterior 26 Sty         Original Owner's Ethnicity Secondary Exterior Arcompared	ndition <u>6</u>
Feature Date 4       Context 7       Pla         Structural System 25       Primary Exterior 26       Sty         Original Owner's Ethnicity       Secondary Exterior       Arc	
Structural System 25       Primary Exterior 26       Sty         Original Owner's Ethnicity       Secondary Exterior       Arc	n Shape <u>5</u>
Original Owner's Ethnicity Secondary Exterior Arc	
	le Gabled Front: Gabled L/T
	hitect/Builder
One cellar door on the southwest corner Other Information: Foundation Poured concrete Sto	ries <u>1</u>
Roof/Cornice_Front-gabled; wood shake shingles underneath gray asphalt sh	ingles.
Window Original openings intact; some frames altered; glass remains in all b	ut one.

### Feature Preservation Recommendation(s) (Check all that apply):

- \_\_\_\_Individual nomination
- \_\_\_\_Contributes to a potential district
- \_\_\_\_No nomination potential
- \_\_\_\_Will not contribute to a district

\_\_\_\_Potential district—feature would be a contributing element if other properties constitute a district

\_\_\_\_\_Thematic nomination potential

\_\_\_\_Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context \_\_with neighboring structures; d) relocation has damaged eligibility

Historical associations require further investigation

Recorded By	D. Barg and A. Meade	Date Recorded	6/17/2014
(First	Name & Last Name)		(mm/dd/year)

NDCRS 2009

### NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code MAC-MNB-1009

#### SITS# 32 MZ

#### Complete a Page 3 for each feature.

#### 1. Feature Description, Integrity, Eligibility:

DESCRIPTION: Feature 1 is a one-room schoolhouse with a small mudroom attached to the south facade. Both the schoolhouse and the mudroom have moderately-pitched front-gabled roofs and horizontal wood clapboard siding. The entire building has recently been painted white. The mudroom stands about five feet shorter than the main schoolhouse. There is a small wooden deck in front of the mudroom. Two entrances are located along the south facade of the mudroom. The westernmost door leads into the mudroom, wherein an interior door leads into the schoolhouse itself. The eastern door leads down to a cellar. Both doors are wood-paneled with simple frames and are painted white. There is an electrical hook-up and light fixture directly beneath the roof apex of the mudroom. Both the schoolhouse and mudroom have wood shingles underneath a more recent layer of interlocking asphalt shingles. There is one wood-framed, double-hung window, which is missing glass in the top pane, on the east face of the mudroom, and another on the west. Six double-hung windows, all set right next to each other, are located on the west facade of the main schoolhouse portion. It appears that the outer panes of these windows have been replaced with new metal-framed panes. There is another set of paired double-hung windows on the south facade of the schoolhouse portion with a wooden frame. The north and east facades of the main building have no windows. A basement window was once located below the northernmost windows, but it has since been boarded up. There is a small round vent with thatched metal wiring just above it. A brick chimney is located at the northern end of the roof. The building has a closed soffit and has decorative trim along the roof edge. A cellar hatch is located at the south end of the western facade.

INTEGRITY: Feature 1 retains integrity of location, setting, design, workmanship, and feeling. Integrity of materials has been slightly impacted by the addition of new metal frames to the windows on the west facade. Overall, the feature in good condition and retains integrity.

ELIGIBILITY: Feature 1 has not been evaluated for eligibility to the National Register of Historic Places. Current survey data are not sufficient to determine significance. Until a deed search can be performed, avoidance is recommended.

#### Recorded By\_

D. Barg and A. Meade (First Name & Last Name) Date Recorded 6/17/2014

(mm/dd/year)

NDCRS 2009

# NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code MAC-MNB-1009

SITS# 32\_MZ\_\_\_

Complete one Page 4 for the entire site.

2. Owner's Contact Information:

Private

3. Access (to rural areas):

From the intersection of US Highway 85/ Theodore Roosevelt Expy and County Road 29, travel east on County Road 29 for 2 miles. The site is located 37 meters north of the road.

4. Site Area (**ft**<sup>2</sup>): 4,510

#### 5. Description of SETTING:

This site is located on the north side of County Road 29. A less significant road, likely an access road for a well pad, is located to the east. A mixture of prairie grassland, a shelter belt, and a farmstead lie to the west. Cultivated fields are located to the north and southeast, while a barbed wire fence runs to the north and east of the site.

# Recorded By D. Barg and A. Meade Date Recorded 6/17/2014 (First Name & Last Name) (mm/dd/year)

NDCRS 2009

# NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code MAC-MNB-1009

## SITS# 32 MZ

#### 6. *Summary of ALL* Site Features & Evaluation of Significance:

Feature 1 is a one room schoolhouse with an attached mudroom. Feature 2, located directly north of the schoolhouse, is an outhouse.

The site retains integrity of location, setting, design, and workmanship. Integrity of materials has been impacted by the addition of new metal frames to the windows in Feature 1, while integrity of feeling is reduced due to the overall poor condition of Feature 2.

This site has not been evaluated for eligibility to the National Register of Historic Places. Current survey data are not sufficient to determine significance. Until a deed search can be performed, avoidance is recommended.

7. References/Comments:

Midland Atlas Co.

2009 (1916 insets) Atlas of McKenzie County North Dakota. On file at the State Historical Society.

Recorded By D. Barg and A. Meade Date Recorded 6/17/2014 (First Name & Last Name) (mm/dd/year)

# NDCRS SITE FORM ATTACHMENTS SECTION

### Field Code MAC-MNB-1009

SITS# 32MZ



Figure 2: Overview of MAC-MNB-1009, view to the northwest (Image 3118).



Figure 3: View to the northeast of MAC-MNB-1009, Feature 1 (Image 3122).

Date Recorded 6/17/2015

# NDCRS SITE FORM ATTACHMENTS SECTION

### Field Code MAC-MNB-1009

SITS# 32MZ



Figure 4: View to the west of MAC-MNB-1009, Feature 1 (Image 3137).



Figure 5: View to the north of MAC-MNB-1009, Feature 2 (Image 3129).

Recorded By D. Barg and A. Meade

Date Recorded 6/17/2015