UPDATE

NDCRS ARCHITECTURAL FORM PAGE 1

Field Code	SITS# 32 PI 85
Map Quad Map Quad	Site Name Meyer Township School #1Site Name
-	QQQ7of the QQ7of the Q7QQQof the QQof the QQof the Q $1 = N\frac{1}{2}$ QQQof the QQof the QQof the Q $2 = E\frac{1}{2}$ QQQof the QQof the QQof the Q $3 = S\frac{1}{2}$
NAD UTM NAD UTM City:	6 = SE¼ 7 = SW¼
Street Number:	8 = NW¼
Street Name:	
Urban Legal Description:	
Total Number of Architectural Features: Fieldwork Date:08/08/2024	1
Reconnaissance Survey	Intensive Survey
Project & Principal Investigator:	
Contracting Firm or Agency Completing the F SHSND	orm:
Additional Information: Photo provided by Hunter Andes via Kathy Wilr	ner. Photo taken in August 2024.
SHSND USE Component Component Component	Verified Site CR Type

 Recorded By:
 E. Scherr, SHSND
 Date Recorded:
 08/19/2024

 Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.
 08/19/2024

NDCRS ARCHITECTURAL FORM PAGE 2 – Feature Data

UPDATE

Field Code	SITS# 32	PI	85
Complete one Page 2 for each architectural feature at the site.			
Architectural Feature #1			
Construction Date			
Feature Date			
Structural System			
Original Owner's Ethnicity			
Feature Type			
Context			
Primary Exterior			
Secondary Exterior			
Condition Good			
Plan Shape			
Style			
Architect/Builder			
Foundation Stor	ies		
Roof/Cornice			
Window			
Dating Method(s)			
Miscellaneous Information			
Feature Preservation Recommendation(s) (Check all that appl	y):		
Individual nomination			
Contributes to a potential district			
No nomination potential			
Will not contribute to a district			
Potential district—feature would be a contributing element	if other propert	ies co	nstitute a district
Thematic nomination potential			
Component of a historic site or landscape			
Moved (specify all applicable choices)—a) relocation occur site, orientation, landscape, and spatial relationships; c) co relocation has damaged eligibility			· · · ·
Historical associations require further investigation			

 Recorded By:
 E. Scherr, SHSND
 Date Recorded:
 08/19/2024

NDCRS ATTACHMENT SECTION

Field Code

```
SITS# 32 PI 85
```



Figure 1: 32PI85, view north. Photo captured by Hunter Andes in August 2024.

Recorded By: E. Scherr, SHSND_____ Date Recorded: 8/19/2024

NDCRS 2020

NDCRS ARCHITECTURAL FORM

PAGE 1

	PAGE 1	UPDATE 오
Field Code Meyer Township School #	SITS# 32 ^{Pl}	85
Map Quad Rugby	Site Name Meyer Township Sc	hool #1
Map Quad		
LTL T. <u>156</u> N., R. <u>72</u> W., Sec	2 QQQ 7 of the QQ 7 of the Q 7	- Subsection
	QQQ of the QQ of the Q	
	QQQ of the QQ of the Q	
	QQQ of the QQ of the Q	
NAD1983 UTM5368402 NAD1983 UTM878474	Zone 13N	$4 = W\frac{1}{2}$
NAD 1983 UTM 878474		5 = NE¼ 6 = SE¼
City: Rugby		7 = SW¼
		8 = NW¼
Street Number:		
65th St NE		
Street Name:65th St NE		
Urban Legal Description:		
Total Number of Architectural Features:	1	
Total Number of Architectural Features.		
444700.40		
Fieldwork Date: 4/4/2016		
Reconnaissance Survey	Intensive Survey	
Designed & Drivering of Jacobi Strategy		
Project & Principal Investigator: Country School House Project		
Kathy Wilner		
366 43rd Ave SE		
Bowdon ND 58418		
Contracting Firm or Agonov Completing th	a Form:	
Contracting Firm or Agency Completing th		
Additional Information:		
SHSND USE		
Component Study Unit	Verified Site CR Type _	
Component		
Component		
Recorded By: Kathy W	/ilner Date Recorded: 9	/16/2020

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM PAGE 2 – Feature Data

Field Code Meyer Township School #1	SITS# 32	Pi	85	
Complete one Page 2 for each architectural feature at the site.				
Architectural Feature #1				
Construction Date1897				
Feature Date <u>1880-1900</u>				
Structural System Wood Frame				
Original Owner's Ethnicity				
Feature Type <u>9 - School; Church school</u>				
Context <u>Education</u>				
Primary Exterior Wood, Horizontal Siding				
Secondary Exterior				
Condition <u>Good</u>				
Plan Shape <u>L-Shaped</u>				
Style <u>Other Style</u>				
Architect/Builder				
	es <u>1</u>			
Roof/Cornice Hip roof with gable at the entry				
Window Double hung, multi pane with most of the glass intact				
Dating Method(s)Original Recording of the site				
Miscellaneous Information				
Feature Preservation Recommendation(s) (Check all that apply	<i>r</i>):			
Individual nomination				
Contributes to a potential district				
No nomination potential				
Will not contribute to a district				
Potential district—feature would be a contributing element in	f other prope	rties c	onstitute a dist	rict
Thematic nomination potential				
Component of a historic site or landscape				
Moved (specify all applicable choices)—a) relocation occurn site, orientation, landscape, and spatial relationships; c) cor relocation has damaged eligibility				
Historical associations require further investigation				

Date Recorded: ____

9/16/2020

Kathy Wilner

Recorded By: _

NDCRS ARCHITECTURAL FORM PAGE 3 – Feature Data

Field Code Meyer Township School #1

SITS# 32 PI 85

Complete one Page 3 for each architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school, foundation was not noted. The roof of this Lshaped building consists of a hip roof over the mainbody of the school and a gable roof over the entry/vestibule, all covered with asphalt shingles. There is a bell tower on the roof of the entry with a peaked roof also covered with asphalt shingles. The soffits are open on this school. There is a metal chimney pipe on the west slope of the school. There are also roof vents on the west and east slopes of the roof. The roof extension above the door on the entry has three brackets for support.

The siding on the school is 4 inch wood lap with metal corner trim. There are concrete steps leading to a wood platform porch. There are half walls to either side as you climb the steps to the porch. The wood door has had the lower half kicked in since pictures were taken. Above the door is a sign the reads Meyer Twp School No. 1 and above the sign is an outdoor light. There are a number of windows, three on the west side are covered and the covering appears to be plywood inserts with framing around each window. There is another on the north side and what appears to be two more on the east side, all covered in the same manner. The windows to the south are two pairs of multipane, double hung windows with most of the glass intact. The pair to the west side are covered while the pair to the east side are partially covered. On the east side of the entry there is a small covered window. The floor is tongue and groove hardwood. The walls and ceiling in the school are of lathe and plaster. The walls are tall with a picture rail running along all walls. There are blackboards running along most of the north wall cornering to cover about 2/3 of the east wall. A two panel wood door leads into the school room from the entry/coat room. A fuel oil barrel on the north side of the school would suggest the last heat used in the building was fuel oil furnace.

2. Owner's Contact Information: Curtis Geibel PO Box 210 Hygiene CO 80533

Recorded By: __

Kathy Wilner

Date Recorded: 9/16/2020

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM PAGE 4 – Site Description

Field Code Meyer Township School #1

SITS# 32 PI 85

3. Site Area (ft²):

4. Description of Access and Site Setting:

This school is located just north of a busy highway. There is a farm site to the northwest and another to the south east. Location of the school is at the intersection of Highway 2 and 34th Avenue, 4 miles east of Rugby.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Kathy Wilner

Date Recorded: 9/16/2020



South Side

Meyer Township School #1 4/4/2016 Kathy Wilner PI







West Side

Meyer Township School #14/4/2016Kathy WilnerP1North Side

Meyer Township School #1 Pl Google Maps Kathy Wilner 9/9/2020 OSTA SRIVE (SETTA STATE) **GELLISTINE** 650 間. GELLISINE GEE SRIVE 2 GERE SERVE 2 200 Google

Imagery ©2020 Maxar Technologies, USDA Farm Service Agency, Map data ©2020 200 ft Feature

NDCRS ARCHITECTURAL SITE FORM PAGE 1

	FAGE	SITS# 32 P	1 85
SITE IDENTIFICATION		5115# 52 <u>-</u>	
Field Code <u>32PIx79</u>			
Map Quad <u>Rugby</u> Map Quad	Site Name		
LTL TWP R S LTL TWP R S LTL TWP R S LTL TWP R S	EC QQQ	QQ	Q <u>7</u> Q Q
UTM5368402N UTM878474E		_3N NAD 1983 <u>↓</u>	Subsection: 1 = N ¹ / ₂
City:			$2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$
Street Number:			4 = W ¹ ⁄ ₂ 5 = NE ¹ ⁄ ₄
Street Name:			6 = SE¼ 7 = SW¼
Urban Legal Description:			8 = NW1⁄4
SITE DATA			
Total # Architectural Features:1			
Fieldwork Date:7/19/2013			
Reconnaissance Survey Ir	ntensive Survey 🗹		
Project Title & Supervisor:			
Highway 2 Devils Lake District; Michelle S	Sadlier		
Report Title & Author(s):			
Highway 2 from the West to East Devils L Inventory, Pierce, Benson, Ramsey, and I			al Resource
Additional Information: Previously recorde	d as Site Lead 32PIx79;them	atic nomination po	otential to NRHP
SHSND USE Area of Significance Area of Significance Area of Significance Area of Significance	Z Verified Site Non-Site	_ CR Type	_2_
Recorded By Michelle S	Sadlier Date	Recorded	7/19/2013
(First Name & Last Name)			(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code <u>32PIx79</u>		SITS# 32 <u>PI</u>		
Complete one Page 2 <u>for each a</u>	architectural feature at th	e site.		
Architectural Feature #1				
Construction Date <u>1897</u>	Feature Type <u>9</u>	Condition <u>6</u>		
Feature Date 2	Context 7	Plan Shape <u>3</u>		
Structural System <u>25</u>	Primary Exterior <u>26</u>	StyleOther Style		
Original Owner's Ethnicity	Secondary Exterior	Architect/Builder		
Other Information:				
Foundation Undetermined		_Stories1		
Roof/Cornice Hip and Gable				
Window Most original windows boarded over, openings intact				
Dating Method(s): Site form for 32PIx79 (original recording of site)				

Feature Preservation Recommendation(s) (Check all that apply):

- ____Individual nomination
- ____Contributes to a potential district
- ____No nomination potential
- ____Will not contribute to a district
- ____Potential district—feature would be a contributing element if other properties constitute a district
- Thematic nomination potential
- ——Component of a historic site or landscape
- Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context _____with neighboring structures; d) relocation has damaged eligibility
- _____Historical associations require further investigation

Recorded By	Michelle Sadlier	Date Recorded	7/19/2013
(Fi	rst Name & Last Name)		(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code 32PIx79

SITS# 32_PI___

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

DESCRIPTION: This historic property is a late nineteenth century, rural, one room schoolhouse. Its L-shaped plan consists of the main, rectangular volume of the school room with a projecting entrance vestibule. It is wood-framed with narrow-gauge, horizontal clapboard painted white; the paint is currently in a state of deterioration. The roof has a gable end to the south-facing entrance vestibule and is hipped to the main volume. Eaves details include brackets and exposed rafter feet. A four sided cupola surmounts the entrance vestibule. The cupola's roof also contains exposed rafter feet and a roof which may be influenced by the Scandinavian Gothic in style. All roof elements are treated in asphalt shingles in good condition. A metal stove pipe projects from the west roof slope. The open front porch appears to have had some modifications, including the concrete steps and platform, both of which appear to be replacements. The clapboard treatment on the porch's two half walls may be original.

Fenestration is mostly boarded over and the presence of original/early window units could not be confirmed for most openings. Based on photographs included with the 32PIx79 site form and the appearance of unboarded windows, those to the south elevation appear to be two pairs of six-over-six, double-hung, sash windows. One pair is currently boarded over while the second is only partially so. This change has occurred since the building was originally recorded. All other windows were boarded over prior to original recording. These include what may be a pair of windows on the east elevation, one window on the north (rear) elevation, three windows on the west elevation, and one window on the east elevation of the entrance vestible. The building contains only one door, which faces south. It is a wood paneled unit and is currently in a state of deterioration. Fenestration has unornamented surrounds and sills.

The building currently has a plywood sign painted with the following: "MEYER TWP. SCHOOL NO. 1". The sign is non-historic.

INTEGRITY: The schoolhouse is currently in good condition but appears to be the subject of ongoing neglect. In its current condition, it possesses integrity of location, design, setting, materials, workmanship, and feeling.

ELIGIBILITY: Historical research was not performed for the site so its historical associations are not known. However, as a rural, one-room, North Dakota schoolhouse which possesses integrity of location, design, setting, materials, workmanship, and feeling, the historic Meyer Township School No. 1 site has the potential for thematic nomination to the National Register of Historic Places (NRHP).

Recorded By	Michelle Sadlier	Date Recorded	7/19/2013
(First	Name & Last Name)		(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code <u>32PIx79</u>

SITS# 32__PI_____

Complete one Page 4 for the entire site.

2. Owner's Contact Information:

Unknown.

3. Access (to rural areas):

The schoolhouse is located 5 miles east of the intersection of US Highway 2 and ND 3 in Rugby, North Dakota, at the intersection of US Highway 2 and 34th Ave NE.

4. Site Area (**ft**²): _____ 29,350

5. Description of SETTING:

This school building is located in a rural setting along US Highway 2. It is surrounded by agricultural fields. It is 0.5 mi south of the railroad. The nearest urbanized area is Rugby, some 5 mi west of the site. Meyer Township itself does not contain a central settlement.

Recorded By Michelle Sadlier Date Recorded 7/19/2013
(First Name & Last Name) (mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code 32PIx79

SITS# 32__PI___

6. Summary of ALL Site Features & Evaluation of Significance:

As a one-room, rural schoolhouse dating from the late nineteenth century, Meyer Township School No. 1 has the potential for thematic nomination to the NRHP.

The site was previously recorded by A. Kulevsky in 2001 as Site Lead 32PIx79.

7. References/Comments:

Kulevsky, A. (2001) NDCRS Architectural Site Form for Site Lead 32PIx79. State Historical Society of North Dakota, Bismarck, ND.

Recorded By Michelle Sadlier Date Recorded 7/19/2013
(First Name & Last Name) (mm/dd/year)



Figure 1: Regional location of Site Lead 32PIx79 and other nearby previously recorded historic properties as depicted on USGS 7.5' Rugby (1980) and Pleasant Lake (1980) quadrangle maps.

Recorded By Michelle Sadlier Date Recorded 7/22/2013 (First Name & Last Name) (mm/dd/year)

NDCRS SITE FORM ATTACHMENTS SECTION



Figure 2: Mapped location of Site Lead 32PIx79, Meyer Township School No. 1 (aerial imagery based on 2013 ESRI data).

Recorded By	Michelle Sadlier	Date Recorded	7/22/2013
	(First Name & Last Name)		(mm/dd/year)

NDCRS SITE FORM ATTACHMENTS SECTION SITS#



N/A

32PIx79 UPDATE



Figure 3: Site Lead 32PIx79, a historic, one-room schoolhouse (Meyer Township School No. 1). View of the south elevation from the US Highway 2 right-of-way.



Figure 4: South (front) and east (side) elevations of the schoolhouse.

Recorded By __

Michelle Sadlier (First Name & Last Name) Date Recorded _____



NDCRS SITE FORM ATTACHMENTS SECTION

Field Code N/A

SITS# 32PIx79 UPDATE



Figure 5: North (rear) elevation of this Meyer Township school in US Highway 2.



Figure 6: West elevation of the schoolhouse.

Recorded By ____

Michelle Sadlier (First Name & Last Name)

Date Recorded 7/22/2013 (mm/dd/year)

NDCRS SITE FORM ATTACHMENTS SECTION



N/A

SITS# <u>32PIx79 UPDATE</u>



Figure 7: Windows on the south elevation at the east end of the building.



Figure 8: Eaves detail to the entrance vestibule.

Recorded By _

Michelle Sadlier (First Name & Last Name)

32PI 85

NDCRS SITE FORM ARCHITECTURAL SITE Page 1

· - ·,

	5
Γ	SITS # 32 PT 811
	Field Code Life Steven Site Name
	Map Quad Buggby 1. Ni Map Quad 2. Ei Map Quad 3. Si
SITE DATA	LTL Twp LTL R Integration Sec QQQ QQQ QQ Integration Int
S	City
	Street # Street #
	Street Name Street Name
	# of Features
FEATURE DATA	
USE	Soil Association المعالية Ecozone المحالية Soil Association المحالية Ecozone المحالية MS Number المحالية MS Number
SHSND	Lick Type Liverified Site INon-Site BIECF BIF
ŝ	L State Registry L National Register
	Coder <u>A Kulevsky</u> Date Coded <u>8/6/01</u>
	Reconnaissance Survey Intensive Survey
	Manuscript/Report Title: <u>Highway Z Bugby to Knot: A Class II Cultural</u> Resince Inventory in Prerce + Benson Counties, North Dakoh
	Author(s): Ed Stine

NDCRS ARCHITECTURAL SITE FORM

page 2

Field Code HFS-029-1

SITS # 32PIX

The Meyer Township Schoolhouse #1 was recorded as a site lead because it lies just outside the project area and therefore was not closely examined. It will not be affected by the proposed work on Highway 2.

The schoolhouse consists of a roughly rectangular building with a projecting entryway. A sign over the front doorway reads: "Meyer Twp. School No. 1 1897-1959." The building has wood siding. Windows on the front (south side) are intact, while all openings on the remaining three sides are covered. The roof consists of asphalt shingles and appears to be new. The chimney also looks new. The building is wired for electricity and has a fuel oil furnace (as indicated by a fuel tank in bank). Field personnel did not enter the building to investigate the interior.

Integrity appears to be excellent. It appears that someone is taking relatively good care of the building. Significance cannot be determined without additional research.

Field Code HFS-029-1

SITS # <u>32PIX</u>



Site location (Rugby USGS 7.5° quadrangle, 1955, pr 1980).

NDCRS ARCHITECTURAL SITE FORM

Field Code HFS-029-1

SITS #<u>32PIX</u>



View to north-northwest over school (exposure 7, roll 8-1-01).

NDCRS ARCHITECTURAL SITE FORM

Field Code HFS-029-1

SITS # <u>32PIX</u>



View to north-northeast over school (exposure 5, roll 8-1-01).