

NDCRS ARCHITECTURAL FORM
PAGE 1

Field Code Dewey District School #2

SITS# 32 PI 793

Map Quad Towner NE

Site Name Dewey District School #2

Map Quad _____

Site Name _____

LTL T. 157 N., R. 74 W., Sec. 20 QQQ 7 of the QQ 7 of the Q 7

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

NAD 1983 UTM 5361608 Zone 14N

NAD 1983 UTM 407290

City: _____

| Subsection | |
|------------|--|
| 1 = N½ | |
| 2 = E½ | |
| 3 = S½ | |
| 4 = W½ | |
| 5 = NE¼ | |
| 6 = SE¼ | |
| 7 = SW¼ | |
| 8 = NW¼ | |

Street Number: _____

Street Name: 68th St NE & 19th Ave NE

Urban Legal Description: _____

Total Number of Architectural Features: 1

Fieldwork Date: 982020

Reconnaissance Survey

Intensive Survey

Project & Principal Investigator:

Country School House Project
Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Contracting Firm or Agency Completing the Form:

Additional Information:

SHSND USE
 Component 2 Study Unit 17 Verified Site _____ CR Type 2
 Component _____
 Component _____

Recorded By: Kathy Wilner Date Recorded: 9172020

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM
PAGE 2 – Feature Data

Field Code Dewey District School #2

SITS# 32 PI

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date _____

Feature Date 1880-1900

Structural System Wood Frame

Original Owner's Ethnicity _____

Feature Type 9 - School; Church school

Context Education

Primary Exterior Wood, Horizontal Siding

Secondary Exterior _____

Condition Very Poor

Plan Shape Rectangular

Style Other Style

Architect/Builder _____

Foundation Poured concrete Stories 1

Roof/Comice Hip

Window Double hung windows of various sizes, all with some glass

Dating Method(s) Estimate

Miscellaneous Information _____

Feature Preservation Recommendation(s) (Check all that apply):

- Individual nomination
- Contributes to a potential district
- No nomination potential
- Will not contribute to a district
- Potential district—feature would be a contributing element if other properties constitute a district
- Thematic nomination potential
- Component of a historic site or landscape
- Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility
- Historical associations require further investigation

Recorded By: Kathy Wilner Date Recorded: 9172020

NDCRS ARCHITECTURAL FORM**PAGE 3 – Feature Data****Field Code** Dewey District School #2**SITS# 32** PIComplete one Page 3 for *each* architectural feature at the site.**1. Feature Description, Integrity, Eligibility:**

This feature is a very tired one room prairie school sitting on a poured concrete foundation. It was moved to the present location for use as a body shop. The hip roof of the building is in very bad shape with most of the asphalt shingles gone and many holes in the roof boards. There is a piece of metal capping with finials at the top of the roof. A yellow brick chimney is located on the north slope of the roof and several brick have fallen onto the roof. The soffits are closed with beadboard but pretty deteriorated.

A rake board begins the siding on all 4 sides of the school. The rest of the siding is 6 inch wood lap with 6 inch wood corner trim. The siding is beginning to fall away. There was an entry on the west side of the building and that was removed to make room for an overhead door. That has since been removed. To the left of the large opening is a walk-in door opening. There are 5 double hung, 4 over 4, windows on the east wall. All are covered and a lot of glass remains. On the south wall there are 5 smaller, 2 over 2, double hung windows with very little glass left. The interior walls were covered with wallboard with much of that gone. There is really nothing left of the ceiling although a few pieces of wallboard shows what used to be there. You look right out to the sky in many places through the ceiling. The floor is a cement pad. A blackboard runs along the south wall under the windows and there is another on the north wall that covers about 2/3 of the wall. There is wainscot on the walls. Light fixtures and wiring indicate electricity was present.

2. Owner's Contact Information:

Obe Bryn
6691 Ave NE
Towner ND 58788

Recorded By: Kathy Wilner **Date Recorded:** 9172020

NDCRS ARCHITECTURAL FORM

PAGE 4 – Site Description

Field Code Dewey District School #2

SITS# 32 PI

3. Site Area (ft²):

4. Description of Access and Site Setting:

This building is sitting on an abandoned farm site. There is a farm to the west and another south. rush Lake is SE with a slough north and farmland all directions. The building is located at the intersection of 68th St NE and 19th Ave NE. From Highway 2 at Berwick go north on Berwick Ln to 66th St NE, turn left (west) and follow the curve to the north, it becomes 19th Ave NE. Go north about 2 miles to reach the intersection with 68th St NE.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Pictures and information shared by Lorie Yocum.

Recorded By: Kathy Wilner **Date Recorded:** 9172020



West Side

Dewey district School #2

9/8/2020

Kathy Wilner

PI

South Side





East Side

Dewey District School #2

9/8/2020

Kathy Wilner

PI

North Side





Imagery ©2020 Maxar Technologies, Map data ©2020 100 ft

Feature