.4

۰.

NDCRS ARCHITECTURAL SITE FORM	
PAGE 1	
SITS# 32)

	PAGE 1	SITS# 32_	SH 794
SITE IDENTIFICATION		3113# 32 <u></u>	
Field Code Buchmann #2		hmann #2	
Map Quad <u>McClusky</u> Map Quad	Site Name 		
LTL TWP R SE LTL TWP R SE	c 27 QQQ c QQQ c QQQ c QQQ	QQ QQ	
UTMN UTME	ZONE NAD 19	027 NAD 1983	
City: McClusky ND			$2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$
Street Number: 150			$4 = W\frac{1}{2}$ 5 = NE ¹ / ₄
Street Name: 3rd Ave NE			6 = SE¼ 7 = SW¼
Urban Legal Description:			8 = NW1⁄4
SITE DATA			
Total # Architectural Features:1			
Fieldwork Date: 10/14/2012			
Reconnaissance Survey	ensive Survey		
Project Title & Supervisor: Country Schoolhouse Project			
Report Title & Author(s):			
Additional Information:			
SHSND USE Area of Significance Ecozone Area of Significance	Verified Site Non-Site		e <u>2</u>
Recorded By Kathy Wi (First Name & Last Name)	Iner	Date Recorded	1/14/2014 (mm/dd/year)

NDCRS 2009

State Historical Society of North Dakota

....

۰.

NDCRS ARCHITECTURAL SITE	FORM
PAGE 2—Feature Data	

Field Code Buchmann	#2	SITS# 32_	SH
Complete one Page	2 for each architectural	<u>feature</u> at the site.	
Architectural Feature	#		
Construction Date	Feature Type	9 Condition <u>3</u>	
Feature Date 2	Context 7	Plan Shape	5
Structural System 25	Primary Exterior	26 Style Other S	Style
Original Owner's Ethnicit	y Secondary Exter	ior Architect/Bu	ilder <u>1</u>
Other Information:			
Foundation None	·	Stories1	
Roof/Cornice_Gable			
Window Mostly gone, ver	ry little frame left and no glass		
Dating Method(s):S	timate		
Feature Preservation	Recommendation(s) (Chec	k all that apply):	
Individual nomina	ation		
Contributes to a	potential district		
✓ No nomination p	otential		
Will not contribute to a district			
Potential district-	-feature would be a contributing	element if other properties of	constitute a district
Thematic nomina	ation potential		
Component of a	historic site or landscape		
recreates origina	Il applicable choices)—a) reloca l site, orientation, landscape, & s structures; d) relocation has dar	spatial relationships; c) comp	
Historical associa	ations require further investigatio	n	
Recorded By	Kathy Wilner	Date Recorded	1/14/2014 (mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 3----Feature Data

Field Code Buchmann #2

SITS#	32	SH	

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

This is a very tired, wood framed, one room prairie school building. It is sitting on dirt and has some very serious tilt going on. I do not expect this building to stand for much longer. The shape of the school remains with an entry attached at the east end. Both the east and west endso of the building were opened up for access with equipment. On the east end there is an opening about the size of a garage door and on the west endd they installed a sliging door that opens most of that well....hence the lean! I doublt there is much holding it up anymore. The roof of the main body is mostly board lumber with remnants of asphalt shingles. The boards at the west end appear to be mostly broken off where they extended beyond the wall. The east end held up a bit better. The entry roof is half hip roof and the asphalt shingles here appear to be intact with metal ridge caps running down the two seams.

The walls are 6 inch lap siding with 4 inch corner trim boards, all without any paint left. There is a bank of four windows on the south side and little remains of the frame work and none of the glass. There is a small window on the south side of the entry, looks like a replacement, slider window. Another smaller opening to the north side of the entry might have been a fuel door. A crooked wooden door can be see on the east side, very likely the entry door. Inside the building there is some remnants of plaster over lathe, wainscoting can be seen on some segments of the walls. The entry walls are beadboard where the wall wasn't removed. Tongue and groove flooring can be seen under the rubble and much of it has heaved. There is little left of the ceiling, some lathe, a few pieces of wall board and electric light fixtures, indicating electricity was present.

Measurements of the building are 18 feet 8 inches north to south and 30 feet 2 inches east to west.

Recorded By Kathy Wilner Date Recorded 1/14/2014 (First Name & Last Name) (mm/dd/year)

 \mathbf{x}_{i}

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Buchmann #2

SITS# 32 _____ SH

Complete one Page 4 for the entire site.

2. Owner's Contact Information:

Renter: Lyle Buchmann	Owner: Tracy Hoherz
150 3rd Ave NE	513 N Miller LN
McClusky ND 58463	Las Vegas NV 89149

3. Access (to rural areas):

From McClusky, Highway 200 drive 2 miles west to 3rd Ave NE. Turn left (south) and drive about 3 miles and the farm is on the east side of the road.

4. Site Area (ft²):

5. Description of SETTING:

This building sits in a farm yard with rolling pastures around the farm. There is a slough to the west.

Recorded By Kathy Wilner Date Recorded 1/14/2014
(First Name & Last Name) (mm/dd/year)

٠.

۰.

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Buchmann #2

SITS# 32_____SH___

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By Kathy Wilner Date Recorded 1/14/2014
(First Name & Last Name) (mm/dd/year)



South Side

Buchmann #210/14/2012Tracy Stein/Kathy WilnerSH



West Side



East Side

Buchmann #2

10/14/2012

Tracy Stein/Kathy Wilner

SH



North Side



- 53 -