NDCRS ARCH	HITECTURAL SITE FORM	
Field Code Wild Rose School	PAGE 1 SITS# 32 ^{[SK} _/;	121
SITE IDENTIFICATION		32
Map Quad Dickinson South	Site Name Wild Rose School	
Map Quad	Site Name	
LTLTWP R SEC LTLTWP R SEC	14 QQQ QQ 5 C QQQ QQ QQ C QQQ QQ QQ C QQQ QQ QQ C QQQ QQ QQ	Q5 Q Q
NAD 1983, UTM 5181912 N NAD 1983, UTM 662217 E	ZONE 13N	Subsection: $1 = N\frac{1}{2}$
City: Dickinson		2 = E½ 3 = S½
Street Number: 4426		4 = W½ 5 = NE¼
Street Name: 115th Ave SW		6 = SE¼ 7 = SW¼
Urban Legal Description:		8 = NW¼
SITE DATA		
Total # Architectural Features: 1		
Fieldwork Date: 6/13/2018		
Reconnaissance Survey 🖉 Inte	ensive Survey	
Project & Principal Investigator: Country Schoolhouse Project		
Report Title & Author(s):		
Contracting firm or Agency completing the fo	rm:	
Additional Information:		
Area of Significance Ecozone Area of Significance Ecozone	2.3 Verified Site CR Type	e 2
Recorded By Kathy Wilner	Date Recorded	2019
(First Name & Last Name)		(mm/dd/year)

	CHITECTURAL SIT	T 1 / T 1 7 7 7 7 7 7 1	
Field Code Wild Rose School		SITS# 32	
Complete one Page 2 for each an	rchitectural feature at	the site.	
Architectural Feature # 1			
Construction Date F	eature Type X 9	Condition 6	
Feature Date 3	Context X 7	Plan Shape	
25	Primary Exterior 26	Style Other Style	
	Secondary Exterior <u>N/A</u>	Architect/Builder	
Other Information:			
Foundation Poured Concrete		Stories1	
Roof/Cornice Hip roof with a decorative, g	able above the entry		
Window Double hung, glass			
Dating Method(s):			
Feature Preservation Recommenda	tion(s) (Check all that a	pply):	
Individual nomination			
Contributes to a potential district			
No nomination potential			
Will not contribute to a district			
Potential district—feature would b	e a contributing element if o	ther properties constitute a distr	rict
Thematic nomination potential			

Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

_____Historical associations require further investigation

Recorded By	Kathy Wilner	Date Recorded 1/21/2019	
	(First Name & Last Name)	(mm/dd/year)	

NDCRS ARCHITECTURAL SITE FORM

Field Code Wild Rose School

SITS# 32 SK

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feather is a one room prairie school on concrete blocks and a few sections of poured concrete. This school was moved to this location to be located at the north side of a farm yard. It is being used for storage. The roof has some wood shakes as well as several pieces of metal sheeting to repair holes in the roof. There is metal capping with finials at the hip roof peak as well as the decorative, peaked addition above the entry door. Also on top of this decorative piece is the remains of the cupola. The soffits are closed with beadboard. There is no evidence of a chimney. The building measures 22 feet north to south and 30 feet east to west.

A frieze board runs under the eaves on all four sides of the school. The remainder of the siding is 6 inch wood lap with 4 inch corner trim. Also at the corners are metal corners that measure about 3 feet in height, added to protect the school from racoons and other climbing varmints. At the bottom of the siding is a skirting board with water table.

There is a broken wood door with a windows at the top. An enclosed transom is above the door. The entry is inside the school with coatrooms opening off to the sides of the entry. 5 panel wood doors lead from the entry into the coat rooms as well as the main room of the school and they are in great shape. The wood work around the doors also looks very good. There are two windows faceing east, either side of the entry door. Small, double hung with glass. On the south side of the school is a bank of 6 windows, double hung with glass. Some of the windows have a protective sheet of glass over them. There are two more shuttered windows on the west wall.

The walls and ceiling in the school are lathe and plaster. The plaster is falling away from the walls as well as the ceiling. The floor is tongue and groove hardwood. There is a blackboard on the north wall, wainscot in most of the school and no signs of electricity.

ecorded By	Kathy Wilner	Date Recorded 1/21/2019
	(First Name & Last Name)	(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Wild Rose School

SITS# 32^{SK}

Complete one Page 4 for the entire site.

2. Owner's Contact Information: Wayne Fisher 4451 115th Ave SW Dickinkson ND 58601

3. Access (to rural areas):

Go 5 miles south of Dickinson on Highway 22 to 44th St SW. Turn right (west) and drive 4 miles to 115th Ave SW, turn left and drive 1/4 mile south to the farm on the right.

4. Site Area (ft²): _____

5. Description of SETTING:

The school is sitting at the north edge of a farm yard. There are bins and buildings to the south. All other directions are farm fields with another farm in the distance to the west.

Recorded By	Kathy Wilner	Date Recorded 1/21/2019	1
	(First Name & Last Name)	(mm/dd/ye	ear)

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Wild Rose School

SITS# 32 SK

6. Summary of ALL Site Features & Evaluation of Significance:

7.	References/Comments:
	Kathy Wilner
	366 43rd Ave SE
	Bowdon ND 58418


Recorded By	Kathy Wilner	Date Recorded 1/21/2019	
	(First Name & Last Name)	(mm/dd/year)	




East Side

Wild Rose School6/13/2018Kathy WilnerSK

North Side






West Side

Wild Rose School

6/13/2018

Kathy Wilner

SK



South Side

Google Maps Dickin Son

Google Maps



Imagery ©2018 Google, Map data ©2018 Google 500 ft

Wayne Fisher 701- 290-2566