# NDCRS ARCHITECTURAL SITE FORM PAGE 1

Field Code IIIP-160	15-605	PAGE		ມລວ WI ດ	0170
Field Code JUP-160 SITE IDENTIFICATION	10-000		5115	# 32 WI 2	2112
Map Quad Tioga SW		Site Na	me		
Map Quad		Site Na	me		
LTLTWP F	R SE R SE	C	QQQ <u>7</u> QQQ QQQ	QQ QQ	Q <u>7</u> Q Q
NAD 1983, UTM5 NAD 1983, UTM	5348281 N 650006 E	ZONE	13N		Subsection: 1 = N <sup>1</sup> / <sub>2</sub>
City:					$2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$
Street Number:					$4 = W\frac{1}{2}$ $5 = NE\frac{1}{4}$
Street Name:	59th St NW				6 = SE½ 7 = SW½
Urban Legal Description:			_		8 = NW1⁄4
SITE DATA					
Total # <u>Architectural</u> Fea	atures:1				
Fieldwork Date:06	/13/2016				
Reconnaissance Survey	Into	ensive Surve	ey <u> </u>		
Project & Principal Invest West White Earth.					
Report Title & Author(s): West White Earth WAWS and Williams Counties, N Chris M. Rohe	•	nsion: Class	III Cultural Res	source Inventory	, Mountrail
Contracting firm or Agence	cy completing the fo	orm:			
Juniper, LLC Additional Information:					
School house, collapsed	structure, depress	sion, concrete	e pad, metal fra	mes.	
SHSND USE Area of Significance 2 Area of Significance 3 Area of Significance	Ecozone	21	Verified Site	1 CR Ty	/pe <u>2</u>
Recorded By	Kaelyn Ol	son	Date	Recorded	06/13/2016
(First Nam	e & Last Name)				(mm/dd/year)

(mm/dd/year)

# NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code JUP-16015-605		SITS# 32_WI
Complete one Page 2 for eac	ch architectural feature	at the site.
Architectural Feature #1	_	
Construction Date	Feature Type9	
Feature Date7	Context 7	Plan Shape 5
Structural System 25	Primary Exterior <u>26</u>	Style Plain Residential
Original Owner's Ethnicity	Secondary Exterior N/A	Architect/Builder
Other Information: School		
Foundation Concrete		Stories
Roof/Cornice_Gable		
WindowOriginal frame, most original		
Dating Method(s): Professional estim		
Thematic nomination potential  ✓ Component of a historic site of the Moved (specify all applicable recreates original site, oriental with neighboring structures; of the Moved (specify all applicable recreates original site, oriental with neighboring structures; of the Moved (specify all applicable recreates original site, oriental with neighboring structures; of the Moved (specify all applicable recreates).	trict  tt  uld be a contributing element  al  or landscape  choices)—a) relocation occur ation, landscape, & spatial rela d) relocation has damaged elig	if other properties constitute a district  red within a historic period; b) ationships; c) compatible in context
✓ Historical associations require	e further investigation	
Recorded ByKael	lyn Olson D	ate Recorded

(First Name & Last Name)

## NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code JUP-16015-605	SITS# 32 WI

#### Complete a Page 3 for each feature.

### 1. Feature Description, Integrity, Eligibility:

Feature 1 is a school. Feature 1 measures approximately 40 feet north/south and 25 feet east/west. Feature 1 has a concrete foundation and front steps. The concrete predominantly consists of well sorted gravels. There is a basement walk-in on the eastern side of the foundation that appears to have been patched or lined with a concrete with poorly sorted gravels and a tan cement. The parts of the basement that are visible have concrete walls and flooring. The basement is divided into two rooms, a boiler room and a furnace room. There are three boarded windows to the basement on the eastern side of the foundation, two on the northern side, and four on the western side. The main part of the school has horizontal wooden siding with vertical wooden corner protectors. Feature 1 is painted white, and the paint is in fair condition. Feature 1 has been wired for electricity. The door and the concrete steps leading up to it are on the south side of the building. There are a single hung window, a round window, and a window composed of glass blocks set into the southern elevation. The round window is set into a gabled dormer centered over the entryway. The doorway is original, but the door is no longer in place. In the eastern elevation are one single hung window and two large square areas that cover almost the entirety of the eastern elevation. There is a wooden box just under the eaves on the eastern elevation. Feature 1 has a gable roof with wooden tiles and a metal roof ridge. There is a brick chimney on the western edge of the roof ridge; it is in poor condition. There is a metal pedestal attached to the top of the dormer. There is a cupola that has fallen to the ground next to the front steps of the school. The cupola has a sheet metal roof that forms a peak; the cupola is painted white. A wooden door is lying on the ground next to the steps.

Feature 1 is in fair condition. Feature 1 maintains aspects of structural integrity, including workmanship and materials, and shows no signs of having been moved. Feature 1 maintains a rural, agricultural setting. Further work is recommended to better understand the relationship of Feature 1 to other historic sties in the area.

Independently, Feature 1 is unevaluated for the National Register of Historic Places. Feature 1 does not meet Criterion D, having significant information potential. Further work is recommended to better understand eligibility under Criteria A, B and C, association with a significant event, association with a significant person, and having significant design.

Recorded By_	Kaelyn Olson	Date Recorded	06/13/2016
,	(First Name & Last Name)		(mm/dd/year)

# NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code JUP-1	6015-605	SITS# 32	WI
Complete one Pa	nge 4 <u>for the entire s</u>	<u>site</u> .	
Owner's Contact Ir     Private	nformation:		
3. Access (to rural are	eas):		
Highway 2 and tra	vel one mile. Turn left (so	ND Highway 40/104th Ave NW. Turn routh) onto 105th Ave NW and travel five The site is on the right (north).	_ , ,
4. Site Area (ft²):	26,264		
surrounding area i The are has been site. Historic Site	05 is located in a predoming a mix of pasture and croportion of pasture and croportion of pasture and croportion of pasture and the state of the sta	nantly agricultural area south of Tioga, op land, and the site has agricultural fier oil exploration. There is a well pad 30 feet northwest of Site JUP-16015-602; only small shifts in the terrain, and so	elds on three sides. 00 feet west of the the relationship
Recorded By	Kaelyn Olson	n Date Recorded	06/13/2016 (mm/dd/year)

Field Code JUP-16015-605

SITS# 32 WI

# NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

	(First Name & Last Name) (mm/dd/ye	ar)
Re	Recorded By Nate Recorded06/13/20	
7.	. References/Comments:	
	significant information potential. Further work is recommended to better understand the eligibility site, notably Feature 1, under Criteria A, B and C, association with a significant event or person having significant design.	ty of the
	Site JUP-16015-605 is unevaluated for the NRHP. Site JUP-16015-605 does not meet Crit	erion D,
	Site JUP-16015-605 is in fair condition. The features of the site maintain their associations each other and a rural setting. Feature 1, the school, maintains aspects of structural integrity su workmanship and materials. Features 2-6 lack significant aspects of structural integrity.	
	Feature 1 is a school. Feature 2 is a metal frame for a clothes line. Feature 3 is a concrete Feature 4 is a collapsed sign. Feature 5 is a square depression. Feature 6 is a collapsed structure 5 are described in the following historic site description.	•
6.	. Summary of ALL Site Features & Evaluation of Significance:	

Field Code: <u>JUP-16015-605</u> SITS#: <u>32WI</u>




Figure 3: Sketch map of Site JUP-16015-605.

Recorded By Kaelyn Olson Date Recorded 6/13/2016 (First Name & Last Name) (mm/dd/year)




Figure 4: Overview of Feature 1 facing northeast.



Figure 5: Overview of Feature 1 facing southeast.

**Field Code:** <u>JUP-16015-605</u> **SITS#:** <u>32WI</u>



Figure 6: Overview of Feature 1 facing southwest.



Figure 7: Overview of Feature 1 facing northwest.



**Figure 8:** Overview of the furnace in the basement of Feature 1.



**Figure 9:** Overview of the boiler in Feature 1.

**Field Code:** <u>JUP-16015-605</u> **SITS#:** <u>32WI</u>



Figure 10: Close up of the fallen cupola next to Feature 1.



Figure 11: Overview of Feature 2, the clothes line frame facing southwest.