NDCRS 2009

| NDCRS AI | RCHITECTURAL S PAGE 1 | ITE FORM | |
|---|---|--------------------------|--|
| | PAGE | SITS# 32_G | v346 |
| SITE IDENTIFICATION | | | |
| Field Code Roen School | Site Name | en School ndin School | |
| Map Quad_ <u>Alpha</u> Map Quad | Site Name <u>20</u> | nain school | |
| LTL TWP38 R104 LTL TWP R LTL TWP R LTL TWP R | SEC 33 QQQ 6 SEC QQQ SEC QQQ SEC QQQ | QQ | Q <u>6</u> Q Q Q |
| UTM 5174879 UTM 591815 | _N ZONE <u>13</u> _E NAD 1923 | N NAD 1983 | Subsection: $1 = N\frac{1}{2}$ |
| City: Sentinel Butte | | | $2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$ |
| Street Number: 4761 | | | $4 = W1/_{2}$ 5 = NE1/_{4} |
| Street Name: County Road 11 | | | 6 = SE¼ 7 = SW¼ |
| Urban Legal Description: | | | 8 = NW1⁄4 |
| SITE DATA | | | |
| Total # Architectural Features: | 1 | | |
| Fieldwork Date: 6/22/2016 | | * | |
| Reconnaissance Survey 🖌 | Intensive Survey | | |
| Project Title & Supervisor: Country Schoolhouse Project | | | |
| Report Title & Author(s): | | | |
| Additional Information: | | | 2 |
| SHSND USE Area of Significance Ecozone Area of Significance Ecozone | Verified Site Non-Site | CR Type | 2 |
| | Wilner D | ate Recorded | 1/28/2017 |
| (First Name & Last Name) | | | (mm/dd/year) |

NDCRS 2009

| NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data | | | |
|--|------------------------------|---------------------|--|
| Field Code Roen School | | SITS# 32_GV | |
| Complete one Page 2 for each | architectural feature at the | e site. | |
| Architectural Feature #1 | | | |
| Construction Date2 | Feature Type <u>9</u> | Condition 6 | |
| Feature Date | Context_7 | Plan Shape <u>5</u> | |
| Structural System 25 | Primary Exterior <u>26</u> | Style Other Style | |
| Original Owner's Ethnicity | Secondary Exterior | Architect/Builder | |
| Other Information: Foundation_Concrete | | Stories 1 | |
| Roof/Cornice Gable, shed on the south | | Stories | |
| | | | |
| Window Double hung, two over two, intact glass Dating Method(s): School history | | | |
| Dating Method(s): | | | |
| Feature Preservation Recommendation(s) (Check all that apply): | | | |
| Individual nomination | | | |
| Contributes to a potential district | | | |
| No nomination potential | | | |
| Will not contribute to a district | | | |
| Potential district—feature would be a contributing element if other properties constitute a district | | | |
| Thematic nomination potential | | | |
| Component of a historic site or landscape | | | |
| d Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility | | | |

____Historical associations require further investigation

| Recorded By | Kathy Wilner | Date Recorded | 1/28/2017 |
|-------------|---------------------|---------------|--------------|
| (First | t Name & Last Name) | | (mm/dd/year) |

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Roen School

SITS# 32 GV

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a concrete foundation. The gable roof of the school of covered with ribbed sheeting and the shed roof will be covered with wood shakes. There is metal capping on the roof peak with finials. The soffits are closed. There is a yellow and red brick chimney at the peak of the roof near the south end. The building measures 34 feet north to south and 20 feet east to west.

There is a wide trim board on the wall under the soffits on the south side. The siding on the south, west and east is 6 inch wood lap with 6 inch wood corner trim. The north side of the building has metal sheeting. There is a door on the north side that was put in for access at this spot. The entry, with a 5 panel wood door, is at the south side of this building. The entry also has a window opening on both the east and west sides, covered. There are two double hung, two over two, windows on the east side with intact glass and two more on the west side and these are covered. There is a blackboard on the west wall between the windows. The walls in the school are covered with lathe and plaster, the ceiling a mixture of lathe and plaster and wallboard. The floor is hardwood with tile over it. The building is used for storage. Light fixtures suggest electricity.

This school was built in 1912 and operated until 1944, started out as Lundin School and when it was moved it became the Roen School.

Recorded By Kathy Wilner Date Recorded 1/28/2017
(First Name & Last Name) (mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Roen School

SITS# 32_GV_____

Complete one Page 4 for the entire site.

2. Owner's Contact Information:

Max Schmeling 4761 County Road 11 Sentinel Butte ND 58654

3. Access (to rural areas):

From Sentinel Butte, drive south on County Road 11 13 miles to see the farm on the west side of the road.

4. Site Area (ft²):

5. Description of SETTING:

This building is sitting in a farm site with bins south, equipment around the school, several other buildings north and west. Crop land all direction around the farm.

Recorded By Kathy Wilner Date Recorded 1/28/2017
(First Name & Last Name) (mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Roen School

SITS# 32_GV_____

6. *Summary of ALL* Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By Kathy Wilner Date Recorded

1/28/2017 (mm/dd/year)




North Side

| Roen School | 6/22/2016 | Kathy Wilner | GV |
|-------------|-----------|--------------|----|
| | | | |



East Side



West Side

Roen School

6/22/2016


Kathy Wilner

GV

7/7/2016

bing maps

| Notes | | |
|--------------|--|--|
| Roen School | | |
| 6/22/2016 | | |
| Kathy Wilner | | |
| GV | | |
| | | |



bing

© 2016 Microsoft Corporation © 2016 HERE

