**NDCRS 2009** 

State Historical Society of North Dakota

· · · ·

NET INCLUSION AT A			SIT	S# 32 BO 9	06
SITE IDENTIFICATION					
Map Quad		Site	Name Hammon	d School	
Map Quad		Site	Name		
LTL TWP	R	SEC	QQQ	QQ	Q
	R	SEC	000	00	Q
TL_TWP	_ R	SEC	_ QQQ	QQ	Q
_TL TWP _TL TWP _TL TWP _TL TWP	_ R	SEC	_ QQQ	QQ	Q
UTM		N	ZONE		Subsection
UTM UTM		E	NAD 1927	NAD 1983	$1 = N\frac{1}{2}$
City:					$2 = E\frac{1}{2}$
City					$3 = S\frac{1}{2}$ $4 = W\frac{1}{2}$
Street Number:					5 = NE¼
Street Name:					6 = SE¼ 7 = SW¼
					$8 = NW^{1/4}$
Urban Legal Description	on:				
SITE DATA Total # <u>Architectural</u>	Features:	0			
-ieldwork Date:					
Reconnaissance Surve	ey	Intensive Su	rvey		
Project Title & Supervi	isor:				
Scranton Telecom					
Ryan Howell					
Report Title & Author(s	s).				
Report Title & Author(s	5):				
Report Title & Author(s	5):				
Report Title & Author(s	5):				
Report Title & Author(s	5):				
		ire sometimo	hetween 1007 o	ad 2011	
		ire sometime	between 1997 ai	nd 2011.	
50EED		ire sometime	between 1997 ai	nd 2011.	
		ire sometime	between 1997 ai	nd 2011.	
Additional Information:	: Building lost to f	_			2
Additional Information: SHSND USE Area of Significance		_	Verified Site _		pe <u>2</u>
Additional Information: SHSND USE Area of Significance	Building lost to f	22			pe <u>2</u>
Additional Information: SHSND USE Area of Significance Area of Significance	: <u>Building lost to f</u>	22	Verified Site _		pe <u>2</u>
Report Title & Author(s Additional Information: SHSND USE Area of Significance Area of Significance Area of Significance Recorded By	Ecozone	22	Verified Site Non-Site		pe <u>2</u> 9/29/2011

State Historical Society of North Dakota

**NDCRS 2009** 

	NDCRS ARCHITECTURA PAGE 2—Feature	Data	DATE
Field Code <u>N/A</u> Complete one Page	e 2 for each architectural feat	SITS# 32 _BO_	906
Architectural Feature			
Construction Date	Feature Type	_ Condition _	
Feature Date	Context	Plan Shape	
Structural System	Primary Exterior	Style	
Original Owner's Ethnici	ty Secondary Exterior	Architect/Bu	ilder
Other Information:			
Foundation		Stories	_
Window			
Roof/Cornice			
Dating Method(s):			
Feature Preservation	Recommendation(s) (Check al	l that apply):	
Individual nomin	ation		
Contributes to a	potential district		
No nomination p	ootential		
Will not contribu	te to a district		
Potential district	feature would be a contributing ele	ment if other properties	constitute a district
Thematic nomin	ation potential		
Component of a	historic site or landscape		
recreates origina	all applicable choices)—a) relocation al site, orientation, landscape, & spati g structures; d) relocation has damag	ial relationships; c) comp	
Historical associ	iations require further investigation		
Recorded By	Mary Mitchell (First Name & Last Name)	Date Recorded_	9/29/2011 (mm/dd/year)

NDCRS 2009

## NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code N/A

SITS# 32 BO 906

### 1. *Feature* Description, Integrity, Eligibility:

This architectural site was originally recorded in 1997 by Tom Isern as a one-room school house on a poured concrete foundation. At the time it was recorded, the windows and steps were in poor condition. The building was recommended as ineligible for the NRHP.

The site was revisited in September 2011 as a part of an inventory for a proposed fiber optic installation. Upon the site revisit, it was found that the school has either been moved off the site or destroyed.

An inquiry to the Bowman Historical Society Pioneed Trails Museum yielded the information that the school was destroyed by fire. The date of the fire is not known.

Recorded By\_

Mary Mitchell

(First Name & Last Name)

Date Recorded

9/29/2011 (mm/dd/year)

State Historical Society of North Dakota

**NDCRS 2009** 

NDCRS ARCHITECTURAL SITE FORM	1
PAGE 4—SITE DESCRIPTION	UPDATE

## Field Code <u>N/A</u> Complete one Page 4 <u>for the entire site</u>.

SITS# 32 \_BO \_\_906\_\_\_

2. Owner's Contact Information:

3. Access (to rural areas):

4. Site Area (ft<sup>2</sup>):

5. Site Description:

The site was revisited in September 2011 as a part of an inventory for a proposed fiber optic installation. Upon the site revisit, it was found that the school has either been moved off the site or destroyed.

Only a slight, rectangular depression remains and it has been cultivated.

The only cultural material observed at the site were approximately six bricks near the center of the depression.

A source at the Pioneer Trails Museum indicated that the school building was destroyed by fire, but did not know the date of the fire.

Recorded By	Mary Mitchell	Date Recorded	9/29/2011	
	(First Name & Last Name)		(mm/dd/year)	
In the college to come	late a divital varian of this form; (1) Download a	any to your hard drive: (2)	Open the caved	

State Historical Society of North Dakota

NDCRS 2009

# NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

UPDATE

906

 Field Code N/A
 SITS# 32 BO

 6. Summary of All Site Features & Evaluation of Site Significance:

No standing features remain at the site. The school burned down.

7. References/Comments:

Recorded By\_\_\_\_

(First Name & Last Name)

\_\_\_\_\_ Date Recorded

9/29/2011 (mm/dd/year)

## NDCRS SITE FORM ATTACHMENTS SECTION SITS# 32BO906 UPDATE

Field Code N/A



Figure 3: 32BO906, bricks in the center of depression.




Figure 4: 32BO906, overview to the east, depression in background

	Page 1
	Field Code Sulla Site Name Harmand School March
SITE DATA	Map Quad       Serention.SW       1. Ni         Map Quad
FEATURE DATA	O.I. Feature #       O.G. Feature Type       G. Condition         O.S. Feature Date       O.G. Feature Type       G. Condition         O.S. Feature Date       O.S. Feature Type       S. Condition         O.S. Structural System **       O.S. Plan Shape *       Secondary Exterior         O.S. Structural System **       O.S. Style *       Secondary Exterior         O.S. Fieldwork Date       O.S. Plan Shape *       Secondary Exterior
SHSND USE	المعندين الم المعندين المعندين الم المعندين المعندين الم المعندين المعندين الم المعندين المعندين المعندين المعندين المعندين المع المعندين المعندين المعن المعندين المعندين المعندين المعندين المعندين المعن المعندين المعندين المعن المعندين المعندين
	Coder       LIRTTI       Date Coded       8/3/97         Reconnaissance Survey       ESURVITO       Intensive Survey         Manuscript/Report Title:       Survito       Survito         Author(s):       Ise:       Survito

NDCRS SITE FORM ARCHITECTURAL SITES Page 1


	ECTURAL SITE FORM
	age 1A
Field Code <u>SU II6</u> Feature I	Number         SITS # <u>32</u>
DESCRIP	<u>FIVE SECTION</u>
FOUNDATION STORIES	ROOF TYPE / CORNICE
powed concrete 1	anbie
WINDOW CONDITION	DATING METHOD
	professional estimate
PRESERVATION RECOMMENDATION (c	
1) Individual Nomination 2)	Contributes to a potential district
3) $\_$ No nomination potential 4)	Will not contribute to district
5) Potential district not known at this tim	ne: feature would be a contributing element if
neighboring properties constitute a dis	
6) Thematic nomination potential 7	) Component of historic site/landscape
8) Feature has an important physical, spa	
relationship to the site/complex/farmst	ead
9) Moved: A) relocation occurred within	historic period. B) recreates original site,
orientation, landscape and spatial chara	acteristics. C) compatible in context with
neighboring structures. D) relocation l	has damaged eligibility.
10) Request comparative study of neight	poring properties
11) IT staniant and side in a manuful further	

11) \_\_\_\_\_ Historical associations require further investigation

#### DESCRIPTION/INTEGRITY/ELIGIBILITY

This schoolhouse is known as Hammond School No. 2. This one-room school is a wood frame building on a foundation of poured concrete. Its gable roof, aligned north and south, is covered with wood shingles. It exterior walls are covered with horizontal wood siding. There is a brick chimney at the north end of the gable. Built onto the front (south) side of the school is a hip roof entryway that extends the length of the south side. The school has three tall windows on the north side and three tall windows on the east side. These are in poor condition. There are smaller windows on the east and south side of the entryway. Access to the entrance is on the south side by wooden steps that are collapsing.

The building lacks associations or distinction sufficient for National Register consideration.



a second design of the second s

SITE 32

Photographic Coverage, Historic Architectural Survey of Bowman County, 1997								
Roll CC	Frame	4	Site SU	116	Feature	Date 8/	3 View from ≤	W
Subject:	Sch	0010	house					



Roll CC	Frame	5	Site SU	116	Feature	Date	8/3	View from	NE
Subject:	Sch	0010	louse						

