NDCRS 2020

NDCRS ARCHITECTURAL FORM DAGE 1

11	D		Λ.	-	
υ		U,	А		

		FAGE		UPDATE
Field Code			SITS# 32 KD	108
Map Quad <u>Tappen SE</u> Map Quad <u>Tanner #1</u>		Site Name		
Map Quad Tanner #1		_ Site Name		
LTL T. <u>138</u> N., R LTL T N., R LTL T N., R LTL T N., R	W., Sec W., Sec	QQQ of the QQ of the QQ	of the Q of the Q	1 = N½ 2 = E½
NAD <u>1983</u> UTM NAD UTM City:	457693	_		5 = NE¼ 6 = SE¼ 7 = SW¼
				8 = NW¼
Street Number:				
Street Name: 43rd Ave) SE			
Urban Legal Description:				
Total Number of Archited	ctural Features:			
Fieldwork Date: 05/	27/2023			
Reconnaissance Survey		Intensive Survey	• 	
	• • • • •			
Project & Principal Invest	-			
IEA KEM RUS 376 Tappe	n South			
Contracting Firm or Agen	ov Completing the E	orm.		
6 6	, , ,	onn.		
Metcalf Archaeological Co	insultants, Inc.			
Additional Information:				
SHSND USE Component Component Component		Verified Site	CR Type	
· · · · · · · · · · · · · · · · · · ·				
Recorded By:	Mike Jacks	on Date	e Recorded:	05/27/2023

NDCRS ARCHITECTURAL FORM PAGE 2 – Feature Data

U	P	DA	١	E
	-	_		_

SITS#	32	KD	108
3113#	JZ		100

Field Code	SITS# 32 KD 108
Complete one Page 2 for <i>each</i> architectural feature at the site.	
Architectural Feature #1	
Construction Date	
Feature Date	
Structural System	
Original Owner's Ethnicity	
Feature Type	
Context	
Primary Exterior	
Secondary Exterior	
Condition Fair	
Plan Shape	
Style	
Architect/Builder	
Foundation Storie	ies
Roof/Cornice	
Window No remaining glass, most windows boarded over	
Dating Method(s)	
Miscellaneous Information	
Feature Preservation Recommendation(s) (Check all that apply	y):
Individual nomination	
Contributes to a potential district	
No nomination potential	
Will not contribute to a district	
Potential district—feature would be a contributing element if	if other properties constitute a district
Thematic nomination potential	
Component of a historic site or landscape	
a, b, c, Moved (specify all applicable choices)—a) relocation occurr d site, orientation, landscape, and spatial relationships; c) con relocation has damaged eligibility	
Historical associations require further investigation	

listorical associations require further i vesigalio

Recorded By:	Mike Jackson	Date Recorded:	05/27/2023

NDCRS ARCHITECTURAL FORM

PAGE 3 – Feature Data

UPDATE

SITS# 32 KD 108

Complete one Page 3 for each architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

Field Code

This feature is the Tanner #1 school, originally recorded in 2009 by Lorna Meidinger. Metcalf revisited the site in 2023 as part of the current project and noted changes in the condition of this feature. Since the previous recording, the building has lost additional asphalt shingles and wood shingles are missing from the north-facing roof slope, revealing wood decking underneath. There is no remaining glass in the uncovered windows. On the interior, plaster has fallen from the walls and the oak flooring has buckled and broken in several places. The building retains its stove and heat shield.

Although the condition has slightly diminished since its last recording, the feature continues to be eligible for listing on the NRHP as part of a thematic nomination.

2. Owner's Contact Information:

Recorded By:

Mike Jackson

Date Recorded: 05/27/2023

NDCRS ARCHITECTURAL FORM PAGE 2 – Feature Data

	חי	Δ	Т	F
	_		•••	

CITC# 22 KD 108

Field Code	SITS# 32 KD	108
Complete one Page 2 for each architectural feature at the s	site.	
Architectural Feature # 2		
Construction Date		
Feature Date		
Structural System		
Original Owner's Ethnicity		
Feature Type		
Context		
Primary Exterior		
Secondary Exterior		
Condition Destroyed		
Plan Shape		
Style		
Architect/Builder		
	Stories	
Roof/Cornice		
Window		
Dating Method(s)		
Miscellaneous Information		
Feature Preservation Recommendation(s) (Check all that a	pply):	
Individual nomination		
Contributes to a potential district		
No nomination potential		
Will not contribute to a district		
Potential district—feature would be a contributing eleme	ent if other properties of	constitute a district
Thematic nomination potential		
Component of a historic site or landscape		
Moved (specify all applicable choices)—a) relocation of site, orientation, landscape, and spatial relationships; crelocation has damaged eligibility		
Historical associations require further investigation		

NDCRS ARCHITECTURAL FORM

PAGE 3 – Feature Data

UPDATE

SITS# 32 KD 108

Field Code _____

Complete one Page 3 for each architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

Feature 2 is an outhouse, located at the northwest corner of Feature 1. The feature was originally recorded in 2009 by Lorna Meidinger. Metcalf revisited the site in 2023 and noted a condition change to this feature. The outhouse has completely collapsed and the exterior is weathered.

The feature does not contribute to the significance of the school house.

2. Owner's Contact Information:

Recorded By: Mike Jackson

Date Recorded: ____ 05/27/2023

NDCRS ARCHITECTURAL FORM PAGE 4 – Site Description

UPDATE

SITS# 32 KD 108

3. Site Area (ft²):

- 4. Description of Access and Site Setting:

Field Code _____


5. Summary of ALL Site Features and Evaluation of Significance:

This site is the Tanner #1 schoolhouse that was originally recorded in 2009 by Lorna Meidinger. Metcalf revisited the site in 2023 as part of the current project and noted changes to the condition of both Feature 1 and 2. The schoolhouse continues to retain sufficient integrity to convey its historic associations and remains eligible for listing on the NRHP under a thematic nomination.

6. References/Comments:

Field Code

SITS# <u>32KD108 update</u>




Map 1: The location of the site depicted on the USGS 7.5' Tappen SE (1952) quadrangle map.


Recorded By: Mike Jackson

Date Recorded: 5/27/2023

Field Code

SITS# 32KD108 update





Recorded By: Mike Jackson

Date Recorded: <u>5/27/2023</u>

Field Code

SITS# 32KD108 update



Figure 2: Feature 1, east elevation, view west (MJ1_8, 5/27/2023).



Figure 3: Feature 1, south and east elevations, view northwest (MJ1_9, 5/27/2023).

Recorded By: Mike Jackson

Date Recorded: 5/27/2023

Field Code

SITS# <u>32KD108 update</u>



Figure 4: Feature 1, west and south elevations, view northeast (MJ1_13, 5/27/2023).



Figure 5: Feature 1, north and west elevations, view southeast. Note Feature 2 in foreground (MJ1_17, 5/27/2023).

Recorded By: Mike Jackson

Date Recorded: 5/27/2023

Field Code _____

SITS# <u>32KD108 update</u>



Figure 6: Feature 1, east and north elevations, view southwest (MJ1_21, 5/27/2023).



Figure 7: Feature 2, view southeast (MJ1_35, 5/27/2023).

Recorded By: Mike Jackson

Date Recorded: <u>5/27/2023</u>

NDCRS 2009

State Historical Society of North Dakota

NDCRS ARCH	IITECTURAL SITE FORM PAGE 1
Field Code	
SITE IDENTIFICATION	
Map Quad <u>Tappen SE</u> Map Quad	Site Name <u>Tanner #1</u>
	; <u>18</u> QQQ <u>5</u> QQ <u>5</u> Q <u>6</u> ; QQQ QQ Q
LTL TWP R SEC	; QQQ QQ Q
LTL TWP R SEC	; QQQ QQ Q
UTM <u>457696</u> N UTM <u>5179633</u> E	ZONE <u>14N</u> Subsection:
UTM5179633E	NAD 1927 NAD 1983 _✓ 1 = N½ 2 = E½
City:	
Street Number:	4 = W½ 5 = NE¼
	6 = SE¼
Street Name: <u>43rd Ave SE</u>	7 = SW¼ 8 = NW¼
Urban Legal Description:	
SITE DATA Total # <u>Architectural</u> Features:2	
Fieldwork Date: <u>12/17/2009</u>	
Reconnaissance Survey Inter	nsive Survey 🖌
Project Title & Supervisor:	
Country Schoolhouse Project	
Report Title & Author(s):	
Additional Information:	
Additional Information:	
SHSND USE Area of Significance <u>2</u> Ecozone <u>1</u>	9 Verified Site 1 CR Type 2
Area of Significance Ecozone	Non-Site
Area of Significance Ecozone	
Recorded By Lorna Meid (First Name & Last Name	

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code	ge 2 <u>for <i>each</i> architectural</u>	SITS# 32 <u>KD</u> feature at the site.	
Architectural Featu			
Construction Date		9 Condition <u>5</u>	
Feature Date 3			
Structural System 25	Primary Exterio	r <u>26</u> Style <u>Other S</u>	Style
Original Owner's Ethni	city Secondary Exte	rior Architect/Bui	lder
Other Information:			
According to Iszler, the built several years ear	e school was built by 1905 when h lier.	is grandfather started school.	It may have been
,			
Foundation concrete		Stories <u>1</u>	n an
WindowMostly dbl-hu	ng, vandals recently broke most o	f the glass panes	
Roof/Cornice hip			
Dating Method(s): ora	l history		
Feature Preservatio	on Recommendation(s) (Cheo	k all that apply):	
Individual nom	ination		
Contributes to	a potential district		
No nomination	potential		
Will not contrib	ute to a district		
Potential distri	ct—feature would be a contributing	g element if other properties c	onstitute a district
✓ Thematic nom	ination potential		
Component of	a historic site or landscape		
a, precreates origi	/ all applicable choices)—a) reloca nal site, orientation, landscape, & ng structures; d) relocation has da	spatial relationships; c) compa	
Historical asso	ciations require further investigation	on	
Recorded By	Lorna Meidinger (First Name & Last Name)	Date Recorded_	12/21/2009 (mm/dd/year)
Instructions to complete a	a digital version of this form: (1) Down	oad a copy to your hard drive. (2) Open the saved

Field Code_

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

SITS# 32 KD

1. Feature Description, Integrity, Eligibility:

Tanner #1 has identical entrances on the north and south ends of the east facade with entry into coatrooms. Iszler believed they were originally built for separate entrances for boys and girls but Haadem said in later years, one entrance was locked to create a washroom and only one entrance was used as such. The identical dimensions and design of the coatrooms suggest the original intent was separate entrances. A decorative molding serves as the fascia. There are six double-hung windows on the east facade providing light into the classroom while the west wall had a small library and a coal room on either side of the stove (still with its shield). Each coatroom also had a large window on the west and a number of storm windows are stored in those areas. A few desks are still in the building and lightweight voting booths were built at the north end of the classroom. In addition to breaking the glass from the windows, vandals also severely damaged the voting booths. Oak flooring, beadboard wainscot, chalkboards, and plaster walls are still the interior materials. Electricity was added at this location and the chimney has been rebuilt with chimney block. Wood shingles can be seen in locations where the asphalt shingles are missing.

Tanner #1 has been moved twice. The first time was between 1910 and 1926 to a location 1.5 miles south and 1 mile east of its present location. It ceased being a school ca 1958 and was moved to its present location in 1962 to serve as a voting hall. The first move did not damage the buildings eligibility as the basic setting and function were the same as when it was originally built. The second move damages eligiblity some as the new function of the building was not education. The building, did, however, retain its design, materials, and basic rural setting despite the change of function. Haadem said the building is oriented in the same direction as it was before the second move. It is also a more unusual surviving schoolhouse with its double entrance and coatrooms and is eligible for the National Register of Historic Places as part of a theme nomination.

Recorded By	Lorna Meidinger	Date Recorded	12/21/2009
	(First Name & Last Name)		(mm/dd/year)
Instructions to complet	e a digital version of this form: (1) Downlo	ad a copy to your hard drive; (2)	Open the saved

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code Complete one Page 2	for each architectural featu	SITS# 32 <u>KD</u> _ <u>ire</u> at the site.	19
Architectural Feature #	2		
Construction Date	Feature Type <u>50</u>	Condition 5	ti da anti-
Feature Date 8	Context 18	Plan Shape <u>5</u>	
Structural System 25	Primary Exterior <u>26</u>	Style_Utilitariar	1
Original Owner's Ethnicity	Secondary Exterior	Architect/Build	ler
Other Information:			
Foundation none		Stories1	- 74
Window			
Roof/Cornice shed			
Dating Method(s): oral histo	ory		
Feature Preservation Re	ecommendation(s) (Check all	that apply):	
Individual nominatio	n		
Contributes to a pot	ential district		
✓ No nomination pote	ntial		
✓ Will not contribute to	o a district		
Potential district—fe	eature would be a contributing elem	ent if other properties co	nstitute a district
Thematic nominatio	n potential		
Component of a his	toric site or landscape		
recreates original si	applicable choices)—a) relocation c te, orientation, landscape, & spatia uctures; d) relocation has damaged	l relationships; c) compat	
Historical associatio	ons require further investigation		
Recorded By	Lorna Meidinger st Name & Last Name)	_ Date Recorded	12/21/2009 (mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code

SITS# 32 KD

1. Feature Description, Integrity, Eligibility:

A small wooden outhouse is located at the northwest corner of the schoolhouse. It has been tipped over and lays a few feet from where it was located previously. This outhouse was built after the school was moved to this property in 1962 to serve voters.

Recorded B	У	
------------	---	--

Lorna Meidinger (First Name & Last Name)

Date Recorded_

12/21/2009 (mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code _____ Complete one Page 4 <u>for the entire site</u>.

SITS# 32 KD

2. Owner's Contact Information:

3. Access (to rural areas):

Go east of Tappen on I-94 to the Pettibone Exit. Go south on 42nd Ave SE for 3 miles, east on 40th St SE, and south on 43rd Ave SE for 4.5 miles.

4. Site Area (ft²):

5. Site Description:

The school is just west of 43rd Ave SE on a small hill with open land surrounding the building. The area does have a wire fence along the property lines.

Recorded By_	Lorna Meidinger						Date Recorded_				12/21/2009			
(First Name & Last Name)								• .				(mm/dd/year)		

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code ______ SITS# 32 <u>KD</u> 6. *Summary of All* Site Features & Evaluation of Site Significance:

The school building retains a high level of integrity in all aspects except location and is eligible for the National Register. The outhouse is non-historic structure in fair condition and does not contribute to the historic significance of the schoolhouse.


7. References/Comments:

Norlyn Iszler, personal interview, 17 December 2009. Tilman Haadem, personal interview, 17 December 2009.

Recorded By___

Lorna Meidinger (First Name & Last Name) _____ Date Recorded_

12/21/2009 (mm/dd/year)



1. 1. 1

NDCRS SITE FORM ATTACHMENTS SECTION

Field Code

SITS# 32 KD



Feature 1 east 1

Feature 1 north J



Date Recorded 12/21/2009 (mm/dd/year) Field Code

SITS# 32 KD



Date Recorded 12/21/2009 (mm/dd/year)



Feature 1 interior east wall 🏫

Feature 1 interior west wall \downarrow







Feature 1 into library \uparrow F1 interior south wall \checkmark



Recorded By Lorna (First I

Field Code **SITS# 32 KD** Back Row - Carl Job Perry Robinson tracher, GM Iszler, Nellie Haaden, Ido Haaden, Denia Haadem, Christina Graf Second Row - John Job, John Iszler, Sam Graf, Henry Haadem, Fred Job, Ray Haadem, Pauline Mueller, Lizzie Job, Emma Iszler Mary Mueller First Four Gottlieb Job Edward Job, David Job Bert Handen, Anton Isaler

Tanner#1 ca 1905



Feature 1 inside northeast corner, ca 1905 Recorded By Lorna Meidinger (First Name & Last Name)

Date Recorded 12/21/2009 (mm/dd/year)