NDCRS ARCHITECTURAL SITE FORM PAGE 1

	70E		
Field Code MAC Town-1	SITS# 32 MH x 285		
SITE IDENTIFICATION			
Map Quad Towner NW	Site Name Poplar Grove School		
Map Quad	Site Name		
LTL TWP158 R76 SEC	22 QQQ <u>5</u> QQ <u>5</u> Q <u>6</u>		
LTL TWP R SEC			
	QQQ QQ Q		
	QQQ QQ Q		
11TM 5372016 N	ZONE 14N Subsection:		
UTM 5372016 N UTM 392840 E	2ONE 14N Subsection: NAD 1927 ✓ NAD 1983 1 = N½		
OTIVI	NAD 1927 $\sqrt{}$ NAD 1983 $_{}$ 1 = N½ 2 = E½		
City:			
	$4 = W\frac{1}{2}$		
Street Number:	· · · · · · · · · · · · · · · · · · ·		
Chroat Name:	6 = SE½		
Street Name:			
Urban Legal Description:	8 = NW1/4		
SITE DATA			
Total # <u>Architectural</u> Features:1			
Fieldwork Date:10/19/2012			
Tieldwork Bate.			
Reconnaissance Survey <u>✓</u> Intens	sive Survey		
Project Title & Supervisor:			
SRT Communications Towner FTTP Exchange	je		
William Bluemle			
Report Title & Author(s):			
SRT Communications Towner FTTP Exchange	ge : A Class II and Class III Cultural Resource Inventory in		
McHenry and Pierce Counties, North Dakota.	•		
Morrolly and Floros Soundos, Horar Banota.			
Author: William Bluemle			
Addior. Villiam Blacimo			
Additional Information: One-room school hous	i e		
SHSND USE			
Area of Significance 2 Ecozone 2	Verified Site CR Type		
Area of Significance Ecozone	Non-Site		
Area of Significance Ecozone			
Recorded By William Blue	emie Date Recorded 10/19/2012		
Recorded By William Blue	Date Necorded		

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Complete one Page 2 for each architectural feature at the site.					
Architectural Featu	ıre #1				
Construction Date	Feature Ty	pe 9 Condition	on <u>5</u>		
Feature Date 4	Context 7	Plan Sh	Plan Shape 5		
Structural System 25	Primary Ex	terior <u>22</u> Style <u>Ga</u>	Style Gabled Front: Gabled L/T		
Original Owner's Ethn	icity Secondary	Exterior Architect	Architect/Builder		
Other Information:					
One window has been boarded-up and and the remaining windows are missing. The roof has cedar shakes and the exterior is stucco.					
Foundation Poured co	oncrete	Stories	1.5		
Window Window openings have no intact lights and one is boarded-up.					
Roof/Cornice Gable roof, cedar shake shingles.					
Dating Method(s): Professional estimate					
Feature Preservation Recommendation(s) (Check all that apply):					
Individual nomination					
Contributes to a potential district					
✓ No nomination potential					
Will not contribute to a district					
Potential district—feature would be a contributing element if other properties constitute a district					
Thematic nomination potential					
Component of a historic site or landscape					
Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility					
✓ Historical associations require further investigation					
Recorded By	William Bluemle (First Name & Last Name)	Date Record	ed 10/19/2012 (mm/dd/year)		

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

NDCRS SITE FORM ATTACHMENTS SECTION

Field Code MAC Town-1

SITS# 32MHx



Figure 1: View to the southwest over site lead MAC Town-1 (Image 21).



Figure 2: View to the northeast over site lead MAC Town-1 (Image 36).