117

State Historical Society of North Dakota

## NDCRS ARCHITECTURAL SITE FORM PAGE 1

		<u>ad 227</u>
SITE IDENTIFICATION		
Field Code Orange Township School Site Name		
Map Quad <u>Lemmon NE</u> Site Name Map Quad		
LTLTWPRRR       SECQQQ         LTLTWPRRSECQQQ         LTLTWPRRSECQQQ         LTLTWPRRRSECQQQ	QQ	Q <u>8</u> Q Q
UTMN ZONE UTME NAD 1927	NAD 1983	
City:		$2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$
Street Number:		$4 = W\frac{1}{2}$ 5 = NE <sup>1</sup> / <sub>4</sub>
Street Name: 28th St E		6 = SE¼ 7 = SW¼
Urban Legal Description:		8 = NW1⁄4
SITE DATA		
Total # Architectural Features:1		
Fieldwork Date: 6/21/2016		
Reconnaissance Survey Intensive Survey		
Project Title & Supervisor:		
Country Schoolhouse Project		
Report Title & Author(s):		
Additional Information:		
SHSND USE	CR Typ	
Recorded By Kathy Wilner Date	Recorded	1/24/2017 (mm/dd/year)

State Historical Society of North Dakota

**NDCRS 2009** 

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data				
FAGE 2-Feature Data				
Field Code Orange Township School		SITS# 32_AD		
Complete one Page 2 <u>for each architectural feature</u> at the site.				
Architectural Feature #1				
Construction Date	Feature Type <u>9</u>	Condition 5		
Feature Date 3	Context_7	Plan Shape <u>5</u>		
Structural System 25	Primary Exterior 26	Style Other Style		
Original Owner's Ethnicity	Secondary Exterior	Architect/Builder		
Other Information: Foundation <u>Concrete</u> and rocks		. Stories <u>1</u>		
Roof/Cornice_Gable, entry has shed roof				
Window Shuttered, fixed pane, double hung				
Dating Method(s): Estimate				
Feature Preservation Recommendation(s) (Check all that apply):				
Individual nomination				
Contributes to a potential district				
No nomination potential				

— Will not contribute to a district

\_\_\_\_\_Potential district-feature would be a contributing element if other properties constitute a district

\_\_\_\_\_Thematic nomination potential

----- Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context \_\_\_\_\_with neighboring structures; d) relocation has damaged eligibility

Historical associations require further investigation

Recorded By	Kathy Wilner	Date Recorded	1/24/2017
(First N	ame & Last Name)		(mm/dd/year)

**NDCRS 2009** 

### NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Orange Township School

SITS# 32 AD

#### Complete a Page 3 for each feature.

#### 1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a foundation of mixed rocks and concrete. The gable roof of the school and the shed roof of the entry are covered with older asphalt shingles. There is a short, red brick chimney at the north end of the peak of the roof. The soffits are closed. The building measures 32 feet north to south, inclusive of the entry, and 24 feet east to west.

There is a wide trim board under the soffits at the peak ends of the roof as well as under the soffits on the entry. The remainder of the siding is 6 inch woodlap with 4 inch wood corner trim, very little paint left. The locked 5 panel entry door is reached by wood steps to a wood platform porch, falling apart. There is a wooden railing along the south side of the porch. On the south wall of the entry, to either side of the door are two covered window openings. Two more covered window openings are on the east and west walls of the entry. On the north side of the school there are two replacement windows with intact glass, the top of what most likely was a taller window was filled in with siding. The east wall has two large covered areas that were likely large windows. The interior of the school, as viewed through a north window, shows wallboard on the walls and ceiling tiles. The floor is tongue and groove hardwood. Blackboards on the south wall of the school room, with a door at the east edge of the entry wall, and on the west wall.

A large fuel tank sits along the north wall. There are newer deskes in the classroom. Playground equipment remains in the south yard. Light fixtures and outside conduit suggest electricity.

Recorded By Kathy Wilner Date Recorded 1/24/2017
(First Name & Last Name) (mm/dd/year)

State Historical Society of North Dakota

**NDCRS 2009** 

## NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Orange Township School

SITS# 32\_AD\_\_\_\_

Complete one Page 4 for the entire site.

2. Owner's Contact Information:

3. Access (to rural areas):

Highway 12 in Lemmon SD, go north on Highway 73 to the North Dakota border and 5th Ave E, turn right and drive 1 mile to turn left and go north on 26th St E, 2 miles, turn right onto 3rd Ave E, 1 mile to then turn left on Black & Blue Road, going two miles north to 1st Ave E, turn right and the school is 1 mile east.

4. Site Area (ft<sup>2</sup>):\_\_\_\_\_

5. Description of SETTING:

The setting is very hilly with buttes in the distance, farms to the north, west and southwest and pasture all directions.

Recorded By Kathy Wilner Date Recorded 1/24/2017
(First Name & Last Name) (mm/dd/year)

State Historical Society of North Dakota

**NDCRS 2009** 

## NDCRS ARCHITECTURAL SITE FORM **PAGE 5—SITE DESCRIPTION**

Field Code Orange Township School

SITS# 32 AD

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By (First Name & Last Name) **Kathy Wilner** 

Date Recorded

1/24/2017 (mm/dd/year)



South Side

Orange Township School

6/21/2016

Kathy Wilner

AD







East Side

Orange Township School

6/21/2016

Kathy Wilner

AD

North Side



#### 7/6/2016

#### Bing Maps - Directions, trip planning, traffic cameras & more

## bing maps

# Notes Orange Township School 6/21/2016 Kathy Wilner AD



