NDCRS ARCHITECTURAL SITE FORM PAGE 1

SITS# 32 BA 317

(First Name & Last Name)		Date Recorded	(mm/dd/year)
Recorded By Kathy Wilne	r	Date Recorded	1/13/2017
SHSND USE Area of Significance Area of Significance Area of Significance Area of Significance	Verified Site Non-Site	CR Typ	e <u>2</u>
Additional Information:	×		
Report Title & Author(s):			
Project Title & Supervisor: Country Schoolhouse Project			
Reconnaissance Survey Intens	ive Survey		
Fieldwork Date:5/3/2016			
Total # Architectural Features:1			
SITE DATA			
Urban Legal Description:			8 = NW ¹ / ₄
Street Name: 26th St SE		_	6 = SE½ 7 = SW½
Street Number:			$4 = W\frac{1}{2}$ $5 = NE\frac{1}{4}$
City: Valley City		_	$2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$
UTMN UTME	ZONE _ NAD 19	 927 NAD 1983	- 111/2
LTL TWP R SEC _ LTL TWP R SEC _	15 QQQ 5 QQQ QQQ QQQ QQQ	QQ	Q <u>5</u> Q Q
Map Quad <u>Baldhill Dam</u> Map Quad	Site Name - -		
Field Code Getchell Hall	Site Name	petchell Hall	
SITE IDENTIFICATION			

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code Getchell Hall			SITS	SITS# 32_BA	
Complete one Page 2 for each architectural feature at the site.					
Architectural Featur	re #1				
Construction Date 18	83	Feature Type9	Cond	ition <u>6</u>	
Feature Date 2		Context 7	Plan	Shape <u>5</u>	
Structural System 25		Primary Exterior <u>16</u>	_ Style_	Other Style	
Original Owner's Ethnic	ity	Secondary Exterior	Archit	ect/Builder	
Other Information:					
Foundation Concrete	10		Storie	s1_	
Roof/Cornice_Gable					
Window Double hung, ι	under the metal s	sheeting			
Dating Method(s): Scho	ool History			·	
Feature Preservation	n Recommend	lation(s) (Check all t	hat apply):		
Individual nomi	nation				
Contributes to a	a potential distric	t			
No nomination	potential				
Will not contribu	ute to a district				
Potential district—feature would be a contributing element if other properties constitute a district					
Thematic nomin	nation potential				
——Component of a	a historic site or l	andscape			
recreates origin	al site, orientation	oices)—a) relocation oc on, landscape, & spatial elocation has damaged	relationships; c		
Historical associations require further investigation					
Recorded By (First Na	Kathy me & Last Name)	Wilner	_Date Record	ded 1/13/2017 (mm/dd/year)	

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Getchell Hall	SITS# 32 BA
Tield Code cotonon rian	3113# 32 <u>5/</u>

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school sitting on a concrete foundation. The gable roof is covered with metal sheeting and the soffits are closed with metal as well. There is a red brick chimney near the east end of the roof. The building measures 40 feet east to west and 24 12 feet north to south.

This building is entirely covered with vertical metal siding. There is an newer entry door at the southwest corner, locked as well as newer entry door on the east side, also locked. There is a small concrete pad just outside this east door. Electric conduit and a meter are just to the right of the entry door and there is an outdoor light high on the east wall.

In conversation with a township board member I learned that the windows were left in place when the siding was put on in the 1980's. The windows are double hung and might have some glass left. There is a foyer inside the entry door and small rooms to either side were coat rooms. The flooring is tongue and groove hard wood. The walls are covered with wall board and wainscot finishes the lower 1/3 of the wall. There is blackboard on the west wall. An oil burner sits inside the south part of the school room and is used today.

A sign on the building says Getchell Hall 1883 to 1983.

Recorded By	Kathy Wilner	Date Recorded	1/13/2017
(First Name & Last Name)			(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM **PAGE 4—SITE DESCRIPTION**

Field Code Getchell Ha	II	SITS# 32_	BA
Complete one Page	4 for the entire site.		
Owner's Contact Inform Getchell Township	nation:		
	n 117th Ave SE or County 21,	drive north about 6 miles to 26 SE. The school will be on your	
4. Site Area (ft²):			
5. Description of SETTING There are trees to the not		ectly west with farmland all dire	ctions.
			*
Recorded By	Kathy Wilner	Date Recorded	1/13/2017 (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Getchell Hall		SITS# 32_BA		
6. Summary of ALL Site Features & Evaluation of Significance:				
			¥	
7. References/Comments:				
Kathy Wilner 366 43rd Ave SE				
Bowdon ND 58418				
	Madley Miller	But But it	4/42/2047	
Recorded By(First Name &	Kathy Wilner Last Name)	Date Recorded	1/13/2017 (mm/dd/year)	

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.



East Side


Getchell Hall

5/3/2016

Kathy Wilner

BA

North Side





South Side

Getchell Hall 5/3/2016 Kathy Wilner BA

West Side



bing maps

Notes

Getchell Hall

5/3/2016

Kathy Wilner

ВА



