NDCRS ARCHITECTURAL SITE FORM PAGE 1

SITS# 32 BA 32H

(First Name & Last Name)		Date Recorded	(mm/dd/year)
Area of Significance Ecozone Ecozone Area of Significance Area of Significance Recorded By Kathy W	Verified Site Non-Site		1/15/2017
SHSND USE Area of Significance 2 Ecozone 18	Varified Site	CR Type	2
Additional Information:			
Report Title & Author(s):			
Project Title & Supervisor: Country Schoolhouse Project			
Reconnaissance Survey <u>✓</u> In	ntensive Survey		
Fieldwork Date:5/6/2016			
Total # Architectural Features:1			
SITE DATA			
Urban Legal Description:			8 = NW ¹ / ₄
Street Name: 106th Ave SE			6 = SE½ 7 = SW¼
Street Number:			4 = W½ 5 = NE¼
City:			2 = E½ 3 = S½
UTMN UTME	ZONE . NAD 19	927 NAD 1983	Subsection: 1 = N½
LTL TWP R S LTL TWP R S	EC QQQ	QQ	Q <u>6</u> Q Q
Map Quad <i>Moon Lake</i> Map Quad	Site Name 	· · · · · · · · · · · · · · · · · · ·	
Field Code Hemen Township School		emen Township	School
SITE IDENTIFICATION			- 4

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code Hemen Township School		SITS# 32_BA	
Complete one Page 2 for each architectural feature at the site.			
Architectural Feature #1	_		
Construction Date <u>1895</u>	Feature Type9	Condition 5	
Feature Date 2	Context 7	Plan Shape	5
Structural System <u>24. 25</u>	Primary Exterior <u>26</u>	Style Other S	Style
Original Owner's Ethnicity	Secondary Exterior	Architect/Bui	lder
Other Information:			
Foundation Conrete		Stories1	
Roof/Cornice_Gable			
Window Double hung, some filled i	n, some broken glass		
Dating Method(s): Sign on the build	ding		
Feature Preservation Recommendation(s) (Check all that apply): Individual nomination Contributes to a potential district No nomination potential Will not contribute to a district Potential district—feature would be a contributing element if other properties constitute a district Thematic nomination potential Component of a historic site or landscape Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility Historical associations require further investigation			
Recorded By Ka	athy Wilner Da	ate Recorded	1/15/2017 (mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

SITS# 32_BA

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school sitting on a concrete foundation. The gable roof of this school is covered with wood shakes and the peak is finishes with metal capping with finials. Many of the wood shakes are missing. there is a red brick chimney located at the west end of the school at the peak of the roof. The half hip roof of the entry is also covered with wood shakes with metal capping and a finial at the east end. The building measures 28 feet east to west and 18 feet north to south. The entry measures 8 feet by 8 feet.

The walls of the school begin with a wide trim board under the peak ends of the roof. The remainder of the siding is 6 inch wood lap with 4 inch corner trim again with a skirting board and water table to complete the bottom of the siding. Originally there were 6 dindows on both the north and south sides. The middle window on the south side was boarded up with siding and the left and right windows on the north side were filled in as well. The remaining windows appear to be original windows, double hung with some glass. There is one small, fixed pane window in the entry. The entry door to the school is a broken 5 panel wood door. There is a small concrete pad just approaching the door. The small entry allows access to the school room through a newer wood door. The walls ceiling in the school are lathe and plaster with some of the plaster falling away from the ceiling. The floor is tongue and groove hardwood. There is a small black board on the west wall of the school room and there is also a fuel oil stove at that end of the room. There is a fuel oil barrel outside the west end of the school and there is also one outhouse to the northwest of the school. An electric meter and conduit suggests the presence of electricity.

Recorded By_	Kathy Wilner	Date Recorded	1/15/2017	
	(First Name & Last Name)		(mm/dd/year)	

Field Code Hemen Township School

SITS# 32_BA____

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Complete one Page 4 <u>for the entire site</u> .
2. Owner's Contact Information:
Keith McCleary 4421 101th Ave SE Marion ND 58466
3. Access (to rural areas):
South of I 94 at Exit 281 drive south on 106th Ave SE 5 1/2 miles to see the school on your left.
4. Site Area (ft²):
5. Description of SETTING :
There is a large slough to the west, farmland to the east and south and a farmstead to the north.
Recorded By Kathy Wilner Date Recorded 1/15/2017
(First Name & Last Name) (mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Hemen Township School		SITS# 32_	BA
6. Summary of ALL Site Features & Evaluation of Significance:			
7. References/Comments:			
Kathy Wilner			
366 43rd Ave SE Bowdon ND 58418			
Recorded By(First Name & I	Kathy Wilner	Date Recorded	1/15/2017 (mm/dd/year)



East Side

Hemen Township School

5/6/2016

Kathy Wilner

BA

North Side





South Side

Hemen Township School

5/6/2016

Kathy Wilner

BA

West Side



bing maps

Notes

Hemen Township School

5/6/2016

Kathy Wilner

ВА





Feature