NDCRS ARCHITECTURAL SITE FORM PAGE 1

UPDATE

SITS# 32 BA 750

Area of Significance Ecozone Verified Site CR Type Area of Significance Ecozone Non-Site Area of Significance Ecozone Non-Site Recorded By Kathy Wilner Date Recorded 1/13/2017	SITE IDENTIFICATION		0110# 02 <u></u>	
Map Quad Map Quad QQ QQ Q	Field Code Heimes School #2	Site Name	eimes No.10	
LTLTWPR RSECQQQQQQQQQQQQ QQQQ LTLTWPR SECQQQQQQQQQQ Q LTLTWPR SECQQQQQQQQ Q UTMN N ZONE	Map Quad			
Time	LTL TWP R S LTL TWP R S	EC QQQ _ EC QQQ _	QQ QQ	Q
City: Valley City 3 = St/₂ Street Number: 5 = NE¹/₂ Street Name: 9th Ave NW and 4th St NW 6 = SE¹/₃ Urban Legal Description: 8 = NW¹/₃ SITE DATA Total # Architectural Features: 1 Fieldwork Date: 5/3/2016 Reconnaissance Survey Intensive Survey Project Title & Supervisor: Country Schoolhouse Project Report Title & Author(s): Additional Information: SHSND USE Area of Significance Ecozone Verified Site CR Type Area of Significance Ecozone Non-Site Non-Site Recorded By Kathy Wilner Date Recorded 1/13/2017	UTMN		27 NAD 1983	1 = N½
Street Number: Street Name: 9th Ave NW and 4th St NW Urban Legal Description: SITE DATA Total # Architectural Features: 1 Fieldwork Date: 5/3/2016 Reconnaissance Survey Intensive Survey Intensive Survey Project Title & Supervisor: Country Schoolhouse Project Report Title & Author(s): Additional Information: SHSND USE Area of Significance Ecozone Non-Site Recorded By Kathy Wilner Date Recorded 1/13/2017	City: Valley City			3 = S½
Street Name: 9th Ave NW and 4th St NW Urban Legal Description:	Street Number:		_	5 = NE1/4
SITE DATA Total # Architectural Features:1 Fieldwork Date:5/3/2016 Reconnaissance Survey ✓ Intensive Survey Project Title & Supervisor: Country Schoolhouse Project Report Title & Author(s): Additional Information: SHSND USE Area of Significance Ecozone Verified Site CR Type Area of Significance Ecozone Non-Site Recorded By Kathy Wilner Date Recorded 1/13/2017	Street Name: 9th Ave NW and 4th St NW		_	7 = SW1/4
Total # Architectural Features:1 Fieldwork Date:5/3/2016 Reconnaissance Survey ✓ Intensive Survey Project Title & Supervisor: Country Schoolhouse Project Report Title & Author(s): Additional Information: SHSND USE Area of Significance Ecozone Verified Site CR Type Area of Significance Ecozone Non-Site Recorded By Kathy Wilner Date Recorded 1/13/2017	Urban Legal Description:		_	8 = NW1/4
Fieldwork Date: 5/3/2016 Reconnaissance Survey ✓ Intensive Survey Project Title & Supervisor: Country Schoolhouse Project Report Title & Author(s): Additional Information: SHSND USE Area of Significance Ecozone Verified Site CR Type Area of Significance Ecozone Non-Site Recorded By Kathy Wilner Date Recorded 1/13/2017	SITE DATA			
Reconnaissance Survey Intensive Survey Project Title & Supervisor: Country Schoolhouse Project Report Title & Author(s): Additional Information: SHSND USE Area of Significance Ecozone Verified Site CR Type Area of Significance Ecozone Non-Site Recorded By Kathy Wilner Date Recorded 1/13/2017	Total # Architectural Features:1			
Project Title & Supervisor: Country Schoolhouse Project Report Title & Author(s): Additional Information: SHSND USE Area of Significance Ecozone Verified Site CR Type Area of Significance Ecozone Non-Site Area of Significance Ecozone Non-Site Recorded By Kathy Wilner Date Recorded 1/13/2017	Fieldwork Date:5/3/2016			
Country Schoolhouse Project Report Title & Author(s): Additional Information: SHSND USE Area of Significance Ecozone Verified Site CR Type Area of Significance Ecozone Non-Site Area of Significance Ecozone Non-Site Recorded By Kathy Wilner Date Recorded 1/13/2017	Reconnaissance Survey <u>✓</u> Ir	ntensive Survey		
Additional Information: SHSND USE Area of Significance				
SHSND USE Area of Significance Ecozone Verified Site CR Type Area of Significance Ecozone Non-Site Area of Significance Kathy Wilner Date Recorded 1/13/2017	Report Title & Author(s):			
Area of Significance Ecozone Verified Site CR Type Area of Significance Ecozone Non-Site Area of Significance Ecozone Non-Site Recorded By Kathy Wilner Date Recorded 1/13/2017	Additional Information:			
The cordical By But it to cordical	Area of Significance Ecozone Area of Significance Ecozone		CR Type	
	Recorded By Kathy W (First Name & Last Name)	/ilner	Date Recorded	1/13/2017 (mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

UPDATE

Field Code Heimes School #2			S	ITS# 32 <u>B</u>	<u>A</u>	750
Complete one Pa	ige 2 <u>for each ar</u>	chitectural feature	e at the	site.		
Architectural Feat	ure #1					
Construction Date	F	eature Type9	C	ondition 6		
Feature Date	_ c	ontext 7	Р	lan Shape <u>5</u>		
Structural System 25	Р	rimary Exterior <u>26</u>	_ S	tyle <u>Other Styl</u>	le	
Original Owner's Ethn	nicity S	econdary Exterior	A	rchitect/Builde	er	-
Other Information:						
Foundation Poured C	oncrete		S	tories1_		
Roof/Cornice						
Window					VII/101011111111111111111111111111111111	
Dating Method(s):						
Feature Preservation Recommendation(s) (Check all that apply): Individual nomination Contributes to a potential district No nomination potential Will not contribute to a district Potential district—feature would be a contributing element if other properties constitute a district Thematic nomination potential Component of a historic site or landscape Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility Historical associations require further investigation						
Historical ass	ociations require furt	ner investigation				
Recorded By	Kathy W	ilner	Date Re	corded	1/13/20 (mm/dd/	

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

UPDATE

Field Code Heimes School #2

SITS# 32_BA___750

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

This feature has been previously recorded so I will add additional notes for small changes. The bell tower showed openings on all sides and that is now closed. The double hung windows have half or more covered for protection. The interior, as viewed through the windows, show wood walls with colorful murals painted on them. The floor has been covered with rubber matting to protect the wood floor and it is now used as a warming house for the ice rink. There are old light fixtures inside.

Recorded By Kathy Wilner Date Recorded 1/13/2017 (First Name & Last Name)

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

UPDATE

Field Code Heimes School #2	2	SITS# 32_	BA 750
Complete one Page 4 <u>for</u>	the entire <i>site</i> .		
Owner's Contact Information: Valley City Park District			
3. Access (to rural areas): At the corner of 9th Ave NW ar	nd 4th St NW in Valley City.		
4. Site Area (ft²):			
5. Description of SETTING :			
In a park.			
			*
Recorded By(First Name & Las	Kathy Wilner	Date Recorded	1/13/2017
(First Name & Las	t Name)		(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

	_	_	-	_	_
	0	п	A	_	
	_	.,	44		•
-		Sec.			


Field Code Heimes School #2	SITS# 32	ВА	750
2 100 200 500 10 100 100 100 100 100 100 100 10	address our supplement resources		

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments:

Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By	Kathy Wilner	Date Recorded	1/13/2017	
(First Name & Last Name)			(mm/dd/year)	_




East Side


Heimes School #2

5/3/2016

Kathy Wilner BA

North Side





South Side

Heimes School #2

5/3/2016

Kathy Wilner

BA

West Side



bing maps

Notes

Heimes School

5/3/2016

Kathy Wilner

BA





Feeture