NDCRS ARCHITECTURAL SITE FORM PAGE 1

SITS# 32 BE 230 SITE IDENTIFICATION Field Code Quarve #3 Site Name Quarve #3 Site Name Map Quad LTL TWP 151 R 69 SEC 34 QQQ. 1 LTL __ TWP _____ R ____ LTL __ TWP _____ R ____ SEC _____ 000 <u></u> SEC ____ QQQ LTL __ TWP _ QQQ _ ZONE_ Subsection: NAD 1927 ___ NAD 1983 _ UTM $1 = N\frac{1}{2}$ $2 = E\frac{1}{2}$ City: Maddock $3 = 5\frac{1}{2}$ $4 = W\frac{1}{2}$ Street Number: $5 = NE\frac{1}{4}$ $6 = SE\frac{1}{4}$ Street Name: 31st St NE $7 = SW\frac{1}{4}$ $8 = NW\frac{1}{4}$ Urban Legal Description: SITE DATA Total # Architectural Features: 1 Fieldwork Date: ____ 8/31/2014 Reconnaissance Survey ______ Intensive Survey ____ Project Title & Supervisor: Country Schoolhouse Project Report Title & Author(s): Additional Information: SHSND USE Area of Significance Ecozone _ Area of Significance _____ Area of Significance _ Kathy Wilner ___ Date Recorded __ Recorded By

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

(First Name & Last Name)

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code Quarve #3		SITS# 32.	BE
Complete one Page 2 <u>f</u>	or each architectural featu	<u>re</u> at the site.	
Architectural Feature # _	1		
Construction Date1890	Feature Type9	Condition 7	
Feature Date 2	Context 7	Plan Shape	5
Structural System 25	Primary Exterior <u>26</u>	Style_Other S	Style
Original Owner's Ethnicity	Secondary Exterior	Architect/Bu	ilder
Other Information:			
Foundation Concrete and woo	od	Stories1	
Roof/Cornice Gable	·		
Window Double hung			
Dating Method(s): County his	tory		
— Individual nomination — Contributes to a poter — No nomination potent — Will not contribute to a — Potential district—fea — Thematic nomination — Component of a histor Moved (specify all apprecreates original site	ial a district ture would be a contributing elem potential	ent if other properties of the courred within a historic relationships; c) comp	c period; b)
Recorded By (First Name & L	Kathy Wilner	_ Date Recorded	2/25/2015 (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) *Print* and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Quarve #3	SITS# 32_BE	
----------------------	-------------	--

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a wood framed prairie school on a foundation of concrete and wood. The roof of the school is covered with wood shakes with metal ridge cap and ball finials. There is a large cupola near the north end of the peak. The roof of the tower is covered with wood shakes and there is a flag pole at the peak. There is a bell in the tower. There is wood framing with more wood shakes finishing the botom box of the cupola. At the south end of the peak is a red brick chimney. This school was moved off a basement at a former location and moved to this spot for preservation. The building measures 40 feet north to south and 20 feet 4 inches east to west.

There is a wide header under the eaves at the peak of both of ends of the main body of the school as well as the peak of the entry. The siding is 6 inch lap with 4 inch corner trim. A wide board is located at the bottom of the siding on all sides of the school. A modern, security door, locked, gives entry to the school from a wood porch. There are two small 4 pane, fixed windows on the west wall of the porch and one small three pane window on the east side. Other windows in the school are 6 large,multipane double hung windows with all glass intact. They have new storm windows on the outside.

The school has lathe and plaster walls and ceiling. Flooring is hardwood. There is wainscot on all walls in the entry but none in the main body of the scxhool. Blackboard was on the east wall. There was electricity present in the school as there is a light fixture over the front door.

Recorded By_	Kathy Wilner	Date Recorded	2/25/2015	
-	(First Name & Last Name)		(mm/dd/year)	

SITS# 32_BE_____

NDCRS ARCHITECTURAL SITE FORM **PAGE 4—SITE DESCRIPTION**

Field Code Quarve #3		SITS# 32_B	<u> </u>
Complete one Page 4 for the e	ntire s <i>it</i> e.		
2. Owner's Contact Information:			
Viking Church %Jim Peterson PO Box 308			
Maddock ND 58348			
3. Access (to rural areas):			
From Maddock, drive south 6 1/2 miles curves to the south again (1 mile) cont school on the right.		-	
4. Site Area (ft²):			
5. Description of SETTING :			
The school sits just to the east of Vikin of the school. There are trees to the school.		•	the southwest
<i></i>	Wilner	Date Recorded	2/25/2015
(First Name & Last Name)			(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Quarve #3		SITS# 32_	BE
6. Summary of ALL Site	e Features & Evaluation	on of Significance:	
7. References/Comments: Kathy Wilner			
366 43rd Ave SE			
Bowdon ND 58418			
Recorded By (First Name & L	Kathy Wilner	Date Recorded	2/25/2015 (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.



North Side

Quarve #3


8/31/2014

Kathy Wilner

BE

East Side





West Side

Quarve #3

8/31/2014 Kathy Wilner

BE

South Side



SOUTH VIKING DIRECTORY

1111111111111111

rrrrrrrrrrrrrrr

