

NDCRS ARCHITECTURAL FORM
PAGE 1

Field Code Beaver Township School #2

SITS# 32 BE 443

Map Quad York
Map Quad _____

Site Name Beaver Township School #2
Site Name _____

LTL T. 1 5 5 N., R. 69 W., Sec. 7 QQQ 5 of the QQ 5 of the Q 6
LTL T. N., R. W., Sec. QQQ of the QQ of the Q
LTL T. N., R. W., Sec. QQQ of the QQ of the Q
LTL T. N., R. W., Sec. QQQ of the QQ of the Q

Subsection
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

NAD 1983 UTM 5345268 Zone 14N
NAD UTM 457830

City: _____

Street Number: _____

Street Name: 49th Ave NE

Urban Legal Description: _____

Total Number of Architectural Features: 1

Fieldwork Date: 7/8/2020

Reconnaissance Survey

Intensive Survey

Project & Principal Investigator:
Country School House Project
Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Contracting Firm or Agency Completing the Form:

Additional Information:

SHSND USE
Component 2 Study Unit 17 Verified Site _____ CR Type 2
Component _____
Component _____

Recorded By: Kathy Wilner Date Recorded: 8/6/2020

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

NDCRS ARCHITECTURAL FORM
PAGE 2 – Feature Data

Field Code Beaver Township School #2

SITS# 32 BE

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date 1903

Feature Date 1900-1915

Structural System Wood Frame

Original Owner's Ethnicity _____

Feature Type 9 - School; Church school

Context Education

Primary Exterior Wood, Horizontal Siding

Secondary Exterior _____

Condition Good

Plan Shape Rectangular

Style Other Style

Architect/Builder _____

Foundation Poured concrete Stories 1

Roof/Cornice Gable, school and entry, shed roof on the addition

Window Double hung with some glass

Dating Method(s) Beaver Township School District #15 1894-1958 Reunion Booklet

Miscellaneous Information _____

Feature Preservation Recommendation(s) (Check all that apply):

Individual nomination

Contributes to a potential district

No nomination potential

Will not contribute to a district

Potential district—feature would be a contributing element if other properties constitute a district

Thematic nomination potential

Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

Historical associations require further investigation

Recorded By: Kathy Wilner Date Recorded: 8/6/2020

NDCRS ARCHITECTURAL FORM
PAGE 3 – Feature Data

Field Code Beaver Township School #2SITS# 32 BEComplete one Page 3 for *each* architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a concrete foundation. The roof of the main part of the school is covered with wood shakes with metal capping and finials. The entry roof is covered with asphalt shingles while the shed roof has metal sheeting. A yellow brick chimney sits at the peak of the roof of the school at the west end and a flag pole sits at the peak at the east end. The soffits are closed. The school measures 19 feet north to south by 21 feet east to west, the entry is 10 feet by 10 feet and the shed is 5 feet by 10 feet.

A rake board begins the siding under the peaked ends of the school and entry. The remaining siding is 6 inch wood lap with 4 inch corner trim. The school has an entry on the east side with a broken wood door. There are pieces of corrugated metal covering broken pieces. A transom window is above the door and the glass is intact. Also in the entry is one small, 4 pane window. The shed on the north side of the entry has broken lumber and junk in it and the walls are stripped. The entry walls are covered with panel and the floor is tongue and groove hard wood. A 6 panel wood door gives entry into the school room. The windows in the main body of the school are two over two double hung windows with a lot of broken glass. There are storm windows covering this bank of 5 windows that run along the south wall as well as another window at the east end of the north wall. There are decorative cornices above the windows and the school room door. Remnants of window shades remain on some of the windows. The interior walls of the school are covered with wallboard. The ceiling has rectangular tiles covering beadboard. The floor is tongue and groove hardwood. Black boards are on the south half of the west wall and along most of the north wall. A large stove stands in the northwest corner of the school room. Light fixtures over the door as well as in the school give evidence of electricity.

The school was furnished with desks, chairs, books in book cases, a wash stand, a teachers desk, several maps and much more.

2. Owner's Contact Information:

Karoline Pierson
 9104 Cedar Lake Rd S
 St. Louis Park MN 55426

Recorded By: Kathy Wilner Date Recorded: 8/6/2020

NDCRS ARCHITECTURAL FORM
PAGE 4 – Site Description

Field Code Beaver Township School #2

SITS# 32 BE

3. Site Area (ft²):

4. Description of Access and Site Setting:

This school is located south of Highway 2 at York. Drive south on 49th Ave NE about 3 1/2 miles. It is 1/2 mile south of 59th St NE.

A farm sits just to the north of the school as well as another to the south east. All other directions are farm fields and pasture.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Recorded By: Kathy Wilner **Date Recorded:** 8/6/2020



South Side

Beaver Township School #2

7/8/2020

Kathy Wilner

BE



West Side



East Side

Beaver Township School #2

7/8/2020

Kathy Wilner

BE



North Side



Imagery ©2020 Google, Imagery ©2020 CNES / Airbus, Maxar Technologies, USDA 500 ft
Farm Service Agency, Map data ©2020

Feature