NDCRS ARCHITECTURAL SITE FORM PAGE 1

	PAGE 1	SITS# 32_B	11/0/0
SITE IDENTIFICATION		0110# 02	
Field Code Billings School #1			
Map Quad Fair field SE Map Quad	Site Name		onto one of the control of the contr
LTL TWP R SEC _ LTL TWP R SEC _	14 QQQ 6 QQQ 2 QQQ 2 QQQ 2	QQ <u>6</u> QQ QQ QQ	Q 7 Q Q Q
UTMN UTME	ZONE NAD 1927	NAD 1983	Subsection: 1 = N½
City:			2 = E½ 3 = S½
Street Number:			4 = W½ 5 = NE¼
Street Name: 21st St SW			6 = SE½ 7 = SW¼
Urban Legal Description:			8 = NW1/4
SITE DATA			
Total # Architectural Features: 1	sphanus		
Fieldwork Date: 4/13/2016			
Reconnaissance Survey <u>✓</u> Intensi	ive Survey		
Project Title & Supervisor: Country Schoolhouse Project			
Report Title & Author(s):			
Additional Information:			
			4
Area of Significance Ecozone Area of Significance Ecozone	Verified Site	. CR Type	_2_

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code Billings Scho	001 #1	SITS# 32.	
Complete one Page	2 <u>for each architectural fe</u>	ature at the site.	
Architectural Feature	<u> 1</u>		
Construction Date	Feature Type	Condition 6	and a distribution of the second of the seco
Feature Date 3	Context 7	Plan Shape	5
Structural System 25	Primary Exterior 2	Style Other S	Style
Original Owner's Ethnicity	Secondary Exterio	r Architect/Bu	ilder
Other Information:			
Foundation Concrete		Stories1	
Roof/Cornice Hip			
Window Glassblock with s	mall central window, replacemen	t	
Dating Method(s): Estimat	e		
Feature Preservation Recommendation(s) (Check all that apply): Individual nomination Contributes to a potential district No nomination potential Will not contribute to a district Potential district—feature would be a contributing element if other properties constitute a district Thematic nomination potential Component of a historic site or landscape Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility Historical associations require further investigation			
Recorded By (First Name	Kathy Wilner	Date Recorded	1/23/2017 (mm/dd/year)

BI

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Billings School #1		SITS# 32_

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a concrete foundation. The hip roof of the school is covered with wood shakes and has metal capping and one finial with metal corner capping on all the hips. There is a metal pipe chimney on the west slope of the roof. The soffits are closed. The building measures 30 feet east to west and 20 feet north to south.

There is a wide trim board under the soffits on all four sides of the school. The siding continues 6 inch wood lap and 4 inch wood corner trim. Near the bottom of the siding is a waterboard with another wide trim board. The entry door is plywood and reached from a concrete step. Inside the entry there are two 5 panel wood doors, one leads into the school room and one to the right leads into the coatroom. There is one small glass block window in the coat room and another just as you step into the school room. Two more large vented glass block windows are on the south wall. Suspect older windows were removed and the block windows replaced them. The interior walls are wallboard and ceiling is a suspended ceiling with tiles. The floor has some lineolum covering tongue and groove hardwood. There is a blackboard on the north wall. A stove pipe hands from the ceiling as the stove/furnace has been removed. Light fixtures and outside wiring suggest electricity.

Recorded By	Kathy Wilner	Date Recorded	1/23/2017	
	(First Name & Last Name)		(mm/dd/year)	

NDCRS ARCHITECTURAL SITE FORM **PAGE 4—SITE DESCRIPTION**

Field Code Billings School #1	SITS# 32_	BI
Complete one Page 4 for the entire site.		
 Owner's Contact Information: Wayne Hecker ETAL for Kathryn Hecker Estate PO Box 1282 Dickinson Nd 58601 		
3. Access (to rural areas):		
North of Belfield on Highway 85 12 plus miles to 23rd St SW. left to drive north on 123rd Ave SW two miles and then right agon the left or north side of the road.		
4. Site Area (ft²):		
 Description of SETTING: There are farms to the east and south and open prairie and pais a quonset just to the northeast of the building. 	sture with some shelter	belts west. There
Recorded By Kathy Wilner	Date Recorded	1/23/2017
(First Name & Last Name)		(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Billings School #	£1	SITS# 32_	BI
6. Summary of ALL Site	Features & Evaluation of	Significance:	
		*	
7. References/Comments: Kathy Wilner			
366 43rd Ave SE Bowdon ND 58418			
DOMOGITAD 30410			
Recorded By (First Name & La	Kathy Wilner	_ Date Recorded	1/23/2017 (mm/dd/year)



South Side


Billings School #1

4/13/2016

Kathy Wilner

BI

West Side





East Side

Billings School #1

4/13/2016

Kathy Wilner

BI

North Side



bing maps

Notes

Billings School #1

4/13/2016

Kathy Wilner

BI





Feature