## NDCRS ARCHITECTURAL SITE FORM PAGE 1

CITE IDENTIFICATION	FA	GE I	SITS# 32	1180
Field Code Hut School		te Name Ruf Schoo		
Map Quad Fairfield Map Quad		e Name		
LTL TWP 143 R 99  LTL TWP R R R LTL TWP R R R R R R R R R R R R R R R R R R R	SEC SEC SEC	QQQ	QQ 6 QQ QQ QQ QQ	Q 5 Q Q
UTM 5233119 UTM 639201	N E	ZONE 13N NAD 1927	NAD 1983	Subsection: 1 = N½
City: Fairfield				2 = E½ 3 = S½
Street Number: 1247		110		4 = W½ 5 = NE¼
Street Name: 126th Ave SW				6 = SE¼ 7 = SW¼ 8 = NW¼
Urban Legal Description:				0-14474
SITE DATA				
Total # Architectural Features:	1		Ju	
Fieldwork Date: 6/12/2018	3			
Reconnaissance Survey	Intensive S	Survey		
Project Title & Supervisor: Cpuntry Schoolhouse Project				
Report Title & Author(s):				
Additional Information:				
SHSND USE Area of Significance Ecozone _ Ecozone _	22_	Verified Site	_ CR Typ	pe <u>2</u>
	y Wilner	Data	Recorded 17	14/2018
(First Name & Last Name		Date	Necolded	(mm/ddlyear)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

## NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code Rur School	)I	SITS# 32 BI
Complete one Page	2 for each architectural f	feature at the site.
Architectural Feature	#1	
Construction Date	Feature Type	9 Condition 6
Feature Date 3	Context 7	Plan Shape 5
Structural System 25	Primary Exterior	26 Style Other Style
Original Owner's Ethnicity	Secondary Exter	rior Architect/Builder
Other Information:		
Foundation Poured Conc	rete	Stories 1
Roof/Cornice Gable/ Hip	Roof	
Window Replacement win	ndows, double hung with glass	
Dating Method(s): Estima	ite	
Thematic nomina Component of a Moved (specify a recreates origina with neighboring	otential district  e to a district  feature would be a contributing  tion potential  nistoric site or landscape  Il applicable choices)—a) reloca  site, orientation, landscape, & s  structures; d) relocation has dan	
HISTORICAL ASSOCIA	itions require further investigatio	on
Recorded By	Kathy Wilner	Date Recorded 1/14/2018
	e & Last Name)	(mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

### NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Rut School	PAGE 3—Feature Data	SITS# 32 BI	
CARL CONTRACTOR OF THE PARTY OF THE PARTY.			

### Complete a Page 3 for each feature.

#### 1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school house placed on a poured concrete foundation. This building was moved to the current location. It is now being used by the family as a butcher shop.

The roof is covered with metal sheeting with metal capping. The soffits are closed. There is a concrete chimney on the north, hip slope of the building. The roof of the school blends gable roofing with a partial hip roof at the north end of the main part of the building and a half hip over the entry. There is a wide trim board running just under the eaves on the east, west and north sides of the building as well as a trim board following the roofline at the south end of the main part of the building. The siding is original 6 inch wood lap with 4 inch wood corner trim. All the windows have been replaced with updated, double hung windows. There are three on the east side, one on the north wall and one on the south wall of the entry. One fixed pane window is located to the right of the entry door. That door is a metal two panel bottom with glass insert top security door. A wooden platform on concrete leads to the door. The entry walls are crackled plaster with coat hooks on the west wall. The entry is split into two rooms, the one with the door gives entry into the school proper and the other half is accessed through a door inside the main room and this space is used for storage. That door is an old, 5 panel wood door. Walls of the main room are lathe and plaster. No wainscot in this building. The ceiling is a mixture of lather and plaster and wallborad. Tongue and groove hardwood covers the floor. Blackboards remain in the school and are found on the west and half of the south wall. There is electricity today. Original heat was coal. The school was closed in 1967.

Recorded By	Kathy Wilner	Date Recorded 1/14/2018	
/First Ms	ma R I set Namal	(mm/ddhroas)	

# NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Rur Scr		SITS# 32 BI
Complete one Pag	ge 4 <u>for the entire site</u> .	
2. Owner's Contact Info Bernard & Judy Palah 1247 126th Ave SW Fairfield ND 58627	ormation: nuik	
		go east three miels, turn left and go north on or west side of the road.
4. Site Area ( <b>ft²</b> ):		
south and various out	ed to a farm yard and it sits amont bu	ildings. There is a house to the east, a barn yard has trees to the north and west. Farm
Recorded By	Kathy Wilner	Date Recorded 1/14/2018
(I-IISE N	ame & Last Name)	(mm/dd/year)

Recorded By

## NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Ruf School	SITS# 32 BI
6. Summary of ALL Site Features & Ev	aluation of Significance:
7. References/Comments: Kathy Wilner	
366 43rd Ave SE Bowdon ND 58418	
DOWUUII ND 30410	


Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

**Kathy Wilner** 

(First Name & Last Name)

Date Recorded 1/14/2018

(mm/dd/year)



South Side


**Ruf School** 


6/12/2018

Kathy Wilner

BI

**East Side** 






West Side

**Ruf School** 

6/12/2018

Kathy Wilner

ВІ



North Side

Notes
Ruf School
6/12/2018
Kathy Wilner

