NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM					
	PAGE 1	SITS# 32_B	к 189		
SITE IDENTIFICATION					
Field Code Dimond Township School	Site Name				
Map Quad Thompson Lake	Site Name				
LTL TWP60 R91 SEC LTL TWP R SEC LTL TWP R SEC LTL TWP R SEC LTL TWP R SEC	QQQ	QQ	Q <u>5</u> Q Q Q		
UTMN UTME	ZONE NAD 1927	NAD 1983	Subsection: $1 = N\frac{1}{2}$		
City:			$2 = E\frac{1}{2}$ $3 = S\frac{1}{2}$		
Street Number:			$4 = W\frac{1}{2}$ $5 = NE\frac{1}{4}$		
Street Name: 79th Ave NW			6 = SE¼ 7 = SW¼		
Urban Legal Description:			8 = NW1⁄4		
SITE DATA					
Total # Architectural Features:1					
Fieldwork Date: 7/14/2016					
Reconnaissance Survey 🖌 Intensi	ve Survey				
Project Title & Supervisor: Country Schoolhouse Project					
Report Title & Author(s):					
Additional Information:					
SHSND USE Area of Significance Area of Significance Area of Significance	Verified Site Non-Site	_ CR Type	2		
Recorded By Kathy Wilner (First Name & Last Name)	Date	Recorded	1/29/2017 (mm/dd/year)		

NDCRS 2009

NDCRS	ARCH	ITECTURAL	. SITE	FORM
	PAGE	2—Feature	Data	

Field Code Dimond Township School		SITS# 32_BK			
Complete one Page 2 for each architectural feature at the site.					
Architectural Feature #1					
Construction Date	Feature Type <u>9</u>	Condition 6			
Feature Date 3	Context 7	Plan Shape <u>5</u>			
Structural System 25	Primary Exterior <u>26</u>	Style <u>Other Style</u>			
Original Owner's Ethnicity	Secondary Exterior	Architect/Builder			
Other Information:					
Foundation Concrete		Stories <u>1</u>			
Roof/Cornice.Gable					
Window Double hung, glass					
Dating Method(s): Estimate					
Feature Preservation Recommendation(s) (Check all that apply):					
Individual nomination					
Contributes to a potential district					
No nomination potential					
Will not contribute to a district					
Potential district—feature would be a contributing element if other properties constitute a district					
Thematic nomination potential					
Component of a historic site or landscape					
Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in contextwith neighboring structures; d) relocation has damaged eligibility					
Historical associations require further investigation					

Recorded By	Kathy	Wilner	Date Recorde	ed 1/29/2017
(1	First Name & Last Name)			(mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Dimond Township School

SITS# 32_BK

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a concrete foundation. The gable roof of the entry and the main body of the school are covered with asphalt shingles. Some metal capping and finials. There is a red brick chimney at the peak of the west end of the roof. The soffits are closed. The building measures 28 feet east to west and 16 feet north to south, the entry mearures 10 feet north to south by 8 feet east to west.

There is a wide trim board on the wall under the soffits at the peak ends of the school and entry. The remainder of the siding is 6 inch wood lap with 6 inch wood trim. The entry is reached by way of a concrete step. The south facing door is 5 panel wood and gives entry to a room with beadboard walls and ceiling. The main body of the school has wallboard on the top third of the walls with beadboard walls and ceiling. The main body of the school has wallboard on the top third of the walls with beadboard walls and ceiling. The main body of the school has wallboard on the top third of the walls with beadboard walls and ceiling. The main body of the school has wallboard on the top third of the walls with beadboard walls and ceilings) and the remainder of the ceiling is also covered with wallboard. The floor is tongue and groove hardwood. The north wall of the entry has a boarded and resided window opening, three more sided over window openings are seen on the north side of the main body of the school. The interior wallboard covers any evidence of windows on the north wall inside. On the east wall of the entry is another boarded up and sided over opening. The south side of the building has three double hung, two over two, windows with glass intact. There is a blackboard on the entire west wall and a fuel oil stove sits in the northwest corner, with stove pipe connected to the chimney. A fuel oil barrel is at the west end of the building, right next to the wall. This place was apparently used for lodging at some point. Light fixtures suggest electricity.

Recorded By Kathy Wilner
(First Name & Last Name)

Date Recorded

1/29/2017 (mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Dimond Township School

SITS# 32_BK____

Complete one Page 4 for the entire site.

2. Owner's Contact Information:

3. Access (to rural areas):

This building can be accessed from Highway 8, north of the Highway 8 and 50 junction about 8 miles. The road curves to the east and a gravel road, 79th Ave NW, continues straight north. Drive about 1/2 mile north on 79th Ave NW to see the school on the left. It is 1/2 mile south of 87th St NW.

4. Site Area (ft²):_____

5. Description of **SETTING**:

There is an abandoned farm site to the west with hills, some crop land and pasture all directions.

Recorded By Kathy Wilner Date Recorded 1/29/2017
(First Name & Last Name) (mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 5-SITE DESCRIPTION

Field Code Dimond Township School

SITS# 32 BK

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By (First Name & Last Name) Kathy Wilner

Date Recorded

1/29/2017 (mm/dd/year)




East Side

Dimond Township School 7/14/2016

Kathy Wilner

BK





North Side

Dimond Township School 7/14/2016 Kathy Wilner BK

South Side



8/5/2016

bing maps

Notes

Dimond Township School 7/14/2016 Kathy Wilner BK





Feature