NDCRS 2009

NDCRS	ARCHITECTURAL	SITE	FORM
	PAGE 1		

	PAGE 1	SITS# 32	вк 194
SITE IDENTIFICATION		0110// 02_	
Field Code Garness Township School			
Map Quad Lunds Valley Map Quad	Site Name		*****
LTLTWP159R92 LTLTWPR LTLTWPR LTLTWPR	SEC QQQ SEC QQQ	6 QQ 7 QQ QQ QQ QQ	Q 7 Q Q
UTM UTM		= 1927 NAD 1983	Subsection: $1 = N\frac{1}{2}$ $2 = E\frac{1}{2}$
City:			3 = S½
Street Number:			$4 = W\frac{1}{2}$ $5 = NE\frac{1}{4}$
Street Name: 90th St NW			6 = SE¼ 7 = SW¼
Urban Legal Description:			8 = NW1⁄4
SITE DATA			
Total # Architectural Features:	1		
Fieldwork Date: 8/21/2016			
Reconnaissance Survey 🗹	Intensive Survey		
Project Title & Supervisor: Country Schoolhouse Project			
Report Title & Author(s):			
Additional Information:			
SHSND USE Area of Significance Area of Significance Area of Significance	ZIVerified Si Non-Site		pe _2_
	Wilner	Date Recorded	1/29/2017
(First Name & Last Name)			(mm/dd/year)

State Historical Society of North Dakota

NDCRS 2009

NDCRS	ARCHITECTURAL SITE FO	RM
	PAGE 2—Feature Data	

Recorded By Kat (First Name & Last Name	thy Wilner		/29/2017 mm/dd/year)
Historical associations requ	ire further investigation		
recreates original site, orien with neighboring structures;			e in context
Moved (specify all applicable choices)a) relocation occurred within a historic period; b)			
Component of a historic site or landscape			
Thematic nomination potential			
Potential district—feature would be a contributing element if other properties constitute a district			
Will not contribute to a district			
No nomination potential			
Contributes to a potential di	strict		
Individual nomination			
Feature Preservation Recomm	endation(s) (Check all	that apply):	
Dating Method(s): Estimate			
Window Double hung, most covered			
Other Information:			
	· ·		
Original Owner's Ethnicity	Secondary Exterior		
Structural System 25	Primary Exterior _26		
Feature Date 3	Context 7	Plan Shape 5	
Construction Date	Feature Type <u>9</u>	Condition 6	
Architectural Feature #1			
Complete one Page 2 for ea	<u>ch architectural featu</u>	re at the site.	
Field Code Garness Township Sc	hool	SITS# 32_BK	unida urabitational de Aldreite de Aldr
	rage z-reature		

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Garness Township School

SITS# 32_BK____

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a foundation of rocks and concrete. The gable roof of the main body and the entry are covered with asphalt shingles. The chimney is gone and the soffits are closed. The building measures 24 feet north to south and 16 feet east to west with the entry measuring 4 feet north to south and 12 feet east to west.

There is a wide trim board on the wall under the soffits at the peak ends of the school and entry. The remainder of the siding is 6 inch wood lap with 6 inch wood trim. The entry was added on to on the west side at some point and that addition has a shed roof. It was created for bathrooms, there are two vents on the slope of the roof and two small, covered openings at the bottom of the wall which I suspect were used to get rid of waste. There is also a covered window on the west wall of the addition. The 5 panel wood door is falling away from the hinges. The entry is reached by three concrete steps to a concrete platform. The interior of the entry has three doors, one to the left into a coat room with a covered window, another straight west into the bathroom addition and the third door into the school proper. The entry walls are covered with beadboard. The door into the main room is covered with paneling on the school room side, perhaps to match the paneling that covers the walls inside the school room. The ceiling is covered with particle board. On the west wall the paneling covers three shuttered windows. The east wall shows two shuttered windows that are also paneled over inside with only one double hung, two over two, window on the east side at the north end for light in the room. There are light fixtures on the ceiling that suggest electricity. The floor in the entry is tongue and groove hardwood and the main room of the school has linoleum over hardwood. A fuel oil stove sits near the north wall. There is shop equipment, some furniture and a mixture of things stored here.

Recorded By Kathy Wilner Date Recorded 1/29/2017
(First Name & Last Name) (mm/dd/year)

State Historical Society of North Dakota

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Garness Township School

SITS# 32_BK_____

Complete one Page 4 for the entire site.

2. Owner's Contact Information:

3. Access (to rural areas):

East of Powers Lake 2 miles to Highway 89. Turn left and go north 3 miles to 82nd St NW, turn right and drive east 1/4 mile to see the school on the north side of the road.

4. Site Area (ft²):_____

5. Description of SETTING:

Open, hilly grassland/pasture with some farm fields to the west.

Recorded By Kathy Wilner Date Recorded 1/29/2017
(First Name & Last Name) (mm/dd/year)

State Historical Society of North Dakota

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Garness Township School

SITS# 32_BK_____

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By Kathy Wilner Date Recorded 1/29/2017 (First Name & Last Name) (mm/dd/year)




West Side

Garness Township School8/21/2016Kathy WilnerBK

North Side





South Side

Garness Township School

8/21/2016

Kathy Wilner

BK

East Side




9/13/2016

Bing Maps - Directions, trip planning, traffic cameras & more

bing maps

Notes

(Barness Township School
	8/21/2016
	Kathy Wilner
	ВК
-	





Feature