×.

### NDCRS ARCHITECTURAL SITE FORM PAGE 1 SITS# 32

	PAGE 1	SITS# 32	BI 778
SITE IDENTIFICATION		3113# 32 <u></u>	
Field Code Frances Township School		es Township School	
Map Quad <u>Solberg Butte</u> Map Quad	Site Name		<u>,,,, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>
LTL TWP R SE LTL TWP R SE	C     18     QQQ     6       C     QQQ     QQQ       C     QQQ     QQQ       C     QQQ     QQQ	QQ	
UTMN UTME	ZONE NAD 192	7 NAD 1983	Subsection: $1 = N\frac{1}{2}$ $2 = E\frac{1}{2}$
City:		-	3 = S½
Street Number:		-	$4 = W^{1/2}$ 5 = NE <sup>1/4</sup>
Street Name: 123rd Ave NE	<u> </u>	_	6 = SE¼ 7 = SW¼
Urban Legal Description:		_	8 = NW <sup>1</sup> ⁄ <sub>4</sub>
SITE DATA			
Total # Architectural Features:1			
Fieldwork Date: 7/11/2014			
Reconnaissance Survey <u>/</u> Inte	ensive Survey		
Project Title & Supervisor:			
Country Schoolhouse Project			
Report Title & Author(s):			
Additional Information:			
SHSND USE Area of Significance Ecozone Area of Significance Ecozone	Verified Site Non-Site		2
Recorded By Kathy Wi	iner E	ate Recorded	218/2015
(First Name & Last Name)			(mm/dd/year)

3

.

NDCRS	ARCH	ITECT	URAL	SITE	FORM
	PAGE	2—Fea	ature l	Data	

Field Code Frances Township School		SITS# 32BL		
Complete one Page 2 for each architectural feature at the site.				
Architectural Feature #1				
Construction Date	Feature Type <u>9</u>	Condition <u>3</u>		
Feature Date	Context 7	Plan Shape 5		
Structural System 25	Primary Exterior <u>26</u>	Style Other Style		
Original Owner's Ethnicity	Secondary Exterior	Architect/Builder		
Other Information:				
Foundation Concrete		_ Stories1		
Roof/Cornice Gable	,	<u> </u>		
Window Mostly destroyed, were double hung				
Dating Method(s): professional estimate				
Feature Preservation Recommendation(s) (Check all that apply):				
Individual nomination				
Contributes to a potential district				
No nomination potential				
Will not contribute to a district				
Potential district—feature would be a contributing element if other properties constitute a district				
Thematic nomination potential				
Component of a historic site or landscape				
Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in contextwith neighboring structures; d) relocation has damaged eligibility				
Historical associations require further investigation				
Recorded By Kati (First Name & Last Nam		Recorded <u>2/8/2015</u> (mm/dd/year)		

## NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Frances Township School

SITS# 32	BL
----------	----

#### Complete a Page 3 for each feature.

#### 1. Feature Description, Integrity, Eligibility:

This feature is a one room prairie school sitting on a concrete foundation. The building measures 18 feet east to west. The main body of the school is 24 feet 4 inches north to south with an entry measuring 16 feet east and west by 8 feet north to south.

There are asphalt shingles over roof sheathing, much of which is missing. There are holes in the roofing of the entry as well as a hole where the chimney used to rest at the north end of the school. A wide header board can be seen under the eaves at the peaked end of the building. The siding is 6 inch wood lap with little or no paint. There are two vents at the north end of the building under the peak of the roof and one more at the south end.

The windows are all gone, very little framing left and no glass. There are three window openings on both the east and west walls of the school, one is covered with metal sheeting. Two more window openings face south, either side of the door opening.

The inside of the entry is covered with bead board. Tongue and groove hard wood covers the floor in both rooms. At the northwest corner of the school there is a raised area that looks like a small stage. The walls and ceiling have some lathe and plaster as well as wall board and all if it is in really tough shape. Many areas only have lathe remaining and the ceiling has little covering left. Wainscoat can be seen in both entry and main room of the school. There was electricity at some point incidated by wires and switch boxes. A blackboard ran along the north wall, about 1/4 of that remains.

Recorded By Kathy Wilner (First Name & Last Name) Date Recorded 2/8/2015 (mm/dd/year)

• • •

## NDCRS ARCHITECTURAL SITE FORM PAGE 4-SITE DESCRIPTION

Field Code Frances Township School

SITS# 32\_\_\_\_\_BL

### Complete one Page 4 for the entire site.

2. Owner's Contact Information:

State of North Dakota

3. Access (to rural areas):

On Highway 83, at 97th Ave drive east 7 miles and turn north. Drive two miles, turn right and drive east 2 1/2 miles. The school will be on your left (north side of the road).

4. Site Area (ft<sup>2</sup>):

5. Description of SETTING:

The country around the school is hilly with pasture and hay land. There is a farm site 1/2 mile to the west.

Recorded By Kathy Wilner
(First Name & Last Name)

Kathy Wilner Date Recorded 2/8/20/5 (mm/dd/year)

NDCRS 2009

# NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION


Field Code Frances Township School

SITS# 32\_\_\_\_\_BL\_\_\_

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By Kathy Wilner Date Recorded 2/8/2015 (First Name & Last Name) (mm/dd/year)





BL



East Side

Frances Township School

7/11/2014 Kathy Wilner BL



North Side

