٠

.

# NDCRS ARCHITECTURAL SITE FORM PAGE 1 SITS# 32\_\_\_\_\_BL 781

SITE IDENTIFICATIO	N				
Field Code Lyman To	wnship School				
Map Quad Wing S Map Quad	5E	Sile		<u></u>	<del></del>
LTL TWP141 LTL TWP LTL TWP LTL TWP	R	SEC SEC SEC SEC		QQ QQ	Q 6 Q Q
UTM UTM		N E	ZONE NAD 1927	NAD 1983	Subsection: $1 = N\frac{1}{2}$ $2 = E\frac{1}{2}$
City:					$3 = S^{1/2}$ $4 = W^{1/2}$
Street Number: 3080	0				5 = NE¼
Street Name: 214th A	ve NE				6 = SE¼ 7 = SW¼
Urban Legal Descript	ion:		<u></u>		8 = NW1⁄4
SITE DATA					
Total # Architectural	Features:	1			
Fieldwork Date:	6/10/2014				
Reconnaissance Surv	vey 🖌	Intensive Su	rvey		
Project Title & Superv Country Schoolhouse					
Report Title & Author	(s):				
Additional Information	n:	<u></u>			
SHSND USE Area of Significance			Verified Site Non-Site	CR Type	2
Recorded By		/ Wilner	Date	Recorded	2/8/2015 (mm/dd/year)
(First	Name & Last Name)				(minuter year)

i.

.

NDCRS	ARCH	ITECI	<b>URAL</b>	SITE	FORM
	PAGE	2Fe	ature	Data	

Field Code Lyman Township School	SITS# 32	BL		
Complete one Page 2 for each	architectural feature at th	e site.		
Architectural Feature #1				
Construction Date	Feature Type <u>9</u>	Condition 6		
Feature Date	Context 7	Plan Shape 6		
Structural System 25	Primary Exterior <u>26</u>	Style <u>Other Style</u>	9	
Original Owner's Ethnicity	Secondary Exterior	Architect/Builde	r	
Other Information:				
Foundation Concrete		_ Stories1		
Roof/Cornice_Hip	·····			
Window Double hung				
Dating Method(s): <u>Similarity</u> 4	e Florence Lake ?	School	<u></u>	
Feature Preservation Recommen	dation(s) (Check all that app	oly):		
Individual nomination				
Contributes to a potential distri	ct			
No nomination potential				
Will not contribute to a district				
Potential district—feature would be a contributing element if other properties constitute a district				
Thematic nomination potential				
Component of a historic site or landscape				
Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility				
Historical associations require further investigation				
Recorded By Kathy (First Name & Last Name)	Wilner Date	Recorded	2/8/2015 (mm/dd/year)	

# NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Lyman Township School

SITS# 32 BL

### Complete a Page 3 for each feature.

#### 1. Feature Description, Integrity, Eligibility:

This feature is a large one room prairie school sitting on a concrete foundation. The building may have been moved to this location as I think the area might have been farm site at one time. The roofing material consists of remnants of old asphalt shingles over wood shakes on wood sheathing. Most of the asphalt shingles are gone. There is a concrete block chimney on the west end of the north slope. The eaves are enclosed with beadboard soffits. At the east end of the school there is a large dormer with asphalt shingle for wall covering and an interesting opening that is boarded up. The building measures 45 1/2 feet east to west and 24 feet north to south.

A wide header runs around the school just under the eaves. The remainder of the siding is 6 inch wood lap with 8 inch wood corner trim. There are several windows, many with glass still intact. On the south side there is a bank of 6 large, double hung, multi pane windows. One small window to the east of the large windows and yet another near the west end of the school. There is also remnants of a door to the left of the large windows. On the east side of the school there is a garage door, allowing access for work as a shop. On the north side there is a window near the west end of the building and two more on the north side. Only one window is covered.

The entry door on the east is a 5 panel wood door. Inside the building I see tongue and groove hardwood flooring, lathe and plaster (and some wall board) on the walls with plaster falling away in areas. There is wallboard on the ceiling, some of that falling down as well. One electric light fixture still has the white milkglass fixture. The blackboards remain on most of the north wall and about 1/3 of the west wall. There is no wainscoat. The west end of the building is another room/rooms. Perhaps this was an entry at some point. No indication of a heat source other than the chimney.

Recorded By	Kathy Wilner	Date Recorded	2/8/2015
······································	(First Name & Last Name)		(mm/dd/year)

**NDCRS 2009** 

# NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Lyman Township School

SITS# 32\_\_\_\_\_BL

### Complete one Page 4 for the entire site.

2. Owner's Contact Information: Jason Siirtola

304 Hill St. Wing ND 58494

3. Access (to rural areas):

This school is located west of Highway 14, north of Sterling exit 14 miles. At 214th Ave. NE turn left (west) and drive about 1/2 mile. It is on the north side of the road.

4. Site Area (ft<sup>2</sup>):\_\_\_\_\_

5. Description of SETTING:

Trees to the west and north with fields to the east and south. There are two big rock piles in the yard as well as an abandoned mobile home.

Recorded By Kathy Wilner Date Recorded 2/8/2015 (First Name & Last Name) (mm/dd/year)

**NDCRS 2009** 

### NDCRS ARCHITECTURAL SITE FORM PAGE 5-SITE DESCRIPTION

Field Code Lyman Township School

SITS# 32\_\_\_\_\_BL\_\_\_

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By Kathy Wilner Date Recorded 2/8/2015 (First Name & Last Name) (mm/dd/year)



East Side

Lyman Township School6/10/2014Kathy WilnerBL

South Side



North Side

Lyman Township School	6/10/2014	Kathy Wilner	ВК
West Side			
	İ		



-89-