τ.

NDCRS ARCHITECTURAL SITE FORM PAGE 1 SITS# 32

| | PAGE 1 | 0170 // 00 | DI 787 |
|---|--|---------------|---|
| SITE IDENTIFICATION | | SITS# 32 | <u>BL 704</u> |
| Field Code Cromwell Township School | | | |
| Map Quad <u>Regan SE</u> Map Quad | Site Name | | |
| LTL TWP R SEC | 2 <u>17</u> <u>000</u> <u>8</u> 2 <u>000</u> | QQ | Q <u>8</u> Q Q |
| UTMN UTME | ZONE _ NAD 19 | 27 NAD 1983 | Subsection: $1 = N\frac{1}{2}$ $2 = E\frac{1}{2}$ |
| City: | | | 3 = S½ |
| Street Number: | | | 4 = W ¹ / ₂ 5 = NE ¹ / ₄ |
| Street Name: 214th Ave NE and 119th St. NE | Ξ | | 6 = SE¼ 7 = SW¼ 8 = NW¼ |
| Urban Legal Description: | | | |
| SITE DATA | | | |
| Total # Architectural Features:1 | | | |
| Fieldwork Date: 7/11/2014 | | | |
| Reconnaissance Survey 🖌 Inter | nsive Survey | | |
| Project Title & Supervisor: Country Schoolhouse Project | | | |
| Report Title & Author(s): | | | |
| Additional Information: | | | |
| SHSND USE Area of Significance Area of Significance Area of Significance Area of Significance | Verified Site Non-Site | | 2 |
| Recorded By Kathy Wilr (First Name & Last Name) | ner | Date Recorded | 2/8/2015 (mm/dd/year) |

1

÷

NDCRS 2009

.

| NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data | | | | |
|---|-----------------------|-----------------|--------------------------|--|
| Field Code Cromwell Township School | | SITS# 32_ | BL | |
| Complete one Page 2 for each architectural feature at the site. | | | | |
| Architectural Feature # | 1 | | | |
| Construction Date | Feature Type <u>9</u> | Condition 5 | | |
| Feature Date | Context 7 | Plan Shape | 5 | |
| Structural System 25 | Primary Exterior 26 | Style_Other S | tyle | |
| Original Owner's Ethnicity | Secondary Exterior | Architect/Bui | der | |
| Other Information: | | | | |
| Foundation Concrete | | Stories1 | _ | |
| Roof/Cornice_Gable, the south | | | | |
| Window Mostly gone, parts of f | rames in some | | | |
| Dating Method(s): professional estimate | | | | |
| Feature Preservation Recommendation(s) (Check all that apply): | | | | |
| Individual nomination | | | | |
| Contributes to a potent | ial district | | | |
| No nomination potential | | | | |
| Will not contribute to a district | | | | |
| Potential districtfeature would be a contributing element if other properties constitute a district | | | | |
| Thematic nomination potential | | | | |
| Component of a historic site or landscape | | | | |
| Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, & spatial relationships; c) compatible in contextwith neighboring structures; d) relocation has damaged eligibility | | | | |
| Historical associations require further investigation | | | | |
| Recorded By | Kathy Wilner | _ Date Recorded | 2/8/2015 (mm/dd/year) | |

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Cromwell Township School

| | SITS# | 32 | BL |
|--|-------|----|----|
|--|-------|----|----|

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a poured concrete foundation. The material used for roofing is wood shakes on the main body and the entry of the school. The addition to the south has remnants of asphalt shingles on wood sheathing. The concrete block chimney is located at the south end of the main body of the school. The main body and south addition of the school measure 36 feet north to south and 18 feet 8 inches east to west. The entry measures 10 feet 8 inches east to west and 7 feet north to south. The eaves have closed soffits.

There is a 8 inch header under the eaves at both peaks of the school with small vents at the peak as well. The outside walls of the school are 6 inch wood lap siding with 4 inch corner trim. The shed on the south side has board lumber with little lap siding on it. Very little paint on any of it.

The windows are all gone, very little framing remains in the openings. There was a bank of 5 windows in the main school room and two more windows in the entry. The shed at the south end has a door and two more window openings. The one to the west in this shed is the only one covered. Access is gained by way of concrete steps. The old wood door at the entry is broken, with holes and the door into the main room of the school is also in tough shape. The floor in the entry and school is tongue and groove hardwood. The walls and ceiling are wallboard. The blackboards were on the west wall and the east half of the south wall.

The addition to the south was most likely used for storage. Access from the school was by way of a wood door with panes of glass at the top. Glass was either broken or gone. Evidence of electricity with wires outside the north wall.

Recorded By Kathy Wilner Date Recorded 2/8/2015 (First Name & Last Name) (mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 4-SITE DESCRIPTION

Field Code Cromwell Township School

SITS# 32_____BL

Complete one Page 4 for the entire site.

2. Owner's Contact Information:

A William Lucas ETAL

No other information

3. Access (to rural areas):

Highway 83 north of Bismarck to 201st Ave NW. This will be the turn for Baldwin. Drive 9 miles east and at 119th St. NE turn left (north) and drive about 1 miles. It will be on your right.

4. Site Area (ft²): _____

5. Description of SETTING:

There is a home to the southwest of the school and all other directions are pastures and fields in gently rolling land.

Recorded By Kathy Wilner Date Recorded 2/8/2015
(First Name & Last Name) (mm/dd/year)

NDCRS 2009

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION


Field Code Cromwell Township School

SITS# 32_____BL___

6. Summary of ALL Site Features & Evaluation of Significance:

7. References/Comments: Kathy Wilner 366 43rd Ave SE Bowdon ND 58418

Recorded By Kathy Wilner Date Recorded 2/8/2015 (First Name & Last Name) (mm/dd/year)





West Side

Cromwell Township School

7/11/2014 Kathy Wilner

BL



South Side

