### NDCRS ARCHITECTURAL SITE FORM PAGE 1

	PAGE		109
SITE IDENTIFICATION		SITS# 32	BL TO I
Field Code Pleasant View School			
Map Quad Mercer 5E Map Quad			
		QQ QQ	a <u>5</u> a
UTMN		 27 NAD 1983	Subsection: 1 = N½
City:	····		2 = E½ 3 = S½
Street Number:			4 = W½ 5 = NE¼
Street Name: 145th St NE + 4	35th Ave NE	_	6 = SE½ 7 = SW¼ 8 = NW¼
Urban Legal Description:		_	0 = INVV /4
SITE DATA			
Total # Architectural Features: 1	<u> </u>		
Fieldwork Date: 7/9/2014			
Reconnaissance Survey ✓ Int	tensive Survey		
Project Title & Supervisor: Country Schoolhouse Project			
Report Title & Author(s):			
Additional Information:			
Area of Significance Ecozone Ecozone	Verified Site Non-Site		2
Recorded By Kathy Wi	Iner	Date Recorded	2/9/2015 (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

# NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code Pleasant View School		SITS# 32_	BL
Complete one Page 2 for ea	ach architectural feature	at the site.	
Architectural Feature #1	nouse—		
Construction Date	Feature Type9	Condition 5	<del></del>
Feature Date	Context 7	Plan Shape	5
Structural System 25	Primary Exterior <u>26</u>	Style Other S	tyle
Original Owner's Ethnicity	Secondary Exterior	Architect/Buil	der
Other Information:			
Foundation Poured Concrete		Stories1	_
Roof/Cornice Hip roof, main body	Gable roof, entry		
Window Side sliders, awning windo	ows, other		
Dating Method(s): profession	al estimate		***************************************
Feature Preservation Recomm	nendation(s) (Check all tha	at apply):	
Individual nomination			
——Contributes to a potential d	listrict		
No nomination potential			
Will not contribute to a dist	rict		
Potential district—feature v	vould be a contributing elemen	t if other properties co	onstitute a district
Thematic nomination poter	ntial		
——Component of a historic sit	e or landscape		
recreates original site, orie	ole choices)—a) relocation occi ntation, landscape, & spatial re s; d) relocation has damaged el	lationships; c) compa	
Historical associations requ	uire further investigation		
Recorded By Ka		Date Recorded	2/9/2015 (mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

### NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

		+ +- <del></del> -	
Field Code Pleasant View School	<del></del>	SITS#	32BL

#### Complete a Page 3 for each feature.

#### 1. Feature Description, Integrity, Eligibility:

The feature is a large wood framed prairie school. It may have been two or four rooms, depending on what use they made of the basement. The hip roof of the main body of the school is covered with wood shakes over wood sheathing. At the peak and at all four corners of the roof there is metal ridge capping with ball finials at the endw on the peak of the roof. The peaked roof of the entry is also covered with wood shakes topped by a metal ridge cap with a ball finial at the outside end. There is a flag pole at the peak of the entry roof. A red brick chimney with concrete cap is located on the west slope of the hip roof. There is an air exchanger at the point where the entry roof ties into the hip roof for allowing the hot air to get out of the attic space. The eaves are closed with beadboard finishing the soffits.

The building measures 56 feet north to south and 28 feet east to west. The entry is 5 feet deep by 20 feet wide.

The building sits high on the poured concrete basement. The concrete walls above the ground are decorative in nature on the north and south sides. There are several covered windows in the basement, 3 both north and south and 6 on the west side. There are also two covered windows at either side of the entry, located below the wood walls of the school. The walls of the school are 6 inch wood lap with 4 inch wood corner trim. Paint is getting tired. There is a wide header running under the eaves on all four sides as well as at the peaked end of the east entry. Windows are a hodgepodge. On the east side entry there are two large miltipane windows with some of the glass is missing. In the middle of the entry is a 5 panel wood door in the middle. Part of the door has been broken in. Above the windows and door there is a small roof piece for decoration with a moon shaped opening above that, under the roof peak. The north wall has three sets of two side slider windows, the west side has two very small, fixed pane windows and on the south side there is a bank of 4 fairly large windows, fixed on the top and awning windows at the bottom. Also on the south side there as another 5 panel wood door, reached by some rickety looking wood steps.

I didn't go into the school but could look through broken door. I saw stairs curving off to the north and south of the entry, going to the basement. Looking straight in the door I saw a wide wood staircase leading up to the classroom level. Wainscot was either side of the stairs as well as the wall at the top. Entry into the school was through a door opening that had a transom above it, glass intact. The floor I saw was tongue and groove hardwood. Walls of lathe and plaster, ceiling as well. A light fixture above the entry shows electricity the prescence of electricity in the school.

Recorded By	Kathy Wilner	Date Recorded	2/9/2015
•	(First Name & Last Name)		(mm/dd/year)

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

DI

### NDCRS ARCHITECTURAL SITE FORM **PAGE 4—SITE DESCRIPTION**

Field Code Pleasant View School	SITS# 32	BL
Complete one Page 4 for the entire site.		
2. Owner's Contact Information:  David Pudwill 43250 145th St NE Regan ND 58477		
3. Access (to rural areas):		
Highway 41, north of Wilton about 8 or 9 miles to 435th Ave NE.	Turn right and drive ea	st 9 miles.
4. Site Area (ft²):		
5. Description of <b>SETTING</b> :		
Field to the south, east and north, farm site to the southwest and	CRP to the west.	
Recorded By Kathy Wilner	Date Recorded	2/9/2015
(First Name & Last Name)		(mm/dd/year)

(mm/dd/year)

# NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Pleasant View	School	SITS# 32_	BL
6. Summary of ALL Site Features & Evaluation of Significance:			
7. References/Comments:			
Kathy Wilner			
366 43rd Ave SE Bowdon ND 58418			
Recorded By	Kathy Wilner	Date Recorded	2/9/2015

Instructions to complete a digital version of this form: (1) Download a copy to your hard drive; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately and save; (5) Print and submit to SHSND.

(First Name & Last Name)



East Side

Pleasant View School

7/9/2014

Kathy Wilner BL

### South Side





North Side

Pleasant View School

7/9/2014

Kathy Wilner


BL

West Side



CODE: BQ

R-78-W



7-A NEW JOHNS LAKE

AT AL AD BL BK

BJ AJ-AK AP BN BY AU

AR AS AG AH BV BC AY

BM AC BH AO BP AE AF

AV-AW AQ BE BD BR AI

AZ AA AB BA BS BU

AN BF BT BG BB BW

BURLEIGH COUNTY
©) COPYRIGHT 2004 GREAT PLAINS DIRECTORY SERVICE