NDCRS SITE FORM ARCHITECTURAL SITES Page 1

	SITS # 3 2 .B.o9.0.4			
	Field Code Sull H Site Name Hours and School Site Name			
SITE DATA	Map Quad			
FEATURE DATA	# of Features			
SHSND USE	221 Soil Association 22 Ecozone 3 Area Signf MS Number Soil Association			
•	Coder LI + TI Date Coded 8/3/97			
Reconnaissance Survey His :				
	Manuscript/Report Title: SIV 3 3 31111 County			
	Author(s):			

NDCRS ARCHITECTURAL SITE FORM

		page 1A				
Field Code 30 114	Featur	e Number	SITS # <u>32</u>			
DESCRIPTIVE SECTION						
		ROOF TYPE				
WINDOW CONDITION	rele	DATING METHOD)			
fair		neighbor's a	gount			
PRESERVATION RECOMM	IENDATION					
1) Individual Nomination 3) No nomination potents 5) Potential district not lead to the neighboring properties 6) Thematic nomination	ntial 4) cnown at this to s constitute a d	_ Will not contribute ime: feature would be listrict	to district e a contributing element if			
6) Thematic nomination potential 7) Component of historic site/landscape 8) Feature has an important physical, spatial, functional, historic or architectural relationship to the site/complex/farmstead 9) Moved: A) relocation occurred within historic period. B) recreates original site, orientation, landscape and spatial characteristics. C) compatible in context with neighboring structures. D) relocation has damaged eligibility. 10) Request comparative study of neighboring properties 11) Historical associations require further investigation						
DESCRIPTION/INTEGRITY	/ELIGIBILIT	Y				
double-hung window in this e four double-hung windows far fair condition, with much of the	s exterior is hold shingles, and south is attack ntryway facing cing south, but ne glass out. It classroom, bes	orizontal wood siding. It is a brick chimney hed to the west end of g west, two double-hut none on the north sidentry to the school by ide the blackboard.	Its gable roof is aligned east at the east end. A hip roof the schoolhouse. There is one ing windows facing east, and de. These windows are in only the entryway on the west end the interior has plaster walls and			

The building lacks associations or distinction sufficient for National Register consideration.

Urban Legal Description	
Croan Begar Description	
SEE CONTINUATION SHEET	

Photographic Coverage, Historic Architectural Survey of Bowman County, 1997

Roll AA Frame 25 Site SU //4 Feature Date 8/3 View from 5 w

Subject: Hammond School



Roll BB Frame / Site SU //4 Feature Date 8/3 View from NE Subject:



Photographic Coverage, Historic Architectural Survey of Bowman County, 1997

Roll BB Frame 2 Site SU //4 Feature Date 8/3 View from SW

Subject: Entrance to Hammond S-Gool



