

NDCRS SITE FORM  
ARCHITECTURAL SITES  
Page 1

SITS # 32 B0 910

Field Code Su. 120 Site Name Schoolhouse  
Field Code \_\_\_\_\_ Site Name \_\_\_\_\_

Map Quad Bowman SE  
Map Quad \_\_\_\_\_

LTL <input type="checkbox"/>	Twp <u>130</u>	R <u>101</u>	Sec <u>7</u>	QQQ <u>6</u>	QQ <u>6</u>	Q <u>8</u>	1. N $\frac{1}{2}$
LTL <input type="checkbox"/>	Twp _____	R _____	Sec _____	QQQ _____	QQ _____	Q _____	2. E $\frac{1}{2}$
LTL <input type="checkbox"/>	Twp _____	R _____	Sec _____	QQQ _____	QQ _____	Q _____	3. S $\frac{1}{2}$
LTL <input type="checkbox"/>	Twp _____	R _____	Sec _____	QQQ _____	QQ _____	Q _____	4. W $\frac{1}{2}$
LTL <input type="checkbox"/>	Twp _____	R _____	Sec _____	QQQ _____	QQ _____	Q _____	5. NE $\frac{1}{4}$
LTL <input type="checkbox"/>	Twp _____	R _____	Sec _____	QQQ _____	QQ _____	Q _____	6. SE $\frac{1}{4}$
LTL <input type="checkbox"/>	Twp _____	R _____	Sec _____	QQQ _____	QQ _____	Q _____	7. SW $\frac{1}{4}$
LTL <input type="checkbox"/>	Twp _____	R _____	Sec _____	QQQ _____	QQ _____	Q _____	8. NW $\frac{1}{4}$
LTL <input type="checkbox"/>	Twp _____	R _____	Sec _____	QQQ _____	QQ _____	Q _____	9. C

City \_\_\_\_\_

Street # \_\_\_\_\_ Street # \_\_\_\_\_

Street Name \_\_\_\_\_ Street Name \_\_\_\_\_

# of Features 1

0.1 Feature # 0.9 Feature Type 5 Condition  
\_\_\_\_\_ Construction Date 0.7 Context \*  
4 Feature Date 5 Plan Shape \*  
2.5 Structural System \*\* 2.6 Primary Exterior \* \_\_\_\_\_ Secondary Exterior  
\_\_\_\_\_ Ethnic \_\_\_\_\_ Style \*  
0.8049.7 Fieldwork Date \_\_\_\_\_ Architect/Builder  
\_\_\_\_\_ Other Information

22.9 Soil Association 2.2 Ecozone 3 Area Signf \_\_\_\_\_ MS Number  
\_\_\_\_\_ Soil Association \_\_\_\_\_ Ecozone \_\_\_\_\_ Area Signf \_\_\_\_\_ MS Number  
2 CR Type 1 Verified Site \_\_\_\_\_ Non-Site 2 ECF 3 T F  
\_\_\_\_\_ State Registry 1 National Register

Coder LI + TI Date Coded 8/4/97

Reconnaissance Survey  Intensive Survey

Manuscript/Report Title: Survey of Bowman County

Author(s): Isert & Velure

SITE DATA

FEATURE DATA

SHSND USE

NDCRS ARCHITECTURAL SITE FORM

page 1A

Field Code SU 120 Feature Number 1 SITS # 32

DESCRIPTIVE SECTION

FOUNDATION	STORIES	ROOF TYPE / CORNICE
<u>poured concrete</u>	<u>1</u>	<u>hip</u>
WINDOW CONDITION		DATING METHOD
<u>poor</u>		<u>professional estimate</u>

PRESERVATION RECOMMENDATION (check all that apply)

- 1)  Individual Nomination
- 2)  Contributes to a potential district
- 3)  No nomination potential
- 4)  Will not contribute to district
- 5)  Potential district not known at this time: feature would be a contributing element if neighboring properties constitute a district
- 6)  Thematic nomination potential
- 7)  Component of historic site/landscape
- 8)  Feature has an important physical, spatial, functional, historic or architectural relationship to the site/complex/farmstead
- 9)  Moved: A) relocation occurred within historic period. B) recreates original site, orientation, landscape and spatial characteristics. C) compatible in context with neighboring structures. D) relocation has damaged eligibility.
- 10)  Request comparative study of neighboring properties
- 11)  Historical associations require further investigation

DESCRIPTION/INTEGRITY/ELIGIBILITY

This country schoolhouse sits upon its original school grounds, but it was moved slightly and turned around for positioning on a new foundation (the present foundation is not the original). This is a wood frame building on a foundation of poured concrete. The exterior is horizontal wood siding. The hip roof is covered with asphalt shingles. The school was built in about 1920. A hip roof addition spans the line of the east side of the school. All the walls of the original section of the school have tall, double-hung windows. The new addition has square windows on the east wall only. It appears that the entrance to the school during its active days was in the middle of this east wall, but the doorway has been covered over with siding and the steps removed. There is a small, shed-roofed entry way over a back door on the west side. There is one more door, ground level, on the south side of the new addition, but this door appears to have been a recent addition. The evidence is that after its use as a schoolhouse, this building was begun to be converted to some other use by a subsequent owner.

The modifications to this building make its integrity questionable, and at any rate, it lacks associations or distinction sufficient for National Register consideration.

Urban Legal Description \_\_\_\_\_  
 SEE CONTINUATION SHEET

Photographic Coverage, Historic Architectural Survey of Bowman County, 1997

Roll DD Frame 13 Site SU 120 Feature Date 8/4 View from SE

Subject: Schoolhouse



Roll DD Frame 13 Site SU 120 Feature Date 8/4 View from NW

Subject: Schoolhouse



376 II NW  
BOWMAN

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

103° 22' 30" 626 3.6 MI. TO U.S. 12 627000m E. 628 20' 629 630  
46° 07' 30"

