

NDCRS SITE FORM
ARCHITECTURAL SITES
Page 1

SITS # 32 BO 974

Field Code SU 190 Site Name Scariona Hills Ranch
Field Code _____ Site Name _____

Map Quad Talbot Butte
Map Quad _____

1. N½
2. E½
3. S½
4. W½
5. NE¼
6. SE¼
7. SW¼
8. NW¼
9. C

LTL	<input type="checkbox"/>	Twp	<u>132</u>	R	<u>101</u>	Sec	<u>23</u>	QQQ	<input checked="" type="checkbox"/>	QQ	<input checked="" type="checkbox"/>	Q	<input checked="" type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>
LTL	<input type="checkbox"/>	Twp	_____	R	_____	Sec	_____	QQQ	<input type="checkbox"/>	QQ	<input type="checkbox"/>	Q	<input type="checkbox"/>

City _____

Street # _____ Street # _____

Street Name _____ Street Name _____

of Features 2

SITE DATA

FEATURE DATA

<u>0.1</u> Feature #	<u>1.0</u> Feature Type	<u>7</u> Condition
<u>1.0.3</u> Construction Date	<u>2.7</u> Context *	<u>7</u> Plan Shape *
<input type="checkbox"/> Feature Date	<u>2.6</u> Primary Exterior *	<u>0.5</u> Secondary Exterior
<u>2.5</u> Structural System **	<input type="checkbox"/> Style *	<input type="checkbox"/> Architect/Builder
<input type="checkbox"/> Ethnic	<input type="checkbox"/> Fieldwork Date	_____ Other Information
<u>0.2</u> <u>1.2</u> <u>1.7</u>		

SHSND USE

230 Soil Association 22 Ecozone 2 Area Signf _____ MS Number
 _____ Soil Association _____ Ecozone _____ Area Signf _____ MS Number
 CR Type Verified Site Non-Site ECF T F
 State Registry National Register

Coder LIATI Date Coded 8/12/97

Reconnaissance Survey Intensive Survey _____

Manuscript/Report Title: _____

Author(s): Isabel & Valera

NDCRS ARCHITECTURAL SITE FORM

page 2

Field Code SU190

SITS # 32

===== FEATURE DATA =====

<u>02</u> Feature #	<u>09</u> Feature Type	<u>6</u> Condition
Construction Date	<u>07</u> Context	<u>5</u> Plan Shape
<u>4</u> Feature Date		
<u>25</u> Structural System**	<u>26</u> Primary Exterior*	Secondary Exterior
Ethnic	Style*	
<u>08/12/97</u> Fieldwork Date		Architect/Builder
		Other Information

===== DESCRIPTIVE SECTION =====

FOUNDATION TYPE	STORIES	ROOF TYPE / CORNICE
<u>poured concrete</u>	<u>1</u>	<u>gable</u>
WINDOW CONDITION	DATING METHODS	
<u>good - some closed off</u>	<u>professional estimate</u>	

PRESERVATION RECOMMENDATION (check all that apply)

- 1) Individual Nomination
- 2) Contributes to a potential district
- 3) No nomination potential
- 4) Will not contribute to district
- 5) Potential district not known at this time: feature would be a contributing element if neighboring properties constitute a district
- 6) Thematic nomination potential
- 7) Component of historic site/landscape
- 8) Feature has an important physical, spatial, functional, historic or architectural relationship to the site/complex/farmstead
- 9) Moved: A) relocation occurred within historic period. B) recreates original site, orientation, landscape and spatial characteristics. C) compatible in context with neighboring structures. D) relocation has damaged eligibility.
- 10) Request comparative study of neighboring properties
- 11) Historical associations require further investigation

DESCRIPTION/INTEGRITY/ELIGIBILITY

This schoolhouse is located southeast of the house that is feature 1. Dating from the 1910s, this is a wood frame building on a foundation of poured concrete. Its gable roof is covered with wood shingles, and its exterior is horizontal wood siding. The east end of this schoolhouse originally was the front entry, but the door and two windows on this side have been closed off. On the opposite end, a single door and two windows have been installed. Three new windows also have been installed on the south wall. This school, known as Buffalo School, was relocated to this farmstead.

The extensive modifications made to this building make it ineligible for the National Register.

Urban Legal Description _____

SEE CONTINUATION SHEET

SU190

SITE 32



Photographic Coverage, Historic Architectural Survey of Bowman County, 1997

Roll LLL Frame 6 Site SU 190 Feature 2 Date 8/12 View from SUR

Subject: Buffalo School



Roll LLL Frame 7 Site SU 190 Feature 2 Date 8/12 View from NE

Subject: Buffalo School



TALBOT BUTTE QUADRANG
NORTH DAKOTA—BOWMAN CO
7.5 MINUTE SERIES (TOPOGRAPHIC)

5376 IV SE
(AMIDON SE)

631

17'30"

632

633

1 300 000 FEET

