## NDCRS ARCHITECTURAL FORM PAGE 1

Field Code Oak Valley	School District 18	_	S	ITS# 32 BU	764	
Map Quad Bottineau		Site Na	me Oak \	/alley School		
Map Quad		Site Na	me			
LTL T. <u></u>	W., Sec W., Sec	QQQ of the QQQ of the	ne <b>QQ</b> ne <b>QQ</b>	_ of the <b>Q</b> _ of the <b>Q</b>	1 = N½	
NAD 1983 UTM NAD 1983 UTM Street Number:	393829	Zone <u>14N</u> -	-		4 = W½ 5 = NE¼ 6 = SE¼ 7 = SW¼ 8 = NW¾	
Street Name: North Ma	in Street		<u>.</u> .			
Urban Legal Description:						
Total Number of <b>Architec</b>	ctural Features:	1				
Fieldwork Date:7/1	8/2020					
Reconnaissance Survey	<u> </u>	Intensive Surv	әу			
Project & Principal Investi Country School House Pr Kathy Wilner 366 43rd Ave SE Bowdon ND 58418	_					
Contracting Firm or Agen	cy Completing the Fo	orm:				
Additional Information:						
SHSND USE Component Component Component	Study Unit	Verified Sit	e	_ CR Type	2	
Recorded By:	Kathy Wilne	r	Date R	ecorded: 8/6	6/2020	

## NDCRS ARCHITECTURAL FORM PAGE 2 – Feature Data

Field Code Oak Valley School District 1	8	SITS# 32	BU	
Complete one Page 2 for each archite	ectural feature at the site.			
Architectural Feature #1				
Construction Date1886				
Feature Date <u>1880-1900</u>				
Structural System Wood Frame				
Original Owner's Ethnicity				
Feature Type <u>9 - School; Church school</u>	L			
Context <u>Education</u>				
Primary Exterior <u>Wood, Horizontal</u>	Siding			
Secondary Exterior				
Condition <u>Excellent</u>				
Plan Shape <u>Rectangular</u>				
Style Other Style				
Architect/Builder				
Foundation Concrete		1		
Roof/Cornice Gable				
Window Double hung with glass				
Dating Method(s)Information on the from	nt of the school building			
Miscellaneous Information				
Feature Preservation Recommendation				
Individual nomination	on, o, tonoon an anacappiy,			
Contributes to a potential distric	t			
No nomination potential				
Will not contribute to a district				
Potential district—feature would	be a contributing element if o	ther propert	ties const	itute a district
Thematic nomination potential				
Component of a historic site or l	andscape			
Moved (specify all applicable ch site, orientation, landscape, and relocation has damaged eligibili	l spatial relationships; c) comp		-	
Historical associations require for	urther investigation			
Recorded By: Kathy	Wilner Date	Recorded	l:	8/6/2020

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

#### NDCRS ARCHITECTURAL FORM PAGE 3 – Feature Data

Field Code	Oak Valley School District 18	SITS# 32 BU
	,	

Complete one Page 3 for each architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

The feature is a one room school moved to the present location from somewhere between Bottineau and Gardena. It is sitting on a concrete foundation. A red brick chimney sits at the peak of the school at the west end of the roof. The roof is covered with wood shakes. The soffits are open.

A rake board begins the siding just under the roof at the peak ends. The remaining siding is 6 inch wood lap with 4 inch wood corner trim. The exterior of the school has a lovely coat of white paint. A 5 panel wood door gives acess to the interior of the school. This is reached by a new wood porch/walkway built to accomodate traffic. There is no separate entry or coat room. You enter directly into the school room. There are three two over two double hung windows on both the south and north sides of the school. All have intact glass and window shades. The walls and sloped ceiling of the school are covered with 2 x 4 wood boards, running the length of the school and installed horizontally on the walls. The same narrow wood boards run vertically along the lower third of the wall as wainscot. The floor is tongue and groove hardwood. A small wood burning stove is located about 8 feet straight inside the door with the stove pipe running up near the ceiling and then along the school room to the chimney, all held up with sires. No evidence of electricity. There is one blackboard on about 2/3 of the west wall.


The interior of this school is furnished with desks, books, teachers desk, wash stand, maps and much more. The school was built in 1886 and closed in 1941.

Owner's Contact Information:
 Bottineau County Historical Society
 Bottineau ND 58318

Recorded By: Kathy Wilner	Date Recorded: 8/6/2020
---------------------------	-------------------------

# NDCRS ARCHITECTURAL FORM PAGE 4 – Site Description

Field Code Oak Valley School District 18	SITS# 32 BU
3. Site Area (ft²):	
museum building on the west side of th	of Main Street in Bottineau. It is just south of a large ne street just before 98th St NE. The school is town. It is mostly industrial in this area.
5. Summary of ALL Site Features and Evaluation	on of Significance:
References/Comments:     Information and photos contributed by Lorie You	ocum.
Recorded By: Kathy Wilner	Date Recorded: 8/6/2020



East Side

Oak Valley School District 18


7/18/2020

Kathy Wilner

BU

**South Side** 






North Side

Oak Valley School District 18 7/18/2020

Kathy Wilner

BU

# West Side





Imagery ©2020 Google, Imagery ©2020 Maxar Technologies, USDA Farm Service Agency, 100 ft Map data ©2020

Bottineau

Bottineau