

NDCRS ARCHITECTURAL FORM  
PAGE 1

Field Code Bottineau School #3

SITS# 32BU 786

Map Quad Bottineau

Site Name Bottineau School #3

Map Quad \_\_\_\_\_

Site Name Trent School

LTL    T. 162 N., R. 75 W., Sec. 9 QQQ 6 of the QQ 7 of the Q 8

LTL    T.    N., R.    W., Sec.    QQQ    of the QQ    of the Q   

LTL    T.    N., R.    W., Sec.    QQQ    of the QQ    of the Q   

LTL    T.    N., R.    W., Sec.    QQQ    of the QQ    of the Q   

NAD 1983 UTM 5414161 Zone 14N

NAD 1983 UTM 397536

City: \_\_\_\_\_

Street Number: 10060

Street Name: Lake Road

Urban Legal Description: \_\_\_\_\_

Total Number of Architectural Features: 1

Fieldwork Date: 8/6/2021

Reconnaissance Survey

Intensive Survey

Project & Principal Investigator:

Country School House Project  
Kathy Wilner  
366 43rd Ave SE  
Bowdon ND 58418

Contracting Firm or Agency Completing the Form: \_\_\_\_\_

Additional Information: \_\_\_\_\_

SHSND USE

Component 2 Study Unit 20 Verified Site \_\_\_\_\_ CR Type 2

Component \_\_\_\_\_

Component \_\_\_\_\_

Recorded By: Kathy Wilner Date Recorded: 10/21/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

Subsection
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

NDCRS ARCHITECTURAL FORM  
PAGE 2 – Feature Data

Field Code Bottineau School #3

SITS# 32 BU                     

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date                     

Feature Date 1880-1900

Structural System Wood Frame

Original Owner's Ethnicity                     

Feature Type 9 - School; Church school

Context Education

Primary Exterior Wood, Horizontal Siding

Secondary Exterior                     

Condition Good

Plan Shape Rectangular

Style Other Style

Architect/Builder                     

Foundation Concrete Block Stories 1

Roof/Cornice Hip

Window Double hung, some fixed pane, most covered

Dating Method(s) Documentation

Miscellaneous Information                     

**Feature Preservation Recommendation(s) (Check all that apply):**

- Individual nomination
- Contributes to a potential district
- No nomination potential
- Will not contribute to a district
- Potential district—feature would be a contributing element if other properties constitute a district
- Thematic nomination potential
- Component of a historic site or landscape
- Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility
- Historical associations require further investigation

Recorded By: Kathy Wilner Date Recorded: 10/21/2021

**NDCRS ARCHITECTURAL FORM**  
**PAGE 3 – Feature Data****Field Code** Bottineau School #3**SITS#** 32 BU**Complete one Page 3 for each architectural feature at the site.****1. Feature Description, Integrity, Eligibility:**

The feature is a one room prairie school moved to this location and placed on a concrete block foundation. The foundation has been skirted with wood. The hip roof is covered with asphalt shingles. The chimney is gone. The soffits are closed. The building measures 32 feet east to west and 28 feet north to south.

The siding begins with a rake board on all sides under the eaves. The remainder of the siding is 6 inch wood lap with 6 inch wood corner trim. The half hip roofed entry is a bump-out on the west side. Wood steps lead up to a 3 panel wood door with the window opening boarded up. The door from the coat room into the school proper is missing. There is a small, decorative fixed pane window on either side of the door. Also on the west wall are two more covered windows. They are fixed 4 pane windows and these are located in the coat room. On the east side there are 4 windows, three over one, some covered and some with glass. Two similar double hung windows are located on the south side, one covered and one not. The ceiling and about 2 feet at the top of the walls are covered with perforated acoustic tiles. The remainder of the walls are finished with lathe and plaster. There is a small blackboard located on the north wall. The floor is tongue and groove hardwood. Light fixtures are indicative of electricity. The heat was coal.

The school began in the late 1880's and closed in 1951. It was originally located a few miles west of Bottineau. The school is used for storage today.

**2. Owner's Contact Information:**

Anthony Schwabe  
10060 Lake Rd  
Bottineau ND 58318

**Recorded By:** Kathy Wilner **Date Recorded:** 10/21/2021

**NDCRS ARCHITECTURAL FORM**  
**PAGE 4 – Site Description****Field Code** Bottineau School #3**SITS# 32** BU3. Site Area (ft<sup>2</sup>):

4. Description of Access and Site Setting:

This building sits on a farm. There are buildings encircling it and beyond the building are lots of trees. To reach this school you go just east of Bottineau on Hwy 5 to 13th Ave. NE or Lake Rd. Turn left and drive north just over 4 1/2 miles to see the farm on the east side of the road.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Photos and information provided by Lorie Yocum.

Kathy Wilner  
366 43rd Ave SE  
Bowdon ND 58418

**Recorded By:** Kathy Wilner **Date Recorded:** 10/21/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.



**West Side**

**Bottineau School #3**

**8/6/2021**

**Kathy Wilner**

**BU**

**North Side**





South Side

Bottineau School #3

8/6/2021

Kathy Wilner

BU

East Side





Imagery ©2021 CNES / Airbus, Maxar Technologies, USDA Farm Service Agency, Map 500 ft data ©2021

Feature