

NDCRS ARCHITECTURAL FORM

PAGE 1

Field Code Sergius School

SITS# 32BU 787

Map Quad Landa SW

Site Name Sergius School

Map Quad _____

Site Name _____

LTL T. 161 N., R. 79 W., Sec. 17 QQQ 7 of the QQ 6 of the Q 5

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

LTL T. N., R. W., Sec. QQQ of the QQ of the Q

NAD 1983 UTM 5403869 Zone 14N

NAD 1983 UTM 358108

City: _____

Street Number: _____

Street Name: 10th Ave. NW

Urban Legal Description: _____

Total Number of Architectural Features: 1

Fieldwork Date: 9/21/2021

Reconnaissance Survey

Intensive Survey _____

Project & Principal Investigator:

Country School House Project
Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Contracting Firm or Agency Completing the Form:

Additional Information:

SHSND USE

Component 2 Study Unit 20 Verified Site _____ CR Type 2

Component _____

Component _____

Recorded By: Kathy Wilner Date Recorded: 10/28/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

Subsection
1 = N½
2 = E½
3 = S½
4 = W½
5 = NE¼
6 = SE¼
7 = SW¼
8 = NW¼

NDCRS ARCHITECTURAL FORM
PAGE 2 – Feature Data

Field Code Sergius School

SITS# 32 BU

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date _____

Feature Date 1900-1915

Structural System Wood Frame

Original Owner's Ethnicity _____

Feature Type 9 - School; Church school

Context Education

Primary Exterior Wood, Horizontal Siding

Secondary Exterior _____

Condition Poor

Plan Shape Rectangular

Style Other Style

Architect/Builder _____

Foundation Concrete Block Stories 1

Roof/Cornice Gable

Window Double hung, some glass

Dating Method(s) Estimate

Miscellaneous Information _____

Feature Preservation Recommendation(s) (Check all that apply):

Individual nomination

Contributes to a potential district

No nomination potential

Will not contribute to a district

Potential district—feature would be a contributing element if other properties constitute a district

Thematic nomination potential

Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

Historical associations require further investigation

Recorded By: Kathy Wilner Date Recorded: 10/28/2021

NDCRS ARCHITECTURAL FORM

PAGE 3 – Feature Data

Field Code Sergius School

SITS# 32 BU

Complete one Page 3 for each architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school on a concrete block foundation. This school was moved into a farm yard for storage. The roof has remnants of wood shakes and there are many holes. The chimney is gone. The soffits are closed. The building measures 20 feet north to south and 32 feet east to west.

The siding begins with a rake board under the eaves at the peak ends of the school. The remainder of the siding is 6 inch wood lap with 6 inch wood corner trim. 6 double hung, 2 over 2, windows run along the south side with one more similar window to the right of the entry door in the coat room. There is some glass in the windows. There is a four panel wood entry door on the west side. Immediately inside the school are three more 4 panel wood doors, one to the left leads into a fuel room with an exterior fuel door on the north wall, another leads into the coat room and a third gives entry into the school room. Another door was added on the east side of the school. The interior of the entry walls are finished with beadboard. The school room walls are lathe and plaster. The ceiling inside the school has only lathe remaining, all the plaster has fallen away. There is wainscot on all walls inside the school. Blackboards are on all four walls with wall space between windows having small blackboards. The floor is tongue and groove hard wood. There was electricity present in the school.

2. Owner's Contact Information:

Glenn Nemyr

MInot ND 58507

Recorded By: Kathy Wilner **Date Recorded:** 10/28/2021

NDCRS ARCHITECTURAL FORM
PAGE 4 – Site Description**Field Code** Sergius School**SITS#** 32 BU3. Site Area (ft²):

4. Description of Access and Site Setting:

This school is located NW of Newburg ND. Drive northwest out of Newburg on County Rd 20, this turns into 90th St NW. Drive about 1/2 mile to 10th Ave NW. Turn right onto 10th Ave NW and drive a little more than 2 1/2 miles north to see the farm on the west side of the road. The school sits in a farm yard with trees to the north and west and farm buildings to the southeast with farm fields all directions.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Information and Photos shared by Lorie Yocum.

Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Recorded By: Kathy Wilner **Date Recorded:** 10/28/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.



East Side

Sergius School

9/21/2021

Kathy Wilner

BU

South Side





West Side

Serguis School

9/21/2021

Kathy Wilner

BU

North Side





Imagery ©2021 CNES / Airbus, Maxar Technologies, USDA Farm Service Agency, Map data ©2021 500 ft

Feature