NDCRS ARCHITECTURAL SITE FORM

Field Code Bell Township #60	PAGE 1 SITS# 32 CS 53/8
SITE IDENTIFICATION Map Quad Grandin	
Map Quad	Site Name Bell Township #60 Site Name
LTL _TWP 143 R 51 SEC LTL _TWP R SEC LTL _TWP R SEC LTL _TWP R SEC NAD 1983, UTM 5228571 N NAD 1983, UTM 642916 E City: Hunter Street Number: Street Name: 15th St SE and 160th Ave SE Urban Legal Description: SITE DATA	22 QQQ 5 QQ 5 Q 5 Q 5 Q 5 Q 5 Q Q Q Q Q
Total # Architectural Features: 1	
Fieldwork Date: 5/11/2018	
Reconnaissance Survey Intens	sive Survey
Project & Principal Investigator: Country Schoolhouse Project	
Report Title & Author(s):	
Contracting firm or Agency completing the form	n:
Additional Information:	
SHSND USE Area of Significance Ecozone Area of Significance Ecozone	Verified Site CR Type
Recorded By Kathy Wilner	Date Recorded 1/18/2019
(First Name & Last Name)	/mm/ddhear)

NDCRS ARCHITECTURAL SITE FORM PAGE 2—Feature Data

Field Code Bell Township #60		SITS# 32 CS	
Complete one Page 2 for each	architectural feature	at the site.	
Architectural Feature #			
Construction Date	Feature Type X 9	Condition 4	
Feature Date 2	Context X 7	Plan Shape 5	
Structural System 25	Primary Exterior 26	Style Other Style	
Original Owner's Ethnicity———	Secondary Exterior N/A	Architect/Builder	
Original Owner's Eurnicity————	Secondary Exterior		
Other Information:			
Foundation Concrete blocks		Stories 1	
Roof/Cornice Gable			
Window Double hung, little framing an	d no glass		
Dating Method(s): Estimate			
	Total Card		
Feature Preservation Recommen	ndation(s) (Check all that	apply):	
Individual nomination			
Contributes to a potential distr	rict		
No nomination potential			
Will not contribute to a district			
Potential district—feature wou	ald be a contributing element i	if other properties constitute a district	
Thematic nomination potentia			
Component of a historic site o		an anoutile to the	
Moved (specify all applicable recreates original site, orienta with neighboring structures; d)	tion, landscape, & spatial rela	ationships; c) compatible in context	
Historical associations require	further investigation		
Recorded By Kathy Wilner		ate Recorded 1/18/2019	1
(First Name & Last Name		(mm/dd/year)	7

Instructions to complete a digital version of this form: (1) Download a copy; (2) Open the saved blank copy; (3) Fill out the form; (4) Use the Save As command to rename the form appropriately, and save; (5) **Print** and submit to SHSND.

NDCRS ARCHITECTURAL SITE FORM PAGE 3—Feature Data

Field Code Bell Township #60	SITS# 32 CS

Complete a Page 3 for each feature.

1. Feature Description, Integrity, Eligibility:

The feature is a one room prairie school sitting on concrete block foundation. Perhaps this school was moved to this location as concrete blocks were not common for foundation in early construction of schools. The roof of the school has a sparse scattering of wood shakes with large areas of the roof sagging bare wood. The entry is nearly devoid of shingles. There is a large cupola on the roof near the east end. Wood shakes cover this roof as well and there is a flag pole at the peak. The roofs of both the school and entry have metal capping with finials. The soffits are closed.

There is a wide trim board under the eaves of all side of the school. The siding is 6 inch wood lap with metal corner trim. The window openings on the south side of the school are mostly just large holes. It appears there were two banks of three double hung windows, with little framing and no glass. The entry also had two double hung windows, no glass and a bit of framing. On the west wall there are two mutipane, double hung windows nearer the north wall and another double hung window closer to the south wall, no glass in any of them. One last window opening is under the peak on the west wall. A stairway inside the door located at the southwest corner of the school of the appears to lead up to a small room at the west most end of the school. Perhaps a room for the teacher. Where the stairway turns to go upstairs it also opens into the school proper. The entire east end of the entry was cut away leaving a large opening. Perhaps the building was used for storage of farm equipment. The remaining walls are lathe and plaster with much of the plaster fallen away. Remnants of beadboard hang from some parts of the ceiling as well as failing lathe and plaster other areas. There are old light fixtures attached to the ceiling boards indicating electricity.

Recorded By Kathy Wilner	Date Recorded 1/18/2019		
77777	(First Name & Last Name)	(mm/dd/year)	

NDCRS ARCHITECTURAL SITE FORM PAGE 4—SITE DESCRIPTION

Field Code Bell Township #60	SITS# 32 CS
Complete one Page 4 for the entire site.	
2. Owner's Contact Information:	
Access (to rural areas): From Hunter ND go east about 4 1/2 miles on 15th side of the road at the corner of the intersection wit	St SE or Couty Road 2. The school is on the south h 160th Ave SE.
4. Site Area (ft²):	
 Description of SETTING: There is a bin site to the north of the school and far straggly trees growing along the north wall of the school. 	
IV-4b., VAVII	
Recorded By Kathy Wilner	Date Recorded 1/18/2019
(First Name & Last Name)	(mm/dd/year)

NDCRS ARCHITECTURAL SITE FORM PAGE 5—SITE DESCRIPTION

Field Code Bell Township #60	SITS# 32 CS
6. Summary of ALL Site Features & Evaluatio	n of Significance:
References/Comments: Pictlures used with permission from Stacy Brekke, Rura	alRoute2 Photography.
Kathy Wilner 366 43rd Ave SE	
Bowdon ND 58418	
Recorded By Kathy Wilner	Date Recorded 1/18/2019
(First Name & Last Name)	(mm/dd/year)



South Side


Bell Township #60


5/11/2018

Kathy Wilner

CS

West Side





East Side

Bell Township #60

5/11/2018

Kathy Wilner

CS

North Side




Google Maps

Bell Township #60 CS

5/11/2018

Kathy Wilner



Imagery @2019 Google, Map data @2019 Google 200 ft

Feature