NDCRS ARCHITECTURAL FORM PAGE 1

	_	_	_	
	_		^	_
		.,	-	_

Field Code			_		5	SITS# 32 <u>CS</u>	53	335	
Map Quad			_	Site Name	East	Gill School Dis	strict 4	14	
Map Quad			_	•		Gill School and			
LTL T LTL T	_N., R _N., R	_W., Sec _W., Sec _W., Sec _W., Sec	QQQ QQQ	of the Q of the Q	Q Q	_ of the Q _ of the Q	- - -	1 = N½ 2 = E½ 3 = S½	
NAD City:	UTM		_					4 = W½ 5 = NE¼ 6 = SE¼ 7 = SW¼ 8 = NW¾	
Street Number:									
Street Name:									
Urban Legal Des	scription:						_		
Total Number of	Architectu	ral Features:		<u> </u>					
Fieldwork Date:	09/15/	2012							
Reconnaissance	e Survey	_	Intens	ive Survey _					
Project & Princip	oal Investiga	tor:							
Contracting Firm SHSND	n or Agency	Completing the F	orm:						
Additional Inform	nation:								
based on nomina	ation questio	nnaire, fieldwork d	ate is es	stimated					
SHSND USE Component Component Component		tudy Unit	Ve	rified Site		_ CR Type _			
Recorded By:	:	Lorna Meidin	iger	Da	ate R	ecorded: _		11/04/2020)

NDCRS ARCHITECTURAL FORM PAGE 2 – Feature Data

UPDATE

Field Code		SITS# 32 <u>C</u>	S 5335
Complete one Page 2 fo	r each architectural feature a	at the site.	
Architectural Feature #			
Construction Date	1898		
Feature Date 1880-19	000		
Structural System			
Original Owner's Ethnicity			
Feature Type			
Context			
Primary Exterior			
Secondary Exterior			
Condition			
Plan Shape			
Roof/Cornice			
	nation questionnaire		
	n school closed in 1951		
Feature Preservation Re	ecommendation(s) (Check al	l that apply):	
Individual nomina			
Contributes to a p	otential district		
No nomination po	tential		
Will not contribute	to a district		
Potential district—	-feature would be a contributin	g element if other properties	constitute a district
Thematic nominat	ion potential		
Component of a h	istoric site or landscape		
` ' '	andscape, and spatial relations		ric period; b) recreates original xt with neighboring structures; d)
Historical associa	tions require further investigati	on	
_	1	_	4410410000
Recorded By:	Lorna Meidinger	Date Recorded: _	11/04/2020

NDCRS ARCHITECTURAL FORM PAGE 3 – Feature Data

Field Code		SITS# 32 <u>CS</u>	SITS# 32 <u>CS</u> <u>5335</u>			
Complete one Page 3	for each architectural feature at	the site.				
1. Feature Description,	Integrity, Eligibility:					
see nomination q	uestionnaire for additional info	rmation				
2. Owner's Contact Info	ormation:					
	Laura Maidire		44/04/0000			
Recorded By:	Lorna Meidinger	Date Recorded:	11/04/2020			

NDCRS ARCHITECTURAL FORM PAGE 4 – Site Description

		$\overline{}$	-	_	
	u	11	Λ		
u		ப	\boldsymbol{H}	\ I	
_	•	_		•	

Field Code		SITS# 32 <u>CS</u>	5335
3. Site Area (ft²):			
4. Description of Access an	d Site Setting:		
5 Summary of ALL Site Fe	eatures and Evaluation of Signi	ificance:	
3. Summary of ALL One Te	atures and Evaluation of Signi	meanee.	
6. References/Comments:			
	Lorna Meidinger		

NOMINATION QUESTIONNAIRE

In which county is this property located? <u>CaSS</u>
What is the historic (or earliest) name of this property? East Gill School District 44
What is the current name of this property? East Gill School and Township Hall
I wish to nominate this property because (check all that apply): National Register listing will honor the history of this property I seek financial assistance in rehabilitating this property This building is my primary residence This is an income-producing property (commercial or rental) I wish to protect this property This property is threatened with demolition or destruction Please list threat: Please list threat:
Where is this property located? If in an incorporated city or village please list: Street and number:
City:
If in a rural area please list: Road or nearest road: Cass County 5
Name of township: Gill
Nearest village or city: Chaffee or wheatland
Township, range, and section: Township 139, Range 53, Section 2
Do you know any of the following information:
The architect's name was:
The builder's name was:
The date of construction was: 1898 RECEIVED

Significance of the property

See atlached

Why do you think this property should be listed in the National Register of Historic Places? Please check one or more box below and briefly explain why the property is important.

This p	property illustrates an important aspect of local history through its:
	Ethnic history
M	Social or political history
	Industrial or commercial history
	Agricultural history
	Transportation history
	Other
	It is directly associated with a person or people who made important individual contributions to local, state, or national history in this field:
It is di	istinctive for its architecture, artistic qualities, or engineering because:
	It is an important example of an architectural style
×	It is an important example of vernacular (commonplace) or ethnic architecture
	It is an unusual or important kind of building or structure
	It has an unusual method of construction
	It is an important work of art
	It is the work of a master architect, builder, or craftsman
	explain your answer(s) above; list your information sources. This rty is important because:

East Gill School stands as a reminder of Country Schools. Built in 1898, it has stood in the same place, next to Cass County 5, for over 100years. It is part of the community. It was built like most country school, almost entirely of wood. It is in good, sound condition and has been checked structurally by building contractor, Charles Albright, Linchburg, ND.

The restoring of it is of interest to former students and Gill Township. We have had many favorable letters and comment since we begin restoring it.

Please list the source(s) of this information: Rural Cass County Book 1976
What alterations/additions/changes have been made since the building was
built? Please check all applicable boxes and list pertinent details (what was the
original material or configuration, where were details that have been removed,
etc.)
□ Additions
Porches (added or removed) Replace L-wood
☐ Replacement doors and windows
□ Replacement siding or residing
☐ Removal of decorative details
Interior remodeling/updating Painted during School Wise
Removal of decorative details Interior remodeling/updating Painted during School use Changes to roof Reshigled wood - Sound - Weathered - Paint Would help
☐ Moved from original location (why? From where? When?)
Please give dates for major alterations.
Replacement of Porch and STep 2011
What do you know about this history of this property? Significant community

What do you know about this history of this property? Significant community events, prominent people associated with the building, and the use of the property are all pertinent. Please list sources for information.

See attached

East Gill School District 44 is located on Cass County 5, in Cass County. It is 3 miles south of Interstate 94, at the Wheatland Chaffee Exit, number 324. It is the only rural school still standing in Cass County. It was organized in 1880, and the school was built on the South West ¼ Section 23 in 1898. It served upwards to 400 students in its time. The school closed in 1951. When the schools were consolidated in 1975, the school went to Central Cass School District 22. It was and still is used as the Gill Township Hall and voting place. The Gill Livestock 4-H Club always held their meetings there. The building was used for card parties, Anniversary parties and social events. The School was deeded back to Gill Township in 1998. There had not been any improvements or paint (inside) done in this time. At some time it was reshingled with wood shingles and painted (outside).

James C. Gill lived on Section 35, and in 1884 owned 4000 acres of land. He was elected to the 1891 Legislature. Relatives of his attended the school until 1946.

All information is found in the "Rural Cass County" history book 1976.

Photographs

A site cannot be evaluated without photographs.

Please submit clear, *recent* photographs that show all sides of the exterior of the structure, important interior spaces, and the site on which the structure sits. Please label the photographs (directions are helpful – i.e. "North side of house."). Photos can be submitted electronically to the address at the bottom; faxed photos are not acceptable. Photos will not be returned.

Map

Please draw a simple sketch map of the lot on which the property is located. Include all structures, adjoining streets, and other major features. If the property is rural, a plat map, county map, or other detail map can be used; please mark the location of the structure about which you are writing.

Person completing the questionnaire:

Name: Marilya McLean

Address: 14835 33 57 56

wheatland, ND 58079

Telephone: 701-633-5245-701-361-1875

Owner Information, if different than above.

☐ Please check if owner has been contacted about this questionnaire

Owner Name: Gill Township

Owner Address:

Owner Telephone:

Please return form and photographs to:

Historic Preservation Division Attn: Architectural Historian State Historical Society of North Dakota 612 East Boulevard Avenue Bismarck, North Dakota 58505

701.328.2089



Front of East Gill School Facing South

Beginning -East Side




North Side Scraped



North East Corner



East + North Painted






West side



North West Wall Windows - West Stove



south wall, Kitchen - Walls to be Scraped



Inside School North Wall

Separation fixed

Work Reeded
Floor
Woodwork
Blackboards



By Amanda Gades

The school desks and chalkboard are gone from the East Gill School, but the memories have not faded of the one-room school house days.

"When I went to school there, all eight grades were taught by one teacher," said Marilyn McLean, Wheatland. "There were 25 students."

McLean, Hank Weber, Joan Schatzke and Kim Nelson comprise the committee working to restore the school.

They aim to obtain funds from grants and corporate and individual donors to paint the building's exterior, shingle the roof and install new windows, according to Hank Weber, committee chair.

"This is a great way to preserve history," said Weber.

Committee members have already been in contact with several businesses and groups about donating for the project, Weber added.

Remembering school days

The East Gill School District was organized in 1893 and the original building and horse barn were located just across the road in section 22 from its present location. In 1898, the local school board decided to build a new school house in the location where it now stands.

In the early years, children either walked, rode a pony or horse and buggy to school. The school continued until 1951 when reorganization and consolidation took place and students then went either to Wheatland or

McLean said. "Mrs. Lawrence Butler made the most delicious buns. Mrs. Lloyd Lass made rice with sugar and cinnamon. Mrs. Edna Munson made creamed eggs and the Pfingstens made macaroni hotdish."

Phyllis Koetz, who obtained her education in the East Gill one-room school house, went on to teach in a one-room school near Enderlin.

"One of things
I did when I was a
teacher that I learned
when I was in school
was that the older kids
helped the younger
kids when they had a
question," said Koetz,
of Leonard.

The current and future function

Since 1951, when the school closed, the building has been used as a community center and voting place. For many years the monthly meeting of the Gill Livestock 4-H club were held there. It has continued to serve as the official meeting site for the



Courtesy Photos

The Gill Township School is located three miles south of the Wheatland exit on Interstate 94. It is currently used for Gill Township officer meetings.

Chaffee Schools.

In operation for 71 years, an average of six or seven new first graders enrolled each year and it is estimated that between 400 and 500 students attended school there. The last teacher at the school was Mrs. Dorothy Buttke.

"My mom and three aunts including Dorothy Buttke attended the school," said Schatzke. "They have very fond memories of the school."

Marilyn McLean, who received her education there, recalls the big Christmas programs, softball games in the spring, success at music competitions, the great teachers and the delicious food the mothers shared.

"Every mother had a favorite food

School house - Page A8



East Gill School Dist. #44, No. 1, Dress up Day, 1952.

township. Some school records are still preserved there. The building is structurally sound and is one of the last one-room schools still standing and being used in Cass County.

Thousands of one-room schools like East Gill once dotted the countryside and are part of our national heritage. Today, opportunities for education are, for the most part, taken for granted and by preserving the building, it will serve as a reminder to future generations of the educational challenges that small rural communities once faced.

NDCRS ARCHITECTURAL FORM PAGE 1

Field Code MAC-738	69-1	_	SITS# 32 CS	5335
Map Quad Chafee Map Quad		Site Name Site Name _		
LTL T. 139 N., R. LTL T. N., R. LTL T. N., R. LTL T. N., R. LTL T. N., R. N., R. LTL T. N., R. MAD 1983 UTM NAD 1983 UTM	W., Sec W., Sec W., Sec 5187909	_ QQQ of the Q0 _ QQQ of the Q0 _ QQQ of the Q0	Q of the Q Q of the Q	1 = N½ 2 = E½
City:				7 = SW¼ 8 = NW¼
Street Name: 149th Av				
Urban Legal Description:				
Total Number of Archite	ctural Features:	1		
Fieldwork Date:07/	28/2020			
Reconnaissance Survey	<u> </u>	Intensive Survey	<u></u>	
Project & Principal Invest	igator:			
Project: Cass County Elect Cass County, North Dakot	•	ass III Cultural Resour	ce Inventory for WO	#73869 Cass Electric Line,
Contracting Firm or Agen Metcalf Archaeological Co		Form:		
Additional Information:				
SHSND USE Component 2 Component Component	Study Unit15	Verified Site	1 CR Type	2
Recorded By:	B. Blueml	e Da	te Recorded:	07/28/2020

NDCRS ARCHITECTURAL FORM PAGE 2 – Feature Data

Field Code MAC-73	369-1	SITS# 32 <u>C</u>	<u>S</u> <u>5335</u>
Complete one Page 2 f	or each architectural feature	e at the site.	
Architectural Feature#_	1		
Construction Date			
Feature Date <u>1880-1</u>	900		
Structural System <u>Wo</u>	ood Frame		
Original Owner's Ethnici	ty Other		
Feature Type <u>9 - Schoo</u>	l; Church school		
Context Education			
Primary Exterior <u>Woo</u>	od, Horizontal Siding		
Secondary Exterior			
Condition Good			
Plan Shape Rectano	 Jular		
Style Other Style			
Roof/Cornice Asphalt			
Window 2 over 2 lite w	vith aluminum storms		
Dating Method(s)Doc	umentation		
- , ,	on		
	Recommendation(s) (Check a		
Individual nomina		11. 27	
Contributes to a	potential district		
No nomination p	otential		
Will not contribut	e to a district		
Potential district-	—feature would be a contributi	ing element if other properties	constitute a district
Thematic nomina	ation potential		
Component of a	historic site or landscape		
site, orientation,			ric period; b) recreates original xt with neighboring structures; d)
Historical associ	ations require further investiga	ation	
Recorded By:	B. Bluemle	Date Recorded:	07/28/2020

NDCRS ARCHITECTURAL FORM PAGE 3 – Feature Data

Field Code MAC-73869-1	SITS# 32 CS 5335

Complete one Page 3 for each architectural feature at the site.

1. Feature Description, Integrity, Eligibility:

Feature 1 is the East Gill School. According to its associated sign, it was constructed c.1898 in the SE quarter of Section 23 to replace an earlier school in Section 22. It is a single-story gable-front building with white painted wood clapboard siding. There is a sign above the doors on the south façade that states "Gill Township, Est. 1884, East Gill School District." The building measures 32 feet north-south by 23 feet east-west. The roof is covered in newer asphalt shingles. The south façade has two steel six panel doors. The door to the west is accessed by a low wood deck with a metal railing along one side. The building has eight total windows, four each on the east and west elevations of the building. The windows are two-over-two-lite windows and have aluminum storm windows over them. There is an attached shed-roofed addition on the west half of the north elevation. The shed addition measures 6.5 feet north-south by 9.8 feet east-west. The addition is roofed in wood shingles; asphalt shingles are visible beneath. The addition has one wooden vertical plank door on the west elevation with a simple metal lift latch.

Overall, the building appears to be in good condition. There is some wood trim missing from the bottom foot and a-half of the northeast corner, and a few spots of peeling or missing paint.

The replacement of the original doors with steel doors, and application of asphalt shingles and aluminum storm windows have affected integrity of materials to some extent. Despite these minor modifications, the site retains all aspects of integrity.

2. Owner's Contact Information:

Recorded By:	B. Bluemle	Date Recorded:	07/28/2020	

NDCRS ARCHITECTURAL FORM PAGE 4 – Site Description

Field Code	MAC-73869-1	SITS# 32 (CS	5335

- 3. Site Area (ft2):
- 4. Description of Access and Site Setting:

From exit 324 off I-94, travel south for three miles on 149th Ave S. Stop 130' from the intersection with 40th St. SE. The site is located east of the road, and borders 149th Ave. SE to the west, and is approximately 300 feet south of Buffalo Creek. There are cultivated fields to the north, south and east.

5. Summary of ALL Site Features and Evaluation of Significance:

The site is the Gill Township School house built between 1880 and 1889. The schoolhouse is in excellent condition and retains all aspects of integrity sufficient to convey historic character.

Schoolhouses are an increasingly rare property type on the Great Plains. In North Dakota, they are among the earliest and also most basic public buildings in a community. Most rural and town schools were based on a popular plan with similar materials and methods of construction, wood-framed, gable-roofed, white schoolhouse with certain characteristic features including wood-paneled doors, lap siding, and window moldings, and have become ubiquitous on the state's landscape. They reflect vernacular building practices of a particular period when commercially-produced materials, including milled-lumber, millwork, and hardware were readily available (Gulliford 1984).

Rural schoolhouses, like the Gill School, served children from the agricultural community and their families, often doubling as a community hall and meeting place. One-room schoolhouses like this began to fall out of use in the early 20th century as reform movements sought to consolidate and standardize education throughout the rural United States. Abandoned, former schoolhouses are frequently found on private properties, converted to new use as an agricultural storage building. Others have been subject to demolition by neglect. Metcalf is not aware of the current number of in-situ one-room schoolhouses in the state that are in good condition and retain all aspects of integrity. Four other one-room schools have been documented in Cass County through the SHSND Country School House Project and while this is not the most ornate example, it is one of the best preserved (SHSND 2020). We find this particular site is a strong representative example of a late-19th Century one-room schoolhouse and recommends it be considered eligible under Criterion A for this historic association.

6. References/Comments:

Gulliford, Andrew (1984) America's Country Schools. Washington DC: Preservation Press.

R.L. Polk & Co. (1906) The County of Cass, North Dakota. R.L. Polk & Co. St. Paul, MN.

SHSND (2020) "Country School House Project" online database, https://www.history.nd.gov/hp/schools/

Accessed 8/26/2020.

Recorded By:	B. Bluemle	Date Recorded:	07/28/2020




Figure 1: Sketch map for site MAC-73869-1.



Figure 2: View northeast over southwest corner (Image #23).



Figure 3: View northwest over the southeast corner (Image #24).



Figure 4: View southwest over northeast corner (Image #26).



Figure 5: View southeast over northwest corner (Image #29).



Figure 6: View east over sign (Image #16).




Figure 7: Excerpt from 1906 R.L. Polk & Co. Cass County Atlas depicting Gill Township, with location of Gill School in Section 23.




Figure 8: Zoomed in view over sign (Image #16).