

NDCRS ARCHITECTURAL FORM
PAGE 1

Field Code Dep. 25 School

SITS# 32 CS 5347

Map Quad Casselton
Map Quad

Site Name Dep. 25 School
Site Name

LTL T. 140 N., R. 52 W., Sec. 10 QQQ 7 of the QQ 6 of the Q 6
LTL T. N., R. W., Sec. QQQ of the QQ of the Q
LTL T. N., R. W., Sec. QQQ of the QQ of the Q
LTL T. N., R. W., Sec. QQQ of the QQ of the Q

Subsection
1 = N1/2
2 = E1/2
3 = S1/2
4 = W1/2
5 = NE1/4
6 = SE1/4
7 = SW1/4
8 = NW1/4

NAD 1983 UTM 5201013 Zone 14N
NAD 1983 UTM 635118

City:

Street Number:

Street Name: 32nd St SE

Urban Legal Description:

Total Number of Architectural Features: 1

Fieldwork Date: 05/31/2021

Reconnaissance Survey [checked] Intensive Survey

Project & Principal Investigator:
Country School House Project
Kathy Wilner
366 43rd Ave SE, Bowdon, ND 58418

Contracting Firm or Agency Completing the Form:

Additional Information:

SHSND USE
Component Study Unit Verified Site CR Type
Component
Component

Recorded By: Kathy Wilner Date Recorded: 06/02/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.

**NDCRS ARCHITECTURAL FORM
PAGE 2 – Feature Data**

Field Code Dep. 25 School

SITS# 32 CS 5347

Complete one Page 2 for each architectural feature at the site.

Architectural Feature # 1

Construction Date _____

Feature Date 1900-1915

Structural System Wood Frame

Original Owner's Ethnicity _____

Feature Type 9 - School; Church school

Context Education

Primary Exterior Wood, Horizontal Siding

Secondary Exterior _____

Condition Good

Plan Shape Rectangular

Style Other Style

Architect/Builder _____

Foundation Railroad ties Stories 1.0

Roof/Cornice Hip

Window Double hung, mostly covered, some glass

Dating Method(s) Estimate

Miscellaneous Information _____

Feature Preservation Recommendation(s) (Check all that apply):

Individual nomination

Contributes to a potential district

No nomination potential

Will not contribute to a district

Potential district—feature would be a contributing element if other properties constitute a district

Thematic nomination potential

Component of a historic site or landscape

Moved (specify all applicable choices)—a) relocation occurred within a historic period; b) recreates original site, orientation, landscape, and spatial relationships; c) compatible in context with neighboring structures; d) relocation has damaged eligibility

Historical associations require further investigation

Recorded By: Kathy Wilner **Date Recorded:** 06/02/2021

NDCRS ARCHITECTURAL FORM**PAGE 3 – Feature Data**Field Code Dep. 25 SchoolSITS# 32 CS 5347**Complete one Page 3 for each architectural feature at the site.**

1. Feature Description, Integrity, Eligibility:

This feature is a one room prairie school sitting on railroad ties. It was moved to this farmsite for storage. The hip roof is covered with asphalt shingles. A stove pipe is seen sticking out of the roof on the east slope. There is small, gable roofed entry on the south side also covered with asphalt shingles. The soffits were close but are open in many places as the wood rots away. The chimney is gone.

The siding begins with a rake board under the eaves on all sides. The remainder of the siding is 6 inch wood lap with 4 inch wood corner trim. There is an entry on the south side of the school. The roof is gable with decorative shakes above an eave extension. Remnants of the bell tower are seen on this roof. The broken, four panel wood door is recessed. To either side of the door there are verticle 2x4's to finish the wall. A transom opening is covered. There are two double hung windows to either side of the entry, four more similar windows are located on the north side. Most of the windows are either partially or totally covered. There are three more smaller windows on the west side, double hung and covered. One more smaller double hung window is located on the east side. The floor is tongue and groove hardwood. The walls and ceiling are covered with lathe and plaster. There is wainscot but no blackboards. It is wired for electricity.

2. Owner's Contact Information:

Darrin and Staci Radermacher
15495 32nd ST SE
Wheatland ND 59079-9779

Recorded By: Kathy Wilner Date Recorded: 06/02/2021

**NDCRS ARCHITECTURAL FORM
PAGE 4 – Site Description**Field Code Dep. 25 SchoolSITS# 32 CS 53473. Site Area (ft²):

4. Description of Access and Site Setting:

This building is locate at the north edge of a farm. There is a large barn and many other farm buidings to the east, trees to the north, and farm land all other directions. It is located 3 miles north of Casselton on Hwy 18. The farm is at the intersection of 32nd St NE and Hwy 18.

5. Summary of ALL Site Features and Evaluation of Significance:

6. References/Comments:

Photos and information from Stacy Brekke, RuralRoute2 Photography.
Kathy Wilner
366 43rd Ave SE
Bowdon ND 58418

Recorded By: Kathy Wilner Date Recorded: 06/02/2021

Form instructions: (1) Download; (2) Save A Copy; (3) Submit a paper copy of the form to the SHSND and upload the PDF version of the form and corresponding GIS shapefiles to the ND SHPO-run FTP site.



RuralRoute2 Photography

South Side

Dep. 25 School

5/31/2019

Kathy Wilner

CS

East Side



RuralRoute2 Photography



West Side

Dep. 25 School

5/31/2019

Kathy Wilner

CS

North Side



Google Maps Dep. 25 School 5-31-2019 - Kathy Wilner CS



Imagery ©2021 Maxar Technologies, USDA Farm Service Agency, Map data ©2021 100 ft

Feature